## **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI** HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 497

Dated: 1.../.1.../.2021

194

## **FIRE SAFETY CERTIFICATE**

Certified that the "Swissten Inn" Guest House located at 8433, Arya Nagar, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 01 guest rooms + 01 store + shops),  $1^{st}$  floor to  $2^{nd}$  floor (08 guest rooms at each floor),  $3^{rd}$  floor (05 guest rooms + 01 room for personal use),  $4^{th}$  floor (06 guest rooms) and terrace floor (01 staff rooms + kitchen for staff sealed), total 28 guest rooms owned/occupied by "Swisston Inn" Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/EH/NDZ/2018/1705 dated 20/07/18. Now, the premise was re-inspected by the officer concerned of this department on 29/10/21 in the presence of Sh. Anil Kumar (Manager) and found that the said guest house building having floor wise occupancy Ground -(reception, 01 store & 01 office ), 1<sup>st</sup> floor to 2<sup>nd</sup> floor (08 guest rooms at each floor), 3<sup>rd</sup> floor (05 guest rooms + 01 room for personal use) and  $4^{th}$  floor & terrace floor not in use as per affidavit dated 26.09.2019 submitted by owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 for Ground -(reception, 01 store & 01 office ), 1st floor to 2nd floor (08 guest rooms at each floor), 3rd floor (05 guest rooms + 01 room for personal use) total -21 guest rooms only with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

(K) pmm

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above and not to use any floor above third floor.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Id no 2021081918209 dated 08.09.21

3. The Manager, "Swissten Inn" Guest House at 8433, Arya Nagar, Pahar Ganj, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all 1. 2.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the 3.
- The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction,
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

			1,T				
1.	Name & address a fill in INSP	ECTION REPO					
••	Name & address of the building "Swissten Inn" Guest House at 8433, Arya						
2.	Type of occupancy:-	•	ar Ganj, New Delh	i			
	· ype or occupancy:-		, Sub Division-A-1				
		Gr. + 04 Upper floors (total 21 Guest rooms)					
	Ground floor (Reception + 01 office + 01 store ), $1^{st}$ floor to $2^{nd}$ floor (08 guest rooms at each						
	floor), $3^{rd}$ floor (05 guest rooms at each						
	personal use), 4 <sup>th</sup> floor and terrace floor not in use						
2	as per affidavit dated 26.09.2019 submitted by owner						
	Type of case:- Renewal						
4.	Details of previous FSC:-	No. F6/DFS/MS/EH/NDZ/2018/1705 dated					
-		20/07/18					
5.	Fire safety directives No	N/A					
6.	Date of inspection:-	29/10/21					
7.	Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC)						
8.	Name & designation of officer						
	From the building side:-	Sh. Anil Kumar (Manager)					
	Year of construction:-	2009					
10.	Applicant's letter No:-	Id no 202108	1918209 dated 08.0	09.21 Old Case			
S.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks			
	Prevention and fire safety U/R 33	Existing fire safety		MR/NMR			
1.	Access to Building	arrangements					
	1) Road width	N/A	N/A	N/A			
	2) Gate width	N/A	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A			
<u> </u>							
2.	Number, Width Type & Arrangement of Exits           A. Number of staircases						
		01 Nos.	01 Nos.	MR			
	1. Upper floors	N/A	N/A	N/A			
	2. Basements						
	B. Width of staircase	0.80 mtr.	1.0 mtr.	MR			
	1. Upper floors	N/A	N/A	N/A			
	2. Basements	IN/A		14/21			
	C. Protection of exits	Dequired	Provided	MR			
	1. Fire check door	Required		N/A			
	2. Pressurization	N/A	N/A N/A	N/A N/A			
	D. No. of continuous staircase to terrace	N/A					
	E. Width of corridor	N/A	N/A	N/A			
-	F. Door size	01 mtr.	01 mtr.	MR			
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	,	N/A	N/A	N/A			
	5) File Dampers						
4.	Smoke Management System	30 ACPH	N/A	N/A			
	1) Basements	12 ACPH	Natural/	MR			
	2) Upper floors		Exhaust fan				
5.	Fire Extinguishers			MR			
	1) Total numbers	12 Nos.	12 Nos.				
	2) Types	ABC & CO2	ABC & CO2	MR			
	3) ISI marking	Required	Provided	MR			

	HV	0		
6.	First-Aid Hose Reel			•
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
	Automatic Fire Detection &			
	1) Type of detectors CO Type	Required	Provided	MR
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
3.	MOEFA	Required	Provided	MR
).	Public Address System	Required	Provided	MR
	Automatic Sprinkler System	Required	Tiovided	
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A N/A	N/A N/A	N/A N/A
	3) Sprinkler above false ceiling	N/A	N/A N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	225 LPM	225 LPM	MR
	b) Head of pump	18 mtr.	18 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for F			
	<ol> <li>Under ground tank capacity</li> </ol>	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	5000 ltr.	5000 ltr.	MR

15.	Exit Signage.	M/20	1	
16.	Provision of Lifts.	Required	Provided	MR
	<ul> <li>a) Pressurization of lift shaft</li> </ul>	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
17	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/NDZ/2018/1705 dated 20/07/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval upto third floor.

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: - ADO (CC)

Para

EHSTPH ETT ANTON

ET?

Aftaron P

Asappoured PT iput up for leve peres HDOCCE

111112

102

2

upbouched MHA onlive Bostul