030

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/ 339

Dated: 18 11 20 21

## FIRE SAFETY CERTIFICATE

Certified that M/s SANA-DI-GI Restaurant (A Unit of Goldfinch Hotels Pvt. Ltd) located at 22.48. Commercial Complex. Malcha Marg. Chanakyapuri, New Delhi, comprised of basement (storage only), ground plus two upper floors owned/occupied by M/s Goldfinch Hotels Pvt. Limited was issued FSC by this department vide letter No. F6/DFS/MS/EH/2019/SZ/296 Dated 06.02.2019. The restaurant premises was re-inspected by the officers concerned of this department on 12/11/2021 in the presence of Sh. Shiv Prasad and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules. 2010 and that the premises is fit for occupancy class "Assembly, Group-D" (Eating House) with effect from 18 / 11 /2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on \8 / \1 /2021 at New Delhi by

(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

## Copy to: -

- 1. Sh. K.P. Shetty (Director) "Sana-Di-Gi" (A Unit of Goldfinch Hotels Pvt. Ltd) at 22/48, Commercial Complex, Malcha Marg, Chanakyapuri, New Delhi-110021
- 2. Director Monitoring / Licensing Officer & Health Enforcement, New Delhi Municipal Council. Palika Kendra, New Delhi-01.

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

1							
		INSPECTIO	N REPOR	RT		Caldfingh	
1	Nan	ne & Address of the Building	M/o SANA DI-GI Restaurant (Unit of Goldfinch				
		_	Lintale Dut 1 td) at 22/48 (Commercial Complex,				
			Malcha Marg, Chanakyapuri, New Delhi-110021 Assembly, "Group-D" (Restt. at GF, FF & SF)				
2	Тур	oe of Occupancy	Assembly	, "Gro	up-D" (Restt. at Gr. r	r & 31)	
3	Bui	lding Comprised of	Basement	, Grou	nd + 2 upper floors.		
4	Тур	oe of Case	Renewal			6.02.2019	
5		ails of Previous NOC		1S/EH	/2019/SZ/296 Dated 0	0-02-2017	
6		e Safety Directives Letter No	Nil				
7		te of Inspection	12-11-2021				
8		me of the Inspecting Officers	DO (SD) & ADO (SJ)				
9		me & Designation of Officers	Sh. Shiv Prasad				
		m the building side					
10		ar of construction	1982	22000	D + 120 00 2021		
11		plicant letter received through MHA ID	2021092922900 Dated 29-09-2021			Remarks	
S. No.		nimum standards on Fire Prevention	Old No		Provided at Site	MR/NMR	
		d Fire Safety U/R 33	Requirer	nents		[VIII] TVIVII	
1	Ac	cess to Building.			9 mtr	MR	
		Road width	6 mt	-		-NA-	
		<ul> <li>Gate width</li> </ul>	-NA		-NA-		
		<ul> <li>Width of internal road</li> </ul>	-NA	-	-NA-	-NA-	
2	Nu	mber, width, type & arrangement of ex	its.				
	a)	Number of Staircase				1.45	
		Upper floors.	02 N	os	2 + 1 No (FF to SF)	MR	
		Basement floor.	02 N	os	Provided	MR	
	b)	Width of Staircase					
	-	<ul> <li>Upper floors</li> </ul>	1.5 mtr	1.5m.	Im & Im (FF to SF)	MR (old case)	
				1.4m	to 1.55 & 0.75m to	MD : 11	
		> Basement floor	1.5 mtr		0.95m	MR (old case)	
	<u>c)</u>	Protection of exits		l			
	()	Fire check door	-NA	-	-NA-	-NA-	
		> Pressurization	-NA	-	-NA-	-NA-	
	<b>d</b> )	No. of continuous staircase to terrace	Requi	red	01 No	MR	
		Width of corridor	-NA		-NA-	-NA-	
		Door size	2 m	r	2m & 1.25m	MR	
3	-	mpartmentation.					
	Cu	• Fire check door.	-NA	-	-NA-	-NA-	
		<ul> <li>Sealing of electrical shafts.</li> </ul>	Requi		Provided	MR	
		• Fire rating of shaft door.	-NA		-NA-	-NA-	
		Water curtain	-NA	and the second s	-NA-	-NA-	
		Fire dampers.	-NA		-NA-	-NA-	
4	e.	ooke Management system.	117			.,,,	
	311	Basement	30 AC	PH	Exhaust fan provide	ed MR	
			12 AC		Exhaust fan provide		
	-	• Upper floors / Restt. Area	12 // (	-111	Zanaust fair provide	WIIX	
_	Fir	re Extinguishers.	Dagos	rad	OO Niga	MAD	
5		<ul> <li>Total numbers</li> </ul>	Requi		08 Nos	MR	
5		T	4 131	CUZ	ABC & CO2	MR	
5		• Types			D ' ' '	1.00	
	,	ISI Marking	ISI ma		Provided	MR	
6	,	• ISI Marking rst Aid Hose Reels.	ISI ma	rked			
	,	<ul> <li>ISI Marking</li> <li>st Aid Hose Reels.</li> <li>Total numbers on each floor.</li> </ul>	ISI ma	rked e	Provided at GF & F	FF MR	
	Fir	• ISI Marking rst Aid Hose Reels.	ISI ma	rked e n			

M s SANA-DI-GI Restt at 22-48, Commercial Complex, Malcha Marg, Chanakyapuri, New Delhi

w.

7		/ 14		
	Automatic fire detection & alarming system.			
	Type of detectors	Required	Heat & Smoke	MR
	<ul> <li>Location of Main Panel</li> </ul>	Required	Reception	MR
	<ul> <li>Location of Repeater Panel</li> </ul>	-NA-	-NA-	-NA-
	<ul> <li>Alternate source of power</li> </ul>	Required	Provided	MR
0	Hooter's location	Required	All floors	MR
9	MOEFA	Required	Provided	MR
	Public Address System	-NA-	-NA-	-NA-
10	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	<ul> <li>Upper floors.</li> </ul>	Required	Provided	MR
	<ul> <li>Sprinkler above false ceiling</li> </ul>	-NA-	-NA-	-NA-
11	Internal Hydrants.			
	<ul> <li>Size of Riser/Down-comer</li> </ul>	100 mm	Provided	MR
	<ul> <li>Number of Hydrant per floor</li> </ul>	One	Provided	MR
	<ul> <li>Hose box.</li> </ul>	One	Provided	MR
12	Yard Hydrants.			
	<ul> <li>Total number of hydrants.</li> </ul>	-NA-	-NA-	-NA-
	<ul> <li>Hose box.</li> </ul>	-NA-	-NA-	-NA-
13	Pumping arrangements.		1	1
	Ground Level			
	<ul> <li>Discharge of main pump.</li> </ul>	-NA-	-NA-	-NA-
	<ul><li>Head of main pump.</li></ul>	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	<ul> <li>Jockey Pump output.</li> </ul>	-NA-	-NA-	-NA-
	<ul> <li>Jockey Pump head.</li> </ul>	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			
	<ul> <li>Discharge of pump.</li> </ul>	900 LPM	900 LPM	MR
	Head of pump.	40m	40m	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	-NA-	-NA-	-NA-
	Praw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
1.5	Overhead tank capacity.  Fig. 1. Signs and 1. Signs	10,000 Ltr	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	XI A		
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage.	-NA-	-NA-	-NA-
7	Standby Power Supply	Required	Provided (Gen Set)	MR
8	Refuge Area			
	Total area	-NA-	-NA-	-NA-
	<ul> <li>Location</li> </ul>	-NA-	-NA-	-NA-

M.s.S.IN.4-DI-GI Resti at 22-48, Commercial Complex, Malcha Marg. Chanakyapuri, New Delhi



19	Fire Control Room.			
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	<ul><li>PA system panel.</li><li>Battery backup.</li><li>Building floor plan.</li></ul>	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			

M s SANA-DI-GI Restt at 22-48, Commercial Complex, Malcha Marg, Chanakyapuri, New Delhi

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/EH-2019/SZ 296 Dated 06-02-2019, renewal under rule 37 of the Delhi Fire Service Rules 2010, is recommended.

Accordingly DFA is put up for approval and signature please

Signature of Inspecting Officer

Name: S.K. Dua Design: DO (SD) Signature of Inspecting Officer

Name: A.K. Jaismal Design: ADO (51)

A DOKS > F.T. is adoled be.

Y CFO/(SZI /) 18/11/20.

m.s. cell