C-8

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No.F.6/DFS/MS/School/2021/SZ/ 953

Dated: 24/11/21

## FIRE SAFETY CERTIFICATE

Issued on 241.1. ANew Delhi by

Director

thi Fire Service

Delhi Fire Service

To,

The Principal,

D.T.E.A. Sr. Sec. School, B-1, Janakpuri, New Delhi-58.

## Copy to:-

The Director of Education, Govt of NCT of Delhi, Old Secretariat, New Delhi-110054.

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

1. Name & address of the building: D.T.E.A. Sr. Sec. School, B-1, Janakpuri, New Delhi-58.

2. Building is comprised of

: Ground plus Two upper floors

3. Type of Occupancy

: Educational

: New

4. Type of Case

5. Details of Previous NOC letter : N/A

: NBC Part-IV

6. Fire Safety Circular No. 7. Date of Inspection

:12/11/2021

8. Name of the Inspecting officers : ADO R.K. Yadav

9. Name and designation of

: Smt. Ranjan Gupta (Principal)

Officer from the building side 10. Year of Construction

: 2005

: Nil dated 22/10/2021

App	Minimum Standards on fire prevention	Requirement	Provided at Site	Remarks	
)	Minimum Standards on The P				
	and fire safety U/R33		06 M	MR	
	Access to building	06 M		MR	
	Road width	05 M	05 M		
	• Gate width	N/A	N/A	N/A	
	• Width of internal road		•		
	Number, Width, Type and Arrangement	OFERICO		MR	
	a Number of Staircases	02 Nos.	02 Nos.		
	• Upper Floor	N/A	N/A	N/A	
	Basement	14/14			
	B. Width of Staircases	1.5 M	1.5 M	MR	
	• Upper Floor	N/A	N/A	N/A	
	Basement	18/73			
	c Protection of exits	N/A	N/A	N/A	
	• Fire check door	N/A	N/A	N/A	
	<ul> <li>Pressurization</li> </ul>	2 Nos	2 Nos	MR	
	e. No. of continuous staircases to		1.5 M	MR	
	terrace	1.5 M		MR	
	g. Width of Corridor	1.2 M	1.20 M		
	h Door Size	N/A			
3	Compartmentation.	N/A	N/A	N/A	
-	Fire check door	N/A	N/A	N/A	
	• Sealing of electrical shafts	N/A	N/A	N/A	
	<ul> <li>Fire rating of shaft door</li> </ul>	N/A	N/A	N/A	
-	<ul> <li>Water curtain</li> </ul>	N/A	N/A	14/1	
	• Fire Dampers				
-	Smoke Management System.	N/A	N/A	N/A	
-	Basement	N/A	N/A	N/A	
	• Upper floor	1011		F 417	
-	5. Fire Extinguishers	06 Nos	06 Nos.		
	• Total numbers	ABC & C		o2 MR	
	• Types	ISI mark		ed MR	
-	IS marking	151 mark			

6	First-aid-Hose Reels.						
U	Total numbers of each floor	1 Nos	1 Nos	MR			
	• Length of hose reel hose	30M	30M	MR			
	Nozzle diameter						
		5mm	5mm	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Y	N/A	N/A	N/A			
	C	N/A	N/A	N/A			
	Alternate source of power						
	Hooter's location	N/A	N/A	N/A			
8	MOEFA	N/A	N/A	N/A			
9	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.	N/A	N/A	N/A			
	Basement	N/A	N/A	N/A			
		N1/A	N/A	N/A			
	• upper floor	N/A		N/A			
	sprinkler above false ceiling	N/A	. N/A	N/A N/A			
11	Internal Hydrants	N/A	N/A				
	size of riser/down-comer	N/A	N/A	N/A			
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.	N/A	N/A	N/A			
12	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Pumping Arrangements.	N/A	N/A	N/A			
13	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	> Jockey pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	> Standby pump out put	N/A	N/A	N/A			
	> Standby pump Head	N/A	N/A	N/A			
-	> Auto Starting /Manual stopping	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	Terrace Level						
	> Discharge of pump	450LPM	450LPM	MR			
	> Head of the Pump	40M	40M	MR			
	> Power supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
	Continuo Con	N/A	N/A	N/A			
14	The state of the s	N/A	N/A	N/A			
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A N/A	N/A	N/A			
	Fire service inlet	N/A N/A	N/A	N/A			
	> Access to tank	10,000Ltrs	Provided	MR.			
	Overhead Tank capacity		Provided	MR			
15	Exit Signage.	Required	Trovided	IVIIX			

16	Provision of Lifts.	N/A	N/A	N/A
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N/A	N/A	N/A
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A
	<ul> <li>Communication in lift car</li> </ul>	N/A	N/A	N/A
	<ul> <li>Firemen's grounding switch</li> </ul>	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	<ul> <li>Detector system panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Flow switch panel</li> </ul>	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/checked at the time of inspection. The shortcomings was issued vide letter no. F6/DFS/MS/School/2011/1844 dated 04/08/2011 has been complied

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety as required under the rule 35 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

Name- R.K. Yadav

Designation-ADO(JKP)

DO(South West)

Dy cho sin

16/11/2021

CFO-

Land 10/1