

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI

C-47


No: F6/DFS/MS/School/MN/2021 / 378

Dated: 03 / 12 / 2021

FIRE SAFETY CERTIFICATE

Certified that the **Guru Teg Bahadur 3rd century Public School** located at **C- Block Mansarovar Garden New Delhi – 110015** comprised of 04 blocks (A & B Blocks Ground Plus Two Upper floors, C & D Blocks ground Plus One upper floor) was issued FSC vide letter No. F6/DFS/MS/School/2018/1910 dated 16/08/2018. The premises was re-inspected by the officer concerned by this department on 25/11/2021 in the presence of Sh. Ravi Kumar and observed that all the fire prevention & fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention & fire safety requirements in accordance with Circular No. F16/Estate/CC/Fire safety/2011/3298 to 3398 dated 01/03/2011/NBC part-IV issued by the Directorate of education and found that the premises is fit for occupancy class "Educational" Group B with effect from 03 / 12 / 2021 for a period of three years in accordance with effect from rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 conditions mentioned below:-

Issued on ... 03 / 12 / 2021 ... at New Delhi.


(Dharampal Bhardwaj)
Dy. Chief Fire Officer,
Delhi Fire Service

Copy to:

1. The Principal, Guru Teg Bahadur 3rd century Public School Mansarovar Garden New Delhi – 110015.

2. Director of Education, Old Sectt. Delhi-110054

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
8. The auditorium shall not be used for any purpose till fire safety clearance is received from this deptt.

N-32

INSPECTION REPORT

1. Name & address of the building : Guru Teg Bahadur 3rd century Public School Located at C-Block, Mansarovar Garden, New Delhi-110015.
2. Type of Occupancy : Educational
3. Type of Case : Renewal
4. Details of previous NOC : F6/MS/DFS/School/2018/1910 dated 16/08/2018
5. Fire Safety directives letter No : Nil
6. Date of inspection : 25/11/2021
7. Name of the Inspecting Officers : Sarabjeet Singh ADO(MN)
8. Name and designation of officers from the building side : Sh. Ravi Kumar
9. Year of Construction : 1979 (As per precious inspection report)
10. Applicant's letter No. : Email dated 18/11/2021

4 Block (78 Class Rooms)
 A = G + 2 Upper Floors
 B = G + 2 Upper Floors
 C = G + 1 Admin Office
 D = G + 1 Primary Wing
 A & D blocks are connected at 1st Floor
 B & C blocks are connected at 1st Floor
 Total Area 2.5 acre,
 Covered area = 4449 Squads

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement/Prev. Ins. Report dtd.-02/08/2018	Provided at site	Remarks MR/NM R
1	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible Accessible N/A	4.5 m Provided 4.7 m Provided N/A	MR MR N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	A Block=2 B Block=2 C Block=1 D Block=1 N/A	Provided N/A	MR N/A
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	1.5 m N/A	ABlock=1X180,1X130,1X150 cms (Iron Staircase) B Block=1X150,1X160 cms C Block=1x120(Connected to BL-A at 1 st floor) D Block=1X130,1X110cms(1 st floor not used for school activity) N/A	MR N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	N/A N/A	N/A N/A	N/A N/A
	e. No. of continuous staircases to terrace			
	f. Width of Corridor			
	g. Door Size			
		1	Provided	MR
		1.5m	Provided	MR
		1m	Provided (with door frame)	MR Being old case
3	Compartmentation.			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
4	Smoke Management System.			
	<ul style="list-style-type: none"> • Basements • Upper floors 	30 a/c per hour 12 a/c per hour	N/A N/A	N/A N/A

N-33				
5	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers Types IS marking 	20 nos CO ₂ , ABC type ISI marked	Provided	MR
			Provided	MR
			Provided	MR
6	First-Aid Hose Reels.			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	Required	Provided	MR
		30m	Provided	MR
		5mm	Provided	MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
8	MOEFA			
		N/A	N/A	N/A
9	Public Address System.			
		N/A	N/A	N/A
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
11	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	N/A	Provided	N/A
		N/A	Provided	N/A
		N/A	Provided	N/A
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A	N/A	N/A
		N/A	N/A	N/A
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	NR	900 Lpm & 450 Lpm	MR
		N/A	40m	MR
		NR	NR	NR
		NR	NR	NR
		NR	NR	NR
		NR	NR	NR
		NR	NR	NR
		NR	NR	NR
		N/A	N/A	N/A
		450Lpm	Provided at G.F	MR Being old case
		40m	Provided at G.F	MR
		Required	Provided at G.F	MR
		Required	Provided at G.F	MR
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet 	N/A	50,000 ltrs	MR
		N/A	N/A	N/A
		N/A	N/A	N/A

D.P.

N-34

	<ul style="list-style-type: none"> ➤ Access to tank • Overhead Tank capacity 	N/A	N/A	N/A
15	Exit Signage.	10,000 ltrs	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Batter backup • Building Floor Plans 	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The shortcomings issued by this department vide letter no F6/DFS/MS/School/MN/2021/441 dated 27/08/2021 & F6/DFS/MS/WZ/School/2021/546 dated 07/10/2021 have been complied.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no.F6/DFS/MS/School/2018/1910 dated 16/08/2018 renewal under DOE Circular no. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Directorate of Education, Govt. OF NCT of Delhi, is recommended.

328/ADOMN
29/11/2021

~~Do (west)~~

~~Signature~~
29/11/2021

Signature of the Inspecting Officer
Name: Sarabjeet Singh
Designation: ADOMN)

306/DO/WD
dt 29/11/2021

~~Signature~~ 29/11/2021
DO (WZ)
20/11/2021

~~Signature~~

Sir F.T. is put up for your personal & signature please!

ms/agg

~~Signature~~
01/12/2021