

C-12

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE
CONNAUGHT PLACE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/ 357

Dated: 7/12/2021

FIRE SAFETY CERTIFICATE

Certified that M/s **Monet** (A unit of Flashbolt Restaurant Pvt. Ltd) at Shop No. CG-04 & C-05, Ground Floor, Block-C, Ansal Plaza Mall, Hudco Place, Khelgaon Marg, Andrews Ganj, New Delhi-110049, comprised of two basements, ground, mezzanine plus three upper floors but Restaurant located at Ground Floor only has complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 01/12/2021 in the presence of Mr. Vishal Prabhakar (Partner) of the restaurant and that the premise is fit for occupancy class "Assembly, Group-D" (Restaurant) with effect from 7/12/2021 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 7/12/2021 at New Delhi by


(Anil Garg)

Director

Delhi Fire Service

Copy to: -

1. The Dy. Health Officer, South MCD, Public Health Department, South Zone, Aurobindo Marg, Green Park, New Delhi-110016 [w.r.t online ID: 2021112326988 dated 25/11/2021]
2. M/s Monet (U/o Flashbolt Restaurant Pvt. Ltd), CG-04 & C-05, Ground Floor, Block-C, Ansal Plaza Mall, Hudco Place, Khelgaon Marg, Andrews Ganj, New Delhi-110049

Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	M/s Monet (A Unit of Flashbolt Restaurant Pvt. Ltd), CG-04 & C-05, Ground Floor, Block-C, Ansal Plaza Mall, Hudco Place, Khelgaon Marg, Andrews Ganj, New Delhi-110049		
2	Type of Occupancy	Assembly "Group-D" (Restaurant)		
3	Building Comprised of	Two tier basement, Ground, Mezzanine plus three upper floors. But restaurant is at GF only.		
4	Type of Case	New		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	01/12/2021		
8	Name of the Inspecting Officers	DO (SD) & ADO (SJ)		
9	Name & Designation of Officers from the building side	Mr. Vishal Prabhakar		
10	Year of construction	1997-1999		
11	Applicant letter No./Online ID No.	2021112326988 dated 25/11/2021		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC / UBBL Requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.	(FSC No: F6/DFS/MS/Mixed/2020/SZ/359 Dated 11/09/2020)		
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Eating house within Ansal Plaza Mall	As above As above As above	MR MR MR
2	Number, width, type & arrangement of exits.	Provided & Maintained by Bldg. Mgmt		
	a) Number of Staircase	Provided & Maintained by Bldg. Mgmt		
	➤ Upper floors.	-NA-	As above	-NA-
	➤ Basement floor.	-NA-	As above	-NA-
	b) Width of Staircase	Provided & Maintained by Bldg. Mgmt		
	➤ Upper floors	-NA-	As above	-NA-
	➤ Basement floor	-NA-	As above	-NA-
	c) Protection of exits	Provided & Maintained by Bldg. Mgmt		
	➤ Fire check door	Required	As above	MR
	➤ Pressurization	-NA-	As above	-NA-
	d) No. of continuous staircase to terrace	Required	As above	MR
	e) Width of corridor	-NA-	As above	-NA-
	f) Door size	1.5m (2 exits)	1.5m & 1.5m	MR
3	Compartmentation.	Provided & Maintained by Bldg. Mgmt		
	• Fire check door.	Required	Provided	MR
	• Sealing of electrical shafts.	Required	Provided	MR
	• Fire rating of shaft door.	Required	Provided	MR
	• Water curtain	-NA-	-NA-	-NA-
	• Fire dampers.	-NA-	-NA-	-NA-
4	Smoke Management system.	Provided & Maintained by Bldg. Mgmt		
	• Basement	30 ACPH	-NA-	-NA-
	• Upper floors/Restt. Area	12 ACPH	Exhaust fans	MR
5	Fire Extinguishers.	Provided & Maintained by Bldg. Mgmt		
	• Total numbers	06 Nos	Provided	MR
	• Types	ABC, CO ₂ , WCO ₂	ABC & CO ₂	MR
	• ISI Marking	ISI marked	Provided	MR
6	First Aid Hose Reels.	Provided & Maintained by Bldg. Mgmt		
	• Total numbers on each floor.	One (near Restt.)	Provided	MR
	• Length of hose-reel hose.	30m	Provided	MR
	• Nozzle Diameter	5mm	Provided	MR

7	Automatic fire detection & alarming system. (Provided & Maintained by Bldg. Mgmt)	Smoke & Heat Ground Floor	Smoke & Heat Ground Floor	M/R M/R
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooter's location 	-NA-	-NA-	-NA-
8	MOEFA	Required	Provided	MR
9	Public Address System	-NA-	-NA-	-NA-
10	Automatic Sprinkler System	Provided & Maintained by Bldg. Mgmt		
	<ul style="list-style-type: none"> Basement Ground floor. Sprinkler above false ceiling 	-NA-	-NA-	-NA-
		Required	Provided	MR
		-NA-	-NA-	-NA-
11	Internal Hydrants.	Provided & Maintained by Bldg. Mgmt		
	<ul style="list-style-type: none"> Size of Riser/Down-comer Number of Hydrant per floor Hose box. 	150 mm	Provided	MR
		One (near Restt.)	Provided	MR
		One (near Restt.)	Provided	MR
12	Yard Hydrants.	Provided & Maintained by Bldg. Mgmt		
	<ul style="list-style-type: none"> Total number of hydrants. Hose box. 	-NA-	As above	-NA-
		-NA-	As above	-NA-
13	Pumping arrangements.	Common for entire complex/building		
	<ul style="list-style-type: none"> Ground Level Discharge of main pump. Head of main pump. Number of main pumps. Jockey Pump output. Jockey Pump head. Standby Pump output. Standby Pump head. Auto Starting/Manual Stopping. Pump house access. 	Provided & Maintained by Bldg. Mgmt		
		4050 LPM	4050 LPM	MR
		90m	90m	MR
		02 Nos	02 Nos	MR
		450 LPM	450 LPM	MR
		90m	90m	MR
		8100LPM	8100LPM	MR
		90m	90m	MR
		Required	Provided	MR
		Required	Provided	MR
	<ul style="list-style-type: none"> Terrace Level Discharge of pump. Head of pump. Power supply. Auto starting of pump. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
14	Captive water storage for fire fighting.	Common for entire complex/building		
	<ul style="list-style-type: none"> Underground tank capacity. Draw-off connection. Fire Service Inlet. Access to tank. Overhead tank capacity. 	450000 Ltrs	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		20,000 Ltrs	Provided	MR
		Required	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provided & Maintained by Bldg. Mgmt		
	<ul style="list-style-type: none"> Pressurization of lift shaft. Pressurization of lift lobby. Communication in lift car. Fireman's switch. Lift signage. 	-NA-	As above	-NA-
		-NA-	As above	-NA-
		-NA-	As above	-NA-
		-NA-	As above	-NA-
		-NA-	As above	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	<ul style="list-style-type: none"> Total area Location 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-

- 173 -

19	Fire Control Room.	Provided & Maintained by Bldg. Mgmt			
		Detector system panel.	Required	Provided	MR
		Flow switch panel.	-NA-	-NA-	-NA-
		PA system panel.	Required	Provided	MR
		Battery backup.	Required	Provided	MR
	Building floor plan.	-NA-	-NA-	-NA-	
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-	

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

S.K. Dua
30/11/21

Signature of the Inspecting Officer
Name : S. K. Dua
Designation: DO (SD)

A.K. Jaiswal
30/11/21 2021

Signature of the Inspecting Officer
Name : A. K. Jaiswal
Designation: ADO (SJ)

DCFO (SZ)

[Signature]
1/12

C.F.O. (D. off)

~~Director~~
21/12/2021
H/Ph

~~0450~~

F.T. letter is put up for sig. pl.

~~Inspector~~
[Signature]
mu

S.K. Dua
30/11/21