

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 532

Dated: (7.../1.2./2021

-91

FIRE SAFETY CERTIFICATE

Certified that the Karan Place Guest House located at 2957/2, Chuna Mandi, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (02 guest rooms + reception + office), 1st floor to 3rd floor (07 guest rooms at each floor) & 4th floor (sealed by MCD), total 23 guest rooms was earlier granted FSC by this department vide letter no.F6/DFS/MS/GH/NDZ/2018/2328 dated 15/10/18. Now, the premises was re-inspected by the officer concerned of this department on 10/12/21 in the presence of Sh. Sahanavz and found that the said guest house building having shops at ground floor, 1st floor (06 Guest rooms) & 2nd to 3rd floor (07 guest rooms at each floor), has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 1st floor (06 Guest room up to third floor only, with effect from ..., The safety require floor (07 guest rooms at each floor) total 20 guest room up to third floor only, with effect from ..., The safety require a safety require strong the safety rooms at each floor), period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

(**Dr. S.K. Tomar**) Dy.Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North Delhi Municipal Corporation, Civic Centre, New Delhi: to ensure the occupancy as detailed above
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2021111726574 dated 17.11.2021.
- 3. The Manager,

Karan Place Guest House, 2957/2, Chuna Mandi, Pahar Ganj, New Delhi. Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

	INCD	ECTION REPO	N/28				
1	Name & address of the building	ECTION REPOR	Guest House at 29	57/2, Chuna			
1.	Name & address of the building	Karan Flace	Guest House at 2	i			
C	Type of occupancy:-	Desidential	ar Ganj, New Delh				
Ζ.	Type of occupancy:-	Residential,	Sub Division-A-1 r floors (total 20 Gue	st rooms)			
		0 10	-1				
		1 st floor(06 gu	est room & reception)	2^{nd} to to 3^{rd}			
		floor (07 mes	t rooms at each level				
		4 th floor (seale	d by MCD) having gi	ven an ailidavit			
	dated 11.12.2019 regarding not to use any floor						
	above third floor.						
	Type of case:-	Renewal		0/2220 dated			
4.	Details of previous FSC:-	No. F6/DFS/MS/GH/NDZ/2018/2328 dated					
	15/10/18.						
5.	Fire safety directives No	N/A					
6.	Date of inspection:-	10/12/21					
	Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC)						
8.	Name & designation of officer						
	From the building side:-	Sh. Sahanavz					
9.	Year of construction:-	Old					
10	. Applicant's letter No:-	Online id no.20	21111726574 date	d 17.11.2021. Old Case			
S.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks			
5.INU.	Prevention and fire safety U/R 33	Existing fire safety		MR/NMR			
1.	Access to Building	arrangements					
1.	1) Road width	N/A	04 mtr.	MR			
		N/A	N/A	N/A			
	2) Gate width			N/A			
	3)Width of internal road	N/A	N/A	10/11			
2.	Number, Width Type & Arr	angement of Ex					
	A. Number of staircases		01 Nos.	MR			
	1. Upper floors	01 Nos.		N/A			
	2. Basements	N/A	N/A	IN/A			
	B. Width of staircase						
	1. Upper floors	0.96 mtr.	0.96 mtr.	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous	01	01	MR			
	staircase to terrace						
		N/A	N/A	N/A			
	E. Width of corridor	01 mtr.	01 mtr.	MR			
	F. Door size	vi mu.					
3.	Compartmentation		N/A	N/A			
	1) Fire check door	N/A		N/A			
	2) Sealing of electrical shafts	N/A	N/A				
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
	Smoke Management System						
4.	1) Basements	30 ACPH	N/A	N/A			
	 Basements Upper floors 	12 ACPH	Exhaust fan	MR			
	LON LINNET TIOOTS						
5	Fire Extinguishers	08 Nos	08 Nos.	MR			
5.	Fire Extinguishers 1) Total numbers	08 Nos.	08 Nos. ABC & CO2	MR MR			
5.	Fire Extinguishers	08 Nos. ABC & CO2 Required	08 Nos. ABC & CO2 Provided				

N/29

6.	First-Aid Hose Reel	17 12	-	<u> </u>			
	1) Total number of eachfloor	01	01	MR			
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR			
	3) Nozzle diameter	05 mm	05 mm	MR			
7.	Automatic Fire Detection & Alarming System						
	1) Type of detectors	Required	Provided	MR			
	2) Location of main panel	Gr. floor	Gr. floor	MR			
	3) Location of repeater panel	N/A	N/A	N/A			
	4) Alternate source of power	Required	Provided	MR			
	5) Hooter's Location	Each floor	Provided	MR			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System						
	1) Basement	N/A	N/A	N/A			
	2) Upper floors	N/A	N/A	N/A			
	3) Sprinkler above false	N/A	N/A	N/A			
	ceiling						
11.	Internal Hydrants						
	1) Size of riser/down-comer	N/A	N/A	N/A			
	2) Number of hydrants per	N/A	N/A	N/A			
	floor						
	3) Hose box	N/A	N/A	N/A			
12.	Yard Hydrants						
	1) Total number of hydrants	N/A	N/A	N/A			
	2) Hose box	N/A	N/A	N/A			
13.	Pumping Arrangement						
_	1) Ground level	N/A	N/A	N/A			
	a) Discharge of main	N/A	N/A	N/A			
	pump						
	b) Head of main pump	N/A	N/A	N/A			
	c) Number of main pump	N/A	N/A	N/A			
	d) Jockey pump out put	N/A	N/A	N/A			
	e) Jockey pump head	N/A	N/A	N/A			
	f) Stand by pump output	N/A	N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual	N/A	N/A	N/A			
	stopping						
	2) Terrace level						
	a) Discharge of pump	450 LPM	450 LPM	MR			
	b) Head of pump	30 mtr.	30 mtr.	MR			
	c) Power supply	Required	Provided				
	d) Auto starting of pump	Required		MR			
			Provided	MR			
1.	Captive Water Storage for Fi		21/4				
	1) Under ground tank	N/A	N/A	N/A			
	capacity						
	a) Draw-off connection	N/A	N/A	N/A			
	b) Fire service inlet	N/A	N/A	N/A			
	c) Access to tank	N/A	N/A	N/A			
ŀ	d) Over head tank	2500 ltr.	2500 ltr.	MR			
	capacity						
		Required	Provided	MD			
•	Exit Signage.	Required	Provided	MR			

16.	Provision of Lifts.	1		
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2018/2328 dated 15/10/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Ar apporred pri patrip for foresed and sprohm Please

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

NAG (KOZ

NIZO