GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001**

No.F6/DFS/MS/EH/NDZ/2021/ Hotel 33

Dated: 13/12/2021

FIRE SAFETY CERTIFICATE

Certified that the M/S PRIVEE NOVELE XO, (A Unit of MJ Bizcrafts LLP) Hotel Shangrilla, Eros, Kanishka Shopping Arcade, 19, Ashoka Road, New Delhi. comprises of Ground + 02 Upper floor, Restaurant is running at ground floor owned/occupied Restaurant was earlier granted FSC by this department vide letter no. F6/DFS/MS/EH/2019/NDZ/09 dated 02/01/19. Now, The premises was re-inspected by the officer concerned of this department on 06/12/21 in the presence of Mr.Rajeev Ranjan and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly Building Group D, Restaurant at ground floor only with effect from. [3. 1.2.202]...for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below. X 0 mm

Issued $\frac{3}{2}$ $\frac{202}{2}$ at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire officer Delhi Fire Service

Copy to:-

- 1. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID no. 2021111226183 dated 12.11.21.
- 2. The Manager, M/S PRIVEE NOVELE XO, (A Unit of MJ Bizcrafts LLP) Hotel Shangrilla, Eros, situated at Kanishka Shopping Arcade, 19, Ashoka Road, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid only for restaurant at ground floor only.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior
- 9. Any flammable material for interior decoration is prohibited.

NID

INSPECTION REPORT

1. Name & address of the building M/S PRIVEE NOVELE XO, (A Unit of MJ Bizcrafts

LLP) – at Hotel Shangrilla, Eros, Kanishka Shopping Arcade, 19, Ashoka Road, New Delhi.

2. Type of occupancy:- Assembly Building Group-D

Gr. + 02 but Restaurant is running at ground floor only

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/EH/2019/NDZ/09 dated

02/01/19.

5. Fire safety directives No.- N/A

6. Date of inspection:- 06/12/21

7. Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC)

Sh. Rajinder Atwal DO (CD)

8. Name & designation of officer From the building side:-

9. Year of construction:-

Sh. Rajeev Ranjan

Old Heritage

10. Applicant's letter No:- ID No. 2021111226183 dated 12.11.21.

	Applicant's letter No:-			Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	09 mtr.	09 mtr.	MR
	2) Gate width	05 mtr	05 mtr	MR
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arra		its	
.	A. Number of staircases			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	N/A	N/A	N/A
	staircase to terrace			,
	E. Width of corridor	1.5 mtr	1.5 mtr	MR
	F. Door size	2 mtr.x 2	2 nos. 2 mtr & 1 nos.1.20 mtr.	MR
3.	Compartmentation			
<u>J.</u>	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	Required	Provided	MR
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System		T	N T / A
7.	1) Basements	N/A	N/A	N/A
	2) Upper floors	12 ACPH	Natural	MR
5.	Fire Extinguishers	,		\ (D)
J.	1) Total numbers	08 Nos.	10 Nos.	MR
		ABC & CO2	ABC & CO2	MR
	2) Types 3) ISI marking	Required	Provided	MR

NIS3

		MISS		
6.	First-Aid Hose Reel			7
0.	1) Total number	02	02	MR
	2) Length of hose reel hose	30 mtr.	36 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syst	em	- 10
/•	1) Type of detectors	Required	Provided	MR
	2) Location of main panel	Ground	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Ground	Provided	MR
0	MOEFA	Required	Provided	MR
8.	Public Address System	Required	Provided	MR
9.	Automatic Sprinkler System			
10.	1) Basement	N/A	N/A	N/A
		Required	Provided	MR
	2) Upper floors3) Sprinkler above false	N/A	N/A	N/A
		1377		
11	ceiling			
11.	Internal Hydrants 1) Size of riser/down-comer	100 mm	150 mm	MR
	2) Number of hydrants	01	02	MR
	3) Hose box	01	02	MR
10	,	01	02	
12.	Yard Hydrants	02	02	02
	1) Total number of hydrants 2) Hose box	02	02	02
10	,		arrangements is o	onnected with
13.	Pumping Arrangement	sangrila Hotel		
	1) Ground level	Sangi na 110te.		
	a) Discharge of main	2850 LPM	2850 LPM	MR
	pump	2000 21112		
	b) Head of main pump	60 mtr.	60 mtr.	MR
	c) Number of main	02	02	MR
	pump			
	d) Jockey pump out put	180 LPM	180 LPM	MR
	e) Jockey pump head	60 mtr.	60 mtr.	MR
	f) Stand by pump	2850 LPM	2850 LPM	MR
	output			
	g) Stand by pump head	60 mtr.	60 mtr.	MR
	h) Auto	Required	Provided	MR
			I	
	starting/Manual		1	
	starting/Manual stopping			
	_			
	stopping	N/A	N/A	N/A
	stopping 2) Terrace level a) Discharge of pump	N/A N/A	N/A	N/A N/A
	stopping 2) Terrace level			
	stopping 2) Terrace level a) Discharge of pump b) Head of pump	N/A	N/A	N/A
	stopping 2) Terrace level a) Discharge of pump b) Head of pump c) Power supply	N/A N/A	N/A N/A	N/A N/A
14.	stopping 2) Terrace level a) Discharge of pump b) Head of pump c) Power supply d) Auto starting of	N/A N/A N/A	N/A N/A	N/A N/A
14.	stopping 2) Terrace level a) Discharge of pump b) Head of pump c) Power supply d) Auto starting of pump Captive Water Storage for 1 1) Under ground tank	N/A N/A N/A	N/A N/A N/A	N/A N/A
14.	stopping 2) Terrace level a) Discharge of pump b) Head of pump c) Power supply d) Auto starting of pump Captive Water Storage for I 1) Under ground tank capacity	N/A N/A N/A Fire Fighting 2,50,000 ltr.	N/A N/A N/A 2,50,000 ltr.	N/A N/A N/A
14.	stopping 2) Terrace level a) Discharge of pump b) Head of pump c) Power supply d) Auto starting of pump Captive Water Storage for I 1) Under ground tank capacity a) Draw-off connection	N/A N/A N/A Fire Fighting 2,50,000 ltr. Required	N/A N/A N/A 2,50,000 ltr. Provided	N/A N/A N/A N/A N/A
14.	stopping 2) Terrace level a) Discharge of pump b) Head of pump c) Power supply d) Auto starting of pump Captive Water Storage for I 1) Under ground tank capacity	N/A N/A N/A Fire Fighting 2,50,000 ltr.	N/A N/A N/A 2,50,000 ltr.	N/A N/A N/A



MR

				5
	d) Over head tank	50,000 ltr.	50,000 ltr.	MIK
	capacity		-	MR
15.	Exit Signage.	Required	Provided	
16.	Provision of Lifts.			VI/A
	a) Pressurization of lift	N/A	N/A	N/A
	shaft			N/A
	b) Pressurization of lift	N/A	N/A	
	lobby			N/A
	c) Communication in lift	N/A	N/A	17/17
	car			A1/A
	d) Fireman's switch	N/A	N/A	N/A
		N/A	N/A	N/A
17.		Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Duilding Boom alon	N/A	N/A	N/A
	e) building 1100r pian	N/A		
20.	Special Fire Protection System for Protection of special Risk,	for Protection		N/A
	ıt any:			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Firefighting arrangements for restaurant is connected with Hotel and other parameters which are not required has been deleted in the present inspection report. In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no.F6/DFS/MS/EH/2019/NDZ/09 dated 02/01/19, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer $\lim_{N \to \infty} \frac{1}{N} |\mathcal{V}|^{|\mathcal{V}|}$ Name :- Sh. Rajinder Atwal

Designation :- DO(CD)

Name :- Sh. Ravinder Singh Designation :- ADO (CC)

Signature of the Inspecting Officer

4

Fire Se

2000

ylladded MHA auliuc Posbul Ywyli 17/11/01/01/V