154

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2021/ 527

Dated: 14/12/2021

FIRE SAFETY CERTIFICATE

Certified that the M/S Yes Sir Guest House located at T-419, General Market, Main Bazar, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception), 1st floor (02 guest rooms + 01 store), 2nd floor (04 guest rooms), 3rd floor (04 guest rooms) and 4th floor (03 guest rooms), total 13 guest rooms owned/occupied by M/s Yes Sir letter Guest department vide House was granted this **FSC** by F6/DFS/MS/GH/2018/NDZ/968 dated 09/05/18. Now, the premises was re-inspected by the officer concerned of this department on 03/12/21 in the presence of Mr. Manohar Ahamad and found that the said guest house building having given an per affidavit dated 14.01.20 not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception), 1st floor (02 guest rooms + 01 store), 2nd floor to 3rd floor (03 guest rooms at each floor) Total - 08 guest rooms up to third floor only with effect from 14 12 2021 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 14 12 2021 at New Delhi by.

(**Dr. S.K.Tomar**)

Dy. Chief Fire Officer

Relhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed and not to use any floor above third floor
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. 2021052613562 dated 26/05/2021 & email brijk943@gmail.com dated 26.11.21
- 3. The Manager, M/s Yes Sir Guest House, T-419, General Market, Main Bazar, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

1. Name & address of the building M/s Yes Sir Guest House at T-419, General Market, Main Bazar, Pahar Ganj, New Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

Ground + 03 Upper floors (total 08 guest rooms) Ground floor (Reception), 1st floor (02 guest rooms + 01 store), 2nd floor (03 guest rooms), 3rd floor (03 guest rooms) and 4th floor (03 guest rooms) not

In use as per affidavit dated 14.01.20

3. Type of case: -Renewal

4. Details of previous FSC: -No. F6/DFS/MS/GH/2018/NDZ/968 dated 09/05/18.

5. Fire safety directives No.-N/A

6. Date of inspection: -03/12/21

7. Name of the inspecting officer: -Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side: -

Mr. Manohar Ahamad 9. Year of construction: -2010

10. Applicant's letter No: -

2021052613562 dated 26/05/2021 & email brijk943@gmail.com dated 26.11.21

Old Case S.No. Minimum Standards on fire Requirement/ Provided at site Remarks Prevention and fire safety U/R 33 Existing fire safety MR/NMR arrangements 1. Access to Building 1) Road width N/A 02 mtr. MR 2) Gate width N/A N/A N/A 3)Width of internal road N/A N/A N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 1.25 mtr. 1.25 mtr. MR 2. Basements N/A N/A N/A C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous 01 01 MR staircase to terrace E. Width of corridor N/A N/A N/A F. Door size 01 mtr. 01 mtr. MR 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A 4. Smoke Management System 1) Basements 30 ACPH N/A N/A 2) Upper floors 12 ACPH Natural/exhaust MR fan 5. Fire Extinguishers 1) Total numbers 10 Nos. 10 Nos MR 2) Types ABC & CO2 ABC & CO2 MR 3) ISI marking Required Provided MR



M/24

		1(-)	1	
6.	First-Aid Hose Reel		D	MR
	1) Total number of eachfloor	01	Provided 30 mtr.	MR
	2) Length of hose reel hose	30 mtr. 05 mm	05 mm	MR .
	3) Nozzle diameter			IVIK
7.	Automatic Fire Detection &		Provided	MR
	1) Type of detectors CO type	Required Ground floor	Provided	MR
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel		Provided	MR
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Each floor		
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System		77/4	
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			157/
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			1271:
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	•		
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump		Provided	MR
4			TTOVIGEG	IVIK
14.	Captive Water Storage for		NT/A	NT/A
	1) Under ground tank	N/A	N/A	N/A
	capacity	NT/A	27/4	1
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	2500 ltr.	2500 ltr.	MR
	capacity			
5.	Exit Signage.	Required	Provided	MR



16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety required under the rules the FSC issued vide F6/DFS/MS/GH/2018/NDZ/968 dated 09/05/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor only.

Signature of the Inspecting Officer

Name: - Rayinder Singh Designation: - ADO (CC)

As apporred, pri i partur forker Perusa and Separahui Pleace.

DYLGICADU