

48

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**


No. F.6/DFS/MS/EH/2021/SZ/ 371

Dated: 14 / 12 /2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of **M/s ZIU (A Unit of Eurasian Speciality LLP)**, Shop No 8, 9 & 10, at Sangam Courtyard, Major Som Nath Marg, Sector 9, R.K Puram, New Delhi 110022 **located at ground floor** in the building comprised of 03 tier Basement, ground plus three upper floor owner occupied by (A Unit of Eurasian Speciality LLP), have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 06/12/2021 in the presence of Mr. Pardeep Kumar (Manager) and that the premises is fit for occupancy class **“Group-D Assembly” (For Ground Floor only)** with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 14 / 12 /2021 at New Delhi by


(ATUL GARG)
DIRECTOR / DFS

Copy to: -

1. The Dy. Health Officer, SDMC, Public Health Department, Green Park, Aurobindo Marg, New Delhi – 110016. (Ref. MHA Portal ID 2021111626531 dated 19/11/2021)
2. The Joint Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049.
3. M/s ZIU (A Unit of Eurasian Speciality LLP), Shop No 8, 9 & 10, at Sangam Courtyard, Major Som Nath Marg, Sector 9, R.K Puram, New Delhi 110022

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/occupier shall submit a declaration every year in Form ‘K’ provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. “The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form ‘J’ [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.”

INSPECTION REPORT

| | | | | |
|---------------|--|---|-------------------------------------|-----------------------|
| 1 | Name & Address of the Building | M/s ZIU (A Unit of Eurasian Speciality LLP), Shop No 8, 9 & 10, at Sangam Courtyard, Major Som Nath Marg, Sector 9, R.K Puram, New Delhi 110022 | | |
| 2 | Type of Occupancy | Group-D Assembly Building. (Eating house) | | |
| 3 | Building Comprised of | 3 tier basement, ground plus two upper floors | | |
| 4 | Type of Case | New Case | | |
| 5 | Details of Previous NOC | Nil | | |
| 6 | Fire Safety Directives Letter No | UBBL / NBC Part -IV | | |
| 7 | Date of Inspection | 06/12/2021 | | |
| 8 | Name of the Inspecting Officers | Sh. Rajesh Kumar ADO (BCP) | | |
| 9 | Name & Designation of Officers from the building side | Sh. Pardeep Kumar (Manager) | | |
| 10 | Year of construction | 2015 | Restt. located at ground floor only | |
| 11 | Applicant letter No. | MHA Portal ID 2021111626531 dated 19/11/2021 | | |
| S. No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | UBBL-2016 Requirements | Provided at Site | Remarks MR/NMR |
| 1 | Access to Building. | F6/DFS/MS/2020/Cinema/508 dated 07/12/2020 | | |
| | <ul style="list-style-type: none"> Road width Gate width Width of internal road | Restt. within Mall | As above | MR |
| | | | As above | N/A |
| | | | As above | N/A |
| 2 | Number, width, type & arrangement of exits. | Provided & Maintained by Mall | | |
| | a) Number of Staircase | Provided & Maintained by Mall | | |
| | ➤ Upper floors. | NA | Restt. at GF | NA |
| | ➤ Basement floor. | N/A | As above | N/A |
| | b) Width of Staircase | Provided & Maintained by Mall | | |
| | ➤ Upper floors | NA | Restt. at GF | NA |
| | ➤ Basement floor | N/A | As above | N/A |
| | c) Protection of exits | Provided & Maintained by Mall | | |
| | ➤ Fire check door | N/A | N/A | N/A |
| | ➤ Pressurization | N/A | N/A | N/A |
| | d) No. of continuous staircase to terrace | Required | One | MR |
| | e) Width of corridor | N/A | N/A | N/A |
| | f) Door size | 2 exits | 2.29m & 2.40 m | MR (old case) |
| 3 | Compartmentation. | Provided & Maintained by Mall | | |
| | • Fire check door. | N/A | N/A | N/A |
| | • Sealing of electrical shafts. | N/A | N/A | N/A |
| | • Fire rating of shaft door. | N/A | N/A | N/A |
| | • Water curtain | N/A | N/A | N/A |
| | • Fire dampers. | N/A | N/A | N/A |
| 4 | Smoke Management system. | Provided & Maintained by Mall | | |
| | • Basement | 30 ACPH | As above | MR |
| | • Upper floors | 12 ACPH | Exhaust Fans Provided | MR |
| 5 | Fire Extinguishers. | Provided & Maintained by Mall | | |
| | • Total numbers | Required | 10 Nos | MR |
| | • Types | ABC/CO ₂ | ABC-07 & CO ₂ -03 | MR |
| | • ISI Marking | ISI marked | Provided | MR |
| 6 | First Aid Hose Reels. | Provided & Maintained by Mall | | |
| | • Total numbers on each floor. | Two | Provided | MR |
| | • Length of hose-reel hose. | 30m | Provided | MR |
| | • Nozzle Diameter | 5mm | Provided | MR |
| 7 | Automatic fire detection & alarming system. | Provided & Maintained by Mall | | |
| | • Type of detectors | N/A | As above | N/A |
| | • Location of Main Panel | N/A | As above | N/A |
| | • Location of Repeater Panel | N/A | As above | N/A |
| | • Alternate source of power | N/A | As above | N/A |
| | • Hooter's location | N/A | As above | N/A |

| | | | | |
|----|---|-------------------------------|----------|-----|
| 8 | MOEFA | Required | Provided | MR |
| 9 | Public Address System | N/A | N/A | N/A |
| 10 | Automatic Sprinkler System | Provided & Maintained by Mall | | |
| | • Basement | N/A | N/A | N/A |
| | • Ground floor. | N/A | N/A | N/A |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11 | Internal Hydrants. | Provided & Maintained by Mall | | |
| | • Size of Riser/Down-comer | N/A | N/A | N/A |
| | • Number of Hydrant per floor | N/A | N/A | N/A |
| | • Hose box. | N/A | N/A | N/A |
| 12 | Yard Hydrants. | | | |
| | • Total number of hydrants. | N/A | N/A | N/A |
| | • Hose box. | N/A | N/A | N/A |
| 13 | Pumping arrangements. | Provided & Maintained by Mall | | |
| | • Ground Level | | | |
| | ➤ Discharge of main pump. | 2850 LPM | Provided | MR |
| | ➤ Head of main pump. | 70 m | Provided | MR |
| | ➤ Number of main pumps. | 02 | Provided | MR |
| | ➤ Jockey Pump output. | 180 LPM | Provided | MR |
| | ➤ Jockey Pump head. | 70 m | Provided | MR |
| | ➤ Standby Pump output. | 2850 LPM | Provided | MR |
| | ➤ Standby Pump head. | 70 m | Provided | MR |
| | ➤ Auto Starting/Manual Stopping. | Required | Provided | MR |
| | ➤ Pump house access. | Required | Provided | MR |
| | • Terrace Level | Provided & Maintained by Mall | | |
| | ➤ Discharge of pump. | N/A | As above | N/A |
| | ➤ Head of pump. | N/A | As above | N/A |
| | ➤ Power supply. | N/A | As above | N/A |
| | ➤ Auto starting of pump. | N/A | As above | N/A |
| 14 | Captive water storage for fire fighting. | Provided & Maintained by Mall | | |
| | • Underground tank capacity. | 2,00,000 ltrs | Provided | MR |
| | ➤ Draw-off connection. | Required | Provided | MR |
| | ➤ Fire Service Inlet. | Required | Provided | MR |
| | ➤ Access to tank. | Required | Provided | MR |
| | • Overhead tank capacity. | 20,000 ltrs | Provided | MR |
| 15 | Exit Signage. | Required | Provided | MR |
| 16 | Provision of Lifts. | Provided & Maintained by Mall | | |
| | • Pressurization of lift shaft. | Required | As above | MR |
| | • Pressurization of lift lobby. | Required | As above | MR |
| | • Communication in lift car. | Required | As above | MR |
| | • Fireman's switch. | Required | As above | MR |
| | • Lift signage. | Required | As above | MR |
| 17 | Standby Power Supply | Required | Provided | MR |
| 18 | Refuge Area | | | |
| | • Total area | N/A | N/A | N/A |
| | • Location | N/A | N/A | N/A |
| 19 | Fire Control Room. | Provided & Maintained by Mall | | |
| | • Detector system panel. | Required | As above | MR |
| | • Flow switch panel. | Required | As above | MR |
| | • PA system panel. | Required | As above | MR |
| | • Battery backup. | Required | As above | MR |
| | • Building floor plan. | Required | As above | MR |
| 20 | Special Fire Protection System for the Protection of special Risk, if any. | N/A | N/A | N/A |

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

AK
8/12/21

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Designation: ADO (BCP)

~~DO (SD)~~

Ling
09/12/21

~~DLFO (S2)~~

dh
10/12

~~CAF. O.~~

deop
09/12



~~an/ (my)~~
12/12/21

IPS

~~any sta~~

As approved, F.S. letter is put up for your signature pl.

AK
14/12

~~Director (my)~~
14/12/21

mu