## 95

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI–110001

No. F.6/DFS/MS/EH/2021/SZ/ 374

Dated: 20 / 12 /2021

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s IVORY (A Unit of UBON Poultry Farm Pvt Ltd) located at Ground Floor, T-540, Panchshila Park, Malviya Nagar, New Delhi- 110017 in the building comprised of ground floor only owned/occupied by (A Unit of UBON Poultry Farm Pvt Ltd) have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 24/11/2021 in the presence of Mr. Harish Negi and that the premises is fit for occupancy class "Group–D Assembly" (Restaurant) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 2 / 12 / 2021 at New Delhi by




Copy to: -

- 1. The Dy. Health Officer, SDMC, Public Health Department, Green Park, Aurobindo Marg, New Delhi 110016. (Ref. MHA Portal ID 2021111226211 dated 12/11/2021)
- 2. The Joint Commissioner of Police (Lic.), 1<sup>st</sup> Floor, P.S. Defence Colony, New Delhi-110049.
- 3. **M/s IVORY** (A Unit of UBON Poultry Farm Pvt Ltd) T-540, Panchshila Park, Malviya Nagar, New Delhi- 110017

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."





[					
	Location of Repeater Panel	N/A	N/A	N/A	
	<ul> <li>Alternate source of power</li> <li>Hooter's location</li> </ul>	N/A	N/A	N/A	
0		N/A	N/A	N/A	
8		Required	Provided	MR	
9	Public Address System	N/A	NA	N/A	
10	1 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 -				
	Basement	N/A	N/A	N/A	
	Ground floor.	N/A	NA	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants.				
	• Size of Riser/Down-comer	100 mm	Provided	MR	
	• Number of Hydrant per floor	One	Provided	MR	
	• Hose box.	One	Provided	MR	
12	Yard Hydrants.				
	• Total number of hydrants.	N/A	N/A	N/A	
	• Hose box	N/A	N/A	N/A N/A	
13	Pumping arrangements.		17/4	IN/A	
	Ground Level				
	<ul> <li>Discharge of main pump.</li> </ul>	N/A	N/A		
	<ul> <li>Head of main pump.</li> </ul>	N/A N/A		N/A	
	<ul> <li>Number of main pumps.</li> </ul>		N/A	N/A	
	Jockey Pump output.	N/A	N/A	N/A	
	Jockey Pump head.	N/A	N/A	N/A	
	Standby Pump output.	N/A	N/A	N/A	
	Standby Pump head.	N/A	N/A	N/A	
	Auto Starting/Manual Stopping.	N/A	N/A	Ν/Λ	
	Pump house access.	N/A	N/A	N/A	
	Terrace Level				
	Discharge of pump.	450 LPM	Provided	MR	
	Head of pump.	40 m	Provided	MR	
	Power supply.	Required	Provided	MR	
	Auto starting of pump.	Required	Provided	MR	
14	Captive water storage for fire fighting.	1		1	
	Underground tank capacity.	N/A	N/A	N/A	
	<ul> <li>Draw-off connection.</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Fire Service Inlet.</li> </ul>		N/A	N/A N/A	
	<ul> <li>Access to tank.</li> </ul>	N/A N/A	N/A N/A		
	• Overhead tank capacity.			N/A	
		20,000 Ltrs	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	• Pressurization of lift shaft.	N/A	N/A	N/A	
	• Pressurization of lift lobby.	N/A	N/A	N/A	
	• Communication in lift car.	N/A	N/A	N/A	
	• Fireman's switch.	N/A	N/A	N/A	
	• Lift signage.	N/A	N/A	N/A	
17	Standby Power Supply	N/A	N/A	N/A	
18	Refuge Area				
	Total area	N/A	N/A	N/A	
1	Location	N/A	N/A	N/A	
9			1		
9	Fire Control Room.	N/A	N/A	N/A	
9	Fire Control Room.         • Detector system panel.	N/A N/A	N/A N/A		
19	Fire Control Room.     Detector system panel.	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A	

0	1
N	12
	12

\ \	Building floor plan.	N/A	N/A	NI/A
20	Special Fire Protection System for the	N/A		N/A
	Protection of special Risk, if any.		N/A	N/A
				1 1/11

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

9/11/21

0

ð

Director

DO(SD)

DeFO

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Designation: ADO (BCP)

PG

the approved, F.T. fetter le ilup dor your synatuce Pl

FSC uploaded