C14

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ/

DELHI
PLACE

Dated: 29 12 202

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Girls Sr. Sec. School,** Paprawat, New Delhi-110043 comprised of three blocks namely Main block, 2nd block & 3rd block. Main block is having ground plus one upper floor, 2nd & 3rd block is having ground floor only owned/occupied by Govt. Girls Sr. Sec. School was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2017/SZ/1357 dated 12/09/2017. The school building was re- inspected by the officer concerned of this department on 21/12/2021 in the presence of Principal and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on $\frac{39}{12}$ $\frac{12}{202}$ at New Delhi.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

Copy to:-

1. The Principal, Govt. Girls Sr. Sec. School, Paprawat, New Delhi-110043

 Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

Comprised of three blocks namely Main block, 2nd block & 3rd block. Main block is having ground plus one upper floor and 2nd & 3rd block is having ground floor only.

INSPECTION REPORT

1. Name & address of the building: Govt. Girls Sr. Sec. School, Paprawat, New Delhi-110043

Type of Occupancy Educational 3. Type of Case4. Details of Previous NOC Renewal

F.6/DFS/MS/School/2017/SZ/1357 dated 12/09/2017

5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

6. Date of inspection 21/12/2021

7. Name of Inspecting Officer : A.D.O. R.K.Yadav

8. Name and designation of officers

From the building side Principal 9. Year of Construction : Before 2010

10.	Applicar	t's letter No. : Nil dated 20/	12/2021		
S. No.	Minim fire saf	um Standards on fire prevention and ety U/R 33	Requirement	Provided at site	Remarks
1.		to building		site	MR/NMR
	•	Road width	Accessible 06 m	07 m	MR
	•	Gate width	4.5 m	Directly accessible	M/R
	•	Width of internal road	N/A	from road N/A	N/A
2.	Numbe	er, Width, Type & Arrangement of Exits			
	a. Num	ber of staircases			
	•	Upper Floors	02 no.'s in M blk	03 no.'s in M blk	MR
	•	Basements	N/A	N/A	N/A
	b. Wid	th of staircases	IN/A	IN/A	IN/A
	•	Upper Floor	1.50.0.75	1 40 1 40 0	7.00
	•	Basements	1.50 & .75 m	1.40, 1.40 & 1.62 m	MR
			N/A	N/A	N/A
	c. Prot	ection of exits			
	•	Fire check door	N/A	N/A	N/A
	•	Pressurization	N/A	N/A	N/A
	J N-	- C 1			
		of continuous staircases to	Required	two	MR
	terr	ace Ith of Corridor	1.50 m	1.52 m	MR
			1.0 m	1.0 m (double door)	
	f. Do	or Size	1.0 III	in M blk & .90 m (double door) in 2 nd & 3 rd blk	MR, being old case
3.	Compa	rtmentation		C 5 BIK	
	•	Fire check door	N/A	N/A	N/A
	•	Sealing of electrical shafts	N/A	N/A	N/A
	•	Fire Rating of shaft door Water Curtain	N/A	N/A	N/A
	•	Fire Dampers	N/A	N/A	N/A
			N/A	N/A	N/A
4.	Smoke	Management System			-
	•	Basements	N/A	N/A	N/A
	•	Upper floors	Required	Natural Ventilation provided	MR
5.	Fire Ex	tinguishers		•	
	•	Total numbers	10 No's	Provided	MR
	•	Types	ABC/CO ₂ type	Provided	MR
	•	IS marking	ISI marked	ISI marked	MR

NA

	First-Aid Hose Reels						
6.	Total numbers on each floor	N/A	N/A	N/A			
	 Length of hose reel hose 	N/A	N/A	N/A			
	Nozzle diameter	N/A	N/A	N/A			
,	Automatic fire detection and alarming system		1772				
'	Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
		N/A	N/A	N/A			
8.	MOEFA	IN/A	14/71				
9.	Public Address System	N/A	Provided	N/A			
10.	Automatic Sprinkler System						
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	➤ Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump headStandby Pump out put	N/A	N/A	N/A			
	Standby Pump Head						
	> Auto Starting/Manual Stopping	N/A	N/A	N/A			
	, rate starting	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace level						
	Discharge of pump	N/A	N/A	N/A			
	> Head of the pump	N/A	N/A	N/A			
	> Power Supply	N/A	N/A	N/A			
	➤ Auto Starting of pump	N/A	N/A	N/A			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity			N/A			
15.	Exit Signage.	N/A N/A	N/A N/A	N/A N/A			
13.	EAR Signage.	IN/A	IN/A	IN/A			

1	Provision of Lifts.		((No Lift)		
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding SwitchLift Signage	N/A	N/A	N/A		
	- Em oignage	N/A	N/A	N/A		
17.	Standby power supply	N/A	N/A	N/A		
18.	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2017/SZ/1357 dated 12/09/2017 renewal in accordance with the Circular No. $F.16/Estate/CC/Fire\ Safety/2011/3298$ to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- R.K.Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

22/12/1021

-T Letter u

putcep

b for signature

28 12/2021

Govt. Girls Sr. Sec. School, Paprawat, New Delhi-110043