

C-9

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/EH/2022/SZ/ 01

Dated: 05/01/2022

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of **M/s ANARDANA Hospitality Pvt. Ltd**, Shop No G-6 & G-7, Sangam Courtyard, Sector 9, R.K Puram, New Delhi 110022 located at **ground floor** in the building comprised of 03 tier Basement, ground plus three upper floor owned/occupied by Mr. Ravi Malik, have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 29/12/2021 in the presence of Mr. Ravi Malik and that the premises is fit for occupancy class "**Group-D Assembly**" (**For Ground Floor only**) with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 05 / 01 /2022 at New Delhi by


(ATUL GARG)
DIRECTOR / DFS

Copy to: -

1. The Dy. Health Officer, SDMC, Public Health Department, Green Park, Aurobindo Marg, New Delhi – 110016. (Ref. MHA Portal ID 2021121128400 dated 13/12/2021)
2. The Joint Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-49.
3. M/s ANARDANA Hospitality Pvt. Ltd, Shop No G-6 & G-7, Sangam Courtyard, Sector 9, R.K Puram, New Delhi 110022.

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	M/s ANARDANA Hospitality Pvt. Ltd, Shop No G-6 & G-7, Sangam Courtyard, Sector 9, R.K Puram, New Delhi 110022		
2	Type of Occupancy	Group-D Assembly Building. (Eating house)		
3	Building Comprised of	3 tier basement, ground plus two upper floors		
4	Type of Case	New Case		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	UBBL / NBC Part -IV		
7	Date of Inspection	29/12/2021		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Sh. Ravi Malik		
10	Year of construction	2015	Restt. located at ground floor only	
11	Applicant letter No.	MHA Portal ID 2021121128400 dated 13/12/2021		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL-2016 Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.	F6/DFS/MS/2020/Cinema/508 dated 07/12/2020		
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	Restt. within Mall	As above As above As above	MR N/A N/A
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase	Provided & Maintained by Mall		
	> Upper floors.	NA	Restt. at GF	NA
	> Basement floor.	N/A	As above	N/A
	b) Width of Staircase	Provided & Maintained by Mall		
	> Upper floors	NA	Restt. at GF	NA
	> Basement floor	N/A	As above	N/A
	c) Protection of exits	Provided & Maintained by Mall		
	> Fire check door	N/A	N/A	N/A
	> Pressurization	N/A	N/A	N/A
	d) No. of continuous staircase to terrace	Required	One	MR
	e) Width of corridor	N/A	N/A	N/A
	f) Door size	2 exits (1.50 x 2)	1.50 m & 1.50 m	MR
3	Compartmentation.	Provided & Maintained by Mall		
	<ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
4	Smoke Management system.	Provided & Maintained by Mall		
	<ul style="list-style-type: none"> Basement Upper floors 	30 ACPH 12 ACPH	As above Exhaust Fans Provided	MR MR
5	Fire Extinguishers.			
	<ul style="list-style-type: none"> Total numbers Types ISI Marking 	Required ABC/CO ₂ ISI marked	10 Nos ABC-07 & CO ₂ -03 Provided	MR MR MR
6	First Aid Hose Reels.	Provided & Maintained by Mall		
	<ul style="list-style-type: none"> Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter 	Two 30m 5mm	Provided Provided Provided	MR MR MR
7	Automatic fire detection & alarming system.	Provided & Maintained by Mall		
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooter's location 	N/A N/A N/A N/A N/A	As above As above As above As above As above	N/A N/A N/A N/A N/A
8	MOEFA	Required	Provided	MR

9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System	Provided & Maintained by Mall		
	• Basement	N/A	N/A	N/A
	• Ground floor.	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.	Provided & Maintained by Mall		
	• Size of Riser/Down-comer	N/A	N/A	N/A
	• Number of Hydrant per floor	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
12	Yard Hydrants.			
	• Total number of hydrants.	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	• Ground Level	Provided & Maintained by Mall		
	➤ Discharge of main pump.	2850 LPM	Provided	MR
	➤ Head of main pump.	70 m	Provided	MR
	➤ Number of main pumps.	02	Provided	MR
	➤ Jockey Pump output.	180 LPM	Provided	MR
	➤ Jockey Pump head.	70 m	Provided	MR
	➤ Standby Pump output.	2850 LPM	Provided	MR
	➤ Standby Pump head.	70 m	Provided	MR
	➤ Auto Starting/Manual Stopping.	Required	Provided	MR
	➤ Pump house access.	Required	Provided	MR
	• Terrace Level	Provided & Maintained by Mall		
	➤ Discharge of pump.	N/A	As above	N/A
	➤ Head of pump.	N/A	As above	N/A
	➤ Power supply.	N/A	As above	N/A
	➤ Auto starting of pump.	N/A	As above	N/A
14	Captive water storage for fire fighting.	Provided & Maintained by Mall		
	• Underground tank capacity.	2,00,000 ltrs	Provided	MR
	➤ Draw-off connection.	Required	Provided	MR
	➤ Fire Service Inlet.	Required	Provided	MR
	➤ Access to tank.	Required	Provided	MR
	• Overhead tank capacity.	20,000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provided & Maintained by Mall		
	• Pressurization of lift shaft.	Required	As above	MR
	• Pressurization of lift lobby.	Required	As above	MR
	• Communication in lift car.	Required	As above	MR
	• Fireman's switch.	Required	As above	MR
	• Lift signage.	Required	As above	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room.	Provided & Maintained by Mall		
	• Detector system panel.	Required	As above	MR
	• Flow switch panel.	Required	As above	MR
	• PA system panel.	Required	As above	MR
	• Battery backup.	Required	As above	MR
	• Building floor plan.	Required	As above	MR
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

