GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No.F6/DFS/MS/2021/School/ W2 06

Dated: 04 / 0/ /2021

FIRE SAFETY CERTIFICATE

Certified that the DAV Nursery School located at Outram Line, Kingsway Camp, Delhi-110009 comprised of Ground and 03 upper floors owned/ occupied by DAV Nursery School was issued Fire Safety Certificated vide this office letter no. F-6/DFS/MS/2018/1198 dated 23.05.2018 The premise was re-inspected by the officer concerned of this department on 23.12.2021 in the presence of Smt. Preeti Sethi (Administrative Officer) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from of the sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on .04 01 2022 at New Delhi

(Sunil Chawdhary)

Dy. Chief Fire Officer

Copy to: -

OC 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi

2. The Manager, DAV Nursery School located at Outram Line, Kingsway Camp, Delhi-110009.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Service Rules 2010. http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms. The form is available
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' | sub rule (1) of rule 37 | along with a copy of this Certificate, six months prior to its

1415

INSPECTION REPORT

1. Name & address of the building

: DAV Nursery School, Outram Lines, Kingsway Camp, Delhi-110009.

2. Type of Occupancy

: Educational (Ground +03 upper Floors only)

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/2018/1198 Dated: 23.05.2018

5. Fire Safety directives letter No

: NBC Part 4/ Director of Education Circular

6. Date of inspection

: 23.12.2021

7. Name of the Inspecting Officers

. 23.12.2021

8. Name and designation of officers

: ADO (RN)

from the building side

:Mrs. Preeti Sethi (Administrative Officer)

9. Year of Construction

: 1990- 2010

10. Applicant's letter No.

: Online E-Mail dated 20.12.2021

	ea-876 m2 Covered Area: 2184 m2 Minimum Standards on fire prevention and fire safety U/R 33	NBC Part 4 / Circular dt: 01.03.2011	Provided at site	Remarks MR/NMR			
	Access to building						
	Road width	6m	6m	MR			
	• Gate width	4.5m	4.5m	MR .			
	Width of internal road	NA	NA	NA			
	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	02	02	MR			
	Basements	NA	NA	NA			
	b. Width of staircases						
	Upper Floors	1.50m	1.50m & 1.35m	MR(old case			
	Basements	NA	NA	NA			
	c. Protection of exits						
		NA	NA	NA			
	Fire check door	NA	NA	NA			
	Pressurization	01	01	MR			
	d. No. of continuous staircases to terrace						
	e. Wi <mark>d</mark> th of Corridor	1.50m	1.50m	MR			
	f. Door Size	1 m	1.10 m	MR			
	Compartmentation.						
	Fire check door	NA	NA	NA			
	• Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	• Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4	Smoke Management System.						
	Basements	12 a/c per hour	NA	NA			
	• Upper floors	12 a/c per hour	Natural Ventilated	MR			
5	Fire Extinguishers						
	Total numbers	10 nos	16 nos	MR			
	• Types	ABC/WCo2	ABC—16	MR			
	ISI marking	ISI Marked	Yes	MR			

	Total numbers on each floor	01	01	MR	
	Length of hose reel hose	30m	30m	MR	
	Nozzle diameter	5mm	5mm	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	Location of Repeater Panel	NΛ	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
	MOEFA	NA	NA	NA	
	Public Address System.	NA	NA	NA	
)	Automatic Sprinkler System.				
	Basement	NA	NA	NA	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	. NA	NA	
	Internal Hydrants				
		100m	100mm	MR	
	Size of riser/down-comerNumber of hydrants per floor	01	01 at each floor	MR	
	Hose Box	01	01	MR	
2	Yard Hydrants.	0.1			
2	ratu fiyurants.		NA	NA	
	Total number of hydrants	NA			
	Hose Box	NA	NA	NA	
3	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps			N/A	
	Jockey Pump out put	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A N/A	N/A N/A	
	> Standby Pump Head	N/A		N/A	
	> Auto Starting/ Manual stopping	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A	
	Terrace level		4501 02	MR	
	Discharge of pump	450lpm	450lpm x 02	MR	
	> Head of the pump	40m	40m Provided	MR	
	> Power Supply	Required		MR	
	Auto Starting of pump	Required	Provided	IVIIC	
4	Captive Water Storage for fire fighting.				
	,	NA	NA	NA	
	Underground tank capacity	NA '	NA	NA	
	> Draw-off connection	NA NA	NA	NA	
	> Fire service inlet		NA	NA	
	> Access to tank	NA ·		MR	
	Overhead Tank capacity	10,000ltrs	10,000ltrs		
	Exit Signage	Required	Provided	MR	
,	Exit Signage				

16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	 Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular / NBC Part 4, the FSC issued vide letter of even no. 1198 dated 23.05.20 8 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

Signature of the Inspecting

Name :- C.L. Meena Designation:- ADO/RN

As approved, F.T. letter is flet up for your singustur Please