C-90



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/NDZ/2021/ 542

Dated 2.2/12/2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Rest Point Guest House located at 7923, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 01 guest room), 1st floor to 3rd floor (03 guest rooms at each floor), 4th floor (02 guest rooms) and terrace floor (DG set. + Kitchen for staff + 01 staff room found sealed), total 12 guest rooms owned/occupied by M/s Rest Point Guest House was earlier granted FSC by this department vide letter no.F6/DFS/MS/GH/NDZ/2018/2595 dated 03/12/18. Now, the premises was re-inspected by the officer concerned of this department on 15/12/21 in the presence of Mr. Dinesh and found that the said guest house building having given an affidavit dated 13.11.2019 regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor – reception & 01 room, 1st floor to 3rd floor (03 guest rooms at each floor) total 10 rooms up to third floor only, with effect from 22/12/21......for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued .2.7.1.12.1.2.1.....at New Delhi by.

(**Dr. S.K.Tomar**) Dy.Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North Delhi Municipal Corporation, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2021100723623 dated 08.10.2021 & mail id no. <restpointhotel@gmail.com> dated 06.12.2021.
- 3. The Manger,

M/s Rest Point Guest House, 7923, Arakashan Road, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

INSPECTION REPORT 1. Name & address of the building

M/s Rest Point Guest House at 7923, Arakashan Road, Pahar Ganj, New Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 10 Guest rooms) Ground floor (Reception + 01 guest room), 1st floor to 3rd floor (03 guest rooms at each floor), 4th floor

(02 guest rooms) and terrace floor (DG set.

for staff + 01 staff room found sealed) not in use as per affidavit dated 13.11.2019 regarding not to use any floor above third floor.

3. Type of case:-Renewal

4. Details of previous FSC:-No.F6/DFS/MS/GH/NDZ/2018/2595 dated

03/12/18

5. Fire safety directives No.-N/A 6. Date of inspection:-

15/12/21 7. Name of the inspecting officer:-

8. Name & designation of officer

Sh. Ravinder Singh (ADO/CC)

From the building side:-

Mr Dinesh 9. Year of construction:-2001

10. Applicant's letter No:-Online id no.2021100723623 dated 08.10.2021 &

mail id no. <restpointhotel@gmail.com> dated 27.11.2021.

				Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building	3		
	1) Road width	N/A	05 feet	NA
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr			
	A. Number of staircases			
	1. Upper floors	02 Nos.	02 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	0.90 to 0.92 Mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	01	01	MR
	staircase to terrace	27/4	2711	
	E. Width of corridor	N/A	N/A	N/A
2	F. Door size	1.0 mtr.	1.0 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System	-1		
	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	12 a/c per	Exhaust fan	MR
		hour		

Nple

NI/A

NT/A

5.	Fire Extinguishers								
	1) Total numbers	10	Nos.	10 Nos.	M				
	2) Types	AE	3C & CO2	ABC & CO2	M				
	3) ISI marking	Re	quired	Provided	M	R			
6.	First-Aid Hose Reel								
	1) Total number of eachflo			01	N/				
	2) Length of hose reel hose			30 mtr.	N/				
	3) Nozzle diameter	N/	A	05 mm	N/	Α			
7.	Automatic Fire Detection & Alarming System								
	1) Type of detectors		quired	Provided	M				
	2) Location of main panel		floor	Gr. floor	M				
	3) Location of repeater par			N/A		Ά			
	4) Alternate source of pow		equired	Provided	M				
	5) Hooter's Location	Ea	ch floor	Provided	M	R			
8.	MOEFA	N/	'A	N/A	N	/A			
9.	Public Address System	N/		N/A	N	/A			
10.	Automatic Sprinkler Sys								
	1) Basement	N/	'A	N/A	N	/A			
	2) Upper floors	N/		N/A		/A			
	3) Sprinkler above false	N/		N/A	N	/A			
	ceiling	- "							
11.	Internal Hydrants								
	1) Size of riser/down-com	ner N	/A	N/A	N	/A			
	2) Number of hydrants pe		/A	N/A	N	/A			
	floor								
	3) Hose box	N.	/A	N/A	N	/A			
12.	Yard Hydrants	,			•				
	1) Total number of hydrar	nts N.	/A	N/A	N	/A			
	2) Hose box		/A	N/A	N	/A			
13.	Pumping Arrangemen	ıt							
	1) Ground level		N/A	N/A		N/A			
	a) Discharge of ma	ain	N/A	N/A		N/A			
	b) Head of main p	ıımn	N/A	N/A		N/A			
			N/A	N/A		N/A			
		Number of main pump Jockey pump out put		N/A		N/A			
		Jockey pump out put Jockey pump head		N/A					
		Stand by pump output		N/A N/A		N/A			
		tand by pump head		N/A N/A		N/A			
	h) Auto starting/M					N/A			
	stopping	iaiiuai	N/A	N/A		N/A			
	2) Terrace level								
				180 LPM		N/A			
		Head of pump		30 mtr.		N/A			
				Provided		N/A N/A			
			1 10/4	i i i i i i i i i i i i i i i i i i i		I IN/A			
	c) Power supply	fnumn	N/A						
14	c) Power supplyd) Auto starting or		N/A	Provided		N/A			
14.	c) Power supply d) Auto starting of Captive Water Storag 1) Under ground t	ge for F	N/A	Provided					
14.	c) Power supply d) Auto starting of Captive Water Storage	ge for Fi	N/A ire Fighting	Provided g		N/A			

Mhos c) Access to tank N/A d) Over head tank N/A N/A N/A 1000 ltr. capacity N/A 15. Exit Signage. 16. Required Provision of Lifts. Provided MR a) Pressurization of lift N/A N/A N/A shaft b) Pressurization of lift N/A N/A N/A lobby c) Communication in N/A N/A N/A lift car d) Fireman's switch N/A N/A N/A e) Lift signage N/A N/A 17. N/A Stand by Power Supply Required Provided MR 18. Refuge Area N/A N/A N/A Total area location N/A N/A N/A 19. Fire Control Room N/A N/A N/A a) Detector system N/A N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

Special Fire Protection System for Protection of special

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. No.F6/DFS/MS/GH/NDZ/2018/2595 dated 03/12/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

20.

panel b) Flow switch panel

Risk, if any:

c) PA system panel

e) Building floor plan

d) Battery backup

As approximates putip for ken pour dans Exposition Please

22/12 Saview