

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110 001

No. F.6/DFS/MS/Motel/2021/SZ/ 01

Dated: 03/01/2021

FIRE SAFETY CERTIFICATE

Certified that **The Radiance Motel** at Property No 284-2, 269, 270, 271 Village Satbari, Chattarpur Mandir Road, Chattarpur New Delhi-110074 comprised of **Basement, Ground plus First floor & open farm house** was issued FSC by this department vide letter F6/DFS/MS/Motel/SZ/2018/2731 dated 18/12/2018. The premise was re-inspected by the officer concerned of this department on 28/12/2021 in the presence of Mr. Sonu (Manager) & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy **Group D "Assembly Building" (Farm House)** with effect 03/01/2021 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules/2010.

Issued on.. 03/01/2021 at New Delhi by


(SUNIL CHAWDHARY)

DY. CHIEF FIRE OFFICER (SZ)

Copy to:-

1. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049. (Ref. MHA Portal ID 2021112427099 dated 24/11/2021)
2. The Executive Engineer (Bldg), SDMC, Jal Vihar, Lajpat Nagar, New Delhi 110024.
3. The Authorized Signatory, The Radiance Motel at Property No 284-2, 269, 270, 271 Village Satbari, Chattarpur Mandir Road, Chattarpur New Delhi-110074

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

2/28

INSPECTION REPORT

1. Name & address of the building : Radiance Motel at Property No 284-2, 269, 270, 271 Village Satbari, Chattarpur Mandir Road, Chattarpur New Delhi-74
2. Type of Occupancy : Group A "Residential"(Motel)Building
3. Type of Case : Renewal
4. Comprised of : Basement, Ground & One Upper Floor and open farm house
5. Details of Previous NOC : F6/DFS/MS/Motel/SZ/2018/2731 dated 18/12/2018
6. Fire Safety directives letter No : F6/MS/DFS/GH/BP/2003/608 dated 21/03/2003
7. Date of inspection : 28/12/2018
8. Name of Inspecting Officer : Sh. Rajesh Kumar, ADO (BCP)
9. Name and designation of officers
From the building side : Mr. Sonu (Manager)
10. Year of Construction : 2003
11. Applicant's letter No. : MHA Portal ID 2021112427099 dated 24/11/2021

S. No	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	9m 5m -NA-	Provided Provided -NA-	MR MR -NA-
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	Three Three	Provided Provided	MR MR
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	1.25m 1.25m	1.3m, 1.3m, & 1.44m 1.25m, 1.24m, & 6.8m	MR(old case) MR(old case)
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	Required in basement -NA-	Provided -NA-	MR -NA-
	d. No. of continuous staircases to terrace	Required	Provided	MR
	e. Width of Corridor	1.5m	1.25m	MR(old case)
	f. Door Size	1m	1m (final exit)	MR
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	Required in basement Required -NA- -NA- -NA-	Provided Provided -NA- -NA- -NA-	MR MR -NA- -NA- -NA-
4.	Smoke Management System			
	<ul style="list-style-type: none"> • Basements • Upper floors 	30 ACPH 12 ACPH	Ex. Fan provided Natural ventilation	MR MR
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	Required ABC/W.Co ₂ /Co ₂ ISI Marked	Total 35 No's 15/15/05No's Yes	MR MR MR
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter 	Two 30m 5mm	Provided Provided Provided	MR MR MR
7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> • Type of detectors 	Smoke & Heat	Provided	MR

N/24

The Radiance Motel at Property No 284-2, 269, 270, 271 Village Satbari, Chattarpur Mandir Road, Chattarpur New Delhi-74

	<ul style="list-style-type: none"> • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooters' Location 	Required	Ground Floor	MR
		-NA-	-NA-	-NA-
		Required	Provided	MR
		Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> • Basement • Upper Floors • Sprinkler above false ceiling 	Required	Provided	MR
		Required	Provided	MR
		-NA-	-NA-	-NA-
11.	Internal Hydrants			
	<ul style="list-style-type: none"> • Size of riser/down-comer • Number of hydrants per floor • Hose Box 	100mm	100mm Provided	MR
		Two	Provided	MR
		Two	Provided	MR
12.	Yard Hydrants			
	<ul style="list-style-type: none"> • Total number of hydrants • Hose Box 	-NA-	4 No's provided	-NA-
		-NA-	4 No's provided	-NA-
13.	Pumping Arrangements			
	<ul style="list-style-type: none"> • Ground Level <ul style="list-style-type: none"> ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/Manual Stopping ➤ Pump House Access 	2280 LPM	Provided	MR
		60m	Provided	MR
		One	Provided	MR
		180 LPM	Provided	MR
		60m	Provided	MR
		2280 LPM	Provided	MR
		60m	Provided	MR
		Required	Provided	NMR
		Required	Provided	MR
	<ul style="list-style-type: none"> • Terrace level <ul style="list-style-type: none"> ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> • Underground tank capacity <ul style="list-style-type: none"> ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	50,000 Lts	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		12,500 Lts	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-

M/30

The Radiance Motel at Property No 284-2, 269, 270, 271 Village Satbari, Chattarpur Mandir Road, Chattarpur New Delhi-74

	<ul style="list-style-type: none"> PA System Panel Battery backup Building Floor Plans 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
20.	Special Fire Protection System for Protection of special Risks, if any:	Required	Two ABC type extinguishers provided	MR

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/Motel/SZ/2018/2731 dated 18/12/2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

[Handwritten signature]
29/12

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Designation: ADO (BCP)

DO (SD)

[Handwritten signature]
29/12

[Handwritten signature]
F.T.

ADO (B/P)

As approved, F.T. letter is put up for your signature pl

[Handwritten signature]
31/12/22

[Handwritten signature]

M.S. Well