GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

F.6/DFS/MS/School/2022/SZ/ 35

Dated: [4 / 6]/ 2022

FIRE SAFETY CERTIFICATE

Certified that the Nursery School Building located at NS-10, Pocket- L, Sarita Vihar, New Delhi 110076 comprised of Basement, Ground + Three Upper Floors owner/occupied by Dream Land Society was issued FSC by this department vide letter No. F6/MS/DFS/School/2019/SZ/15 Dated 02-01-2019. The said premise was re-inspected by officer concerned of this department on 05/01/2022 in presence of Mr. T.R. Garg (Proprietor) and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and the building is fit for occupancy class "Educational Building Group - B" with effect from 19/01/2022 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued 14/01 / 2022 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- 1. Dream land Society, Nursery School, at NS-10, Pocket- L, Sarita Vihar, New Delhi 110076.
- 2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire fighting system.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	INSPECTION REPORT				
1	Name & Address of the Building	Nursery School, at NS-10, Pocket-L, Sarita			
_	Transce Transces of the Emilian g	Vihar, New Delhi-110076 (Dreamland Society)			
2	Type of Occupancy	Educational, Group-B (School)			
3	Building Comprised of	Basement, Grou	und + 03 upper floors.		
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/MS/DFS/Sc	hool/2019/SZ/15 Dated 0	2-01-2019	
6	Fire Safety Directives Letter No	UBBL-2016			
7	Date of Inspection	05/01/2022			
8	Name of the Inspecting Officers	Sh. Rajesh Kun	nar ADO (BCP)		
9	Name & Designation of Officers	. Mr. T. R. 2018	- 1. A.		
	from the building side	Mr. T.R.	Gara My		
10	Year of construction	2018	0 100/10/2021		
11	Applicant letter No.	Outdoor diary no 5110 dated 09/12/2021			
S. No.		Old NOC	Provided at Site	MR/NMR	
	and Fire Safety U/R 33	requirements		MINIMIN	
1.	Access to Building.	26	00	MR	
	Road width	06 mtr	09 mtr	-NA-	
	Gate width	-NA-	-NA-		
	Width of internal road	-NA-	-NA-	-NA-	
2.	Number, width, type & arrangement of ex	cits.			
	a) Number of Staircase				
	Upper floors.	02 Nos	02 Nos	MR	
	Basement floor.	02 Nos	02 Nos	MR	
	b) Width of Staircase				
	> Upper floors	1.50 mtr	1.50 mtr each	MR	
	Basement floor	1.50 mtr	1.50 mtr each	MR	
	c) Protection of exits	1.50 MG			
	Fire check door	-NA-	-NA-	-NA-	
	> Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	Required	Provided	MR	
	e) Width of corridor	1.50 mtr	Provided	MR	
	f) Door size	1.50 mtr	Provided	MR	
3.	Compartmentation.				
	Fire check door.	-NA-	-NA-	-NA-	
	 Sealing of electrical shafts. 	-NA-	-NA-	-NA-	
	 Fire rating of shaft door. 	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.				
	Basement	30 ACPH	Exhaust fan provided	MR	
	 Upper floors 	12 ACPH	Exhaust fan provided	MR	
5.	Fire Extinguishers.				
	Total numbers	Required	20 Nos	MR	
	• Types	ABC / CO2	ABC & CO2		
		ISI marked		MR	
	• ISI Marking	151 marked	Provided	MR	
6.	First Aid Hose Reels.	01.27			
	Total numbers on each floor.	01 Nos	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
7.	Automatic fire detection & alarming system.				
	Type of detectors	-NA-	-NA-	-NA-	
				~ 14 1	

	Location of Main Panal	•		
	Ecoation of Main Failer	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
8.	Hooter's location	-NA-	-NA-	-NA-
9.	MOEFA	Required	Provided	MR
	Public Address System	-NA-	NA	-NA-
10.	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.			
	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	 Number of Hydrant per floor 	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
12.	Yard Hydrants.			
	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			
	Discharge of pump.	900 LPM	Provided	MR
	➤ Head of pump.	40 m each	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting.			
	 Underground tank capacity. 	-NA-	-NA-	-NA-
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	 Overhead tank capacity. 	15,000 Ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
15	Lift signage. Standby Power Supply	NA NA	Provided	NA
17.	Standby Power Supply	14/1	1 TOTAGE	14/1
18.	Refuge Area	-NA-	-NA-	-NA-
	Total area			
	• Location	-NA-	-NA-	-NA-
	Fire Control Room.			
19.	rire Control Room.			
19.	Detector system panel.	-NA-	-NA-	-NA-

	PA system panel.	-NA-	-NA-	-NA-
	Battery backupBuilding floor plan.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
20.	Special Fire Protection System for the	m for the Protection of special Risk, if any.		-NA-

The fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rule FSC issued vide letter No. F6/MS/DFS/School/2019/SZ/15 Dated 02-01-2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Deforms

ADDÍTSCA

AS Approved, F.P. Letter in books for your

engrature of

As Approved of the for your

engrature of

All Charles

Al