

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ/ 3 8

Dated: 14/01/22

FIRE SAFETY CERTIFICATE

Certified that the **St. Sai Public School**, A-3, Prakash Sector, Vikas Nagar, Phase-II, Uttam Nagar, New Delhi-110059 comprised of ground floor only, having total 07 rooms (including class rooms & offices etc.) owned/occupied by Gram Vikas Shiksha Parishad (Regd.) was issued FSC by this department vide letter no. F6/DFS/MS/School/2019/151 dated 18/01/2019. The school building was re-inspected by the officer concerned of this department on 04/01/2022 in the presence of Sh. Mahesh Tyagi (Manager) and found that the School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

Copy to:-

0.

- The Principal,
 St. Sai Public School,
 A-3, Prakash Sector, Vikas Nagar,
 Phase-II, Uttam Nagar, New Delhi-110059
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

INSPECTION REPORT

St. Sai Public School, A-3, Prakash Sector, Vikas Nagar, Phase-II, 1. Name & address of the building :

Uttam Nagar, New Delhi-110059

Ground floor only. Building comprised of Educational 3. Type of Occupancy

Renewal 4. Type of Case

F6/DFS/MS/School/2019/151 dated 18/01/2019 5. Details of Previous NOC

Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Fire Safety directives letter No

04/01/2022 7. Date of inspection

A.D.O. R.K. Yadav 8. Name of Inspecting Officer

9. Name and designation of officers

: Sh. Mahesh Tyagi (Manager) From the building side

: 2006 10. Year of Construction

Nil dated 03/01/2022

Minimu	's letter No. : Nil dated 03/0 m Standards on fire prevention and	Requirement	Provided at	Remarks		
fire safe	ety U/R 33	as per FSC dt. 18/01/2019	site	MR/NMR		
Access	to building		D 11.1	MR		
				N/A		
•	Width of internal road	N/A		1772		
	Y LU T C A was goment of Frits			•		
Number, Width, Type & Arrangement of Extis						
		N/A	N/A	N/A		
•	• •			N/A		
•		N/A	14/14			
			27/4	N/A		
•		N/A				
•	Basements	N/A	N/A	N/A		
		21/4	N/A	N/A		
c. Prot	ection of exits			N/A		
•		N/A	N/A	IV/A		
•	Pressurization	21/4	N/A	N/A		
d No	of continuous staircases to			N/A		
1		N/A	N/A			
e. Wi	dth of Corridor	1. 0 M	1.0/.85/.90M	MR, being old case		
Comp	artmentation					
		N/A	N/A	N/A		
•	Fire check door	N/A	N/A	N/A		
	Fire Rating of shaft door		N/A	N/A		
	Water Curtain		N/A	N/A		
•		The second secon	N/A	N/A		
		.,,,,,				
Smok	6 Management System		27/4	N/A		
	Basements	N/A	N/A	IN/A		
		Deswind	Natural Ventilation	MR		
•	Upper floors	Required	provided			
Fire Extinguishers						
		04 No's	Provided	MR		
•		ABC/CO ₂ type	Provided	· MR		
•		ISI marked		MR		
	b. Wid c. Prot d. No terr e. Wi f. Cl: Comp	 Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors Basements b. Width of staircases Upper Floor Basements c. Protection of exits Fire check door Pressurization d. No. of continuous staircases to terrace e. Width of Corridor f. Class Room Door Size Compartmentation Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers Smoke Management System Basements Upper floors Fire Extinguishers	• Road width • Gate width • Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases • Upper Floors • Basements b. Width of staircases • Upper Floor • Basements	Road width Gate width Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases • Upper Floors Basements b. Width of staircases • Upper Floor Basements • Upper Floor • Basements • N/A • N/A • N/A • N/A • Pressurization d. No. of continuous staircases to terrace • Width of Corridor f. Class Room Door Size Compartmentation • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Sealing of shaft door • Water Curtain • Fire Dampers • Basements • Upper floors Provided N/A N/A N/A N/A N/A N/A N/A N/		

	First-Aid Hose Reels					
	Total numbers on each floor	N/A	N/A	N/A		
	Length of hose reel hose	N/A	N/A	N/A		
	Nozzle diameter	N/A	N/A	N/A		
	Automatic fire detection and alarming system					
•	 Type of detectors 	N/A	N/A	N/A		
	 Location of Main Panel 	N/A	N/A	N/A		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	 Hooters' Location 	N/A	N/A	N/A		
3.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	N/A	N/A	N/A		
•	1 done 1 day 355 2 J 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3					
10.	Automatic Sprinkler System	N/A	N/A	N/A		
	Basement	N/A N/A	N/A	N/A		
	Ground Floor Swinkler above false cailing	N/A	N/A	N/A		
	Sprinkler above false ceiling Literal Madronto	18/73	1 W A A			
11.	Internal Hydrants • Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level		27/4	NI/A		
	Discharge of main Pump	N/A	N/A	N/A		
	> Head of Main pump	N/A	N/A	N/A		
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A		
	Jockey Pump out putJockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	> Auto Starting/Manual Stopping	N/A	N/A	N/A		
		N/A	N/A	N/A		
	D House Access	N/A	N/A	N/A		
	Pump House AccessTerrace level			27/4		
	Terrace levelDischarge of pump	N/A	N/A	N/A		
	Head of the pump	N/A	N/A	N/A N/A		
	Power Supply	N/A	N/A	N/A N/A		
	> Auto Starting of pump	N/A	N/A	18/73		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	 Overhead Tank capacity 	N/A	N/A	N/A		

2

fi

20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Detector System Panel Flow Switch Panel	N/A	N/A	N/A
_	D	P		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2019/151 dated 18/01/2019 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Office

Name:- R.K. Yadav

Designation: - Asstt. Divisional Officer

Divisional Officer (South West)

24 Cro (52)

and exp

FT helter to

up for

signature pleas

13/1/2022

Dycro(\$2)

M, S, all