



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 34

Dated: 18.../2.1./2022

**FIRE SAFETY CERTIFICATE** 

Issued  $\frac{18}{01}$   $\frac{2022}{202}$  at New Delhi by.

(Dr. S.K.Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

## Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2021090520255 dated 05/09/2021 & mail id ak297372@gmail.com dated. 29.12.2022.
- The Manager, M/s Geetanjali Inn 3997,4000 & 4001, Gali School Wali, Bagichi Ram Chander, Mohalla Kaseruwalan, Pahar Ganj, New Delhi.

## Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand cancelled, if guest house owner/occupier fails to comply all conditions mentioned in the gazette notification dated 27.05.2019 & letter of extension of time period issued on dated 20.12.2021, latest by 31.03.2022.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

INSPÉCTION REPORT

1. Name & address of the building M/s Geetanjali Inn at 3997, 4000 & 4001, Gali School Wali, Bagichi Ram Chander, Mohalla

Kaseruwalan, Pahar Ganj, New Delhi.

Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 10 Guest rooms) Ground floor (01 guest rooms), 1st floor to 3<sup>rd</sup> floor (03 guest rooms at each floor).

3. Type of case:-Renewal

4. Details of previous FSC:-No. F6/DFS/MS/GH/2018/NDZ/1887 dated 10/08/18.

5. Fire safety directives No.-

6. Date of inspection:-

2. Type of occupancy:-

07/01/2022.

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

Sh. Ravinder Singh (ADO/CC)

9. Year of construction:-

Sh. Mustakh 2010

N/A

10. Applicant's letter No:-

ID No. 2021090520255 dated 05.09.21 ak297372@gmail.com dated. 29.12.2022.

Old Case S.No. Minimum Standards on fire Requirement/ Provided at site Remarks Prevention and fire safety U/R 33 Existing fire safety MR/NMR arrangements 1. Access to Building 1) Road width N/A 06 mtr. N/A 2) Gate width N/A N/A N/A 3) Width of internal road N/A N/A N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 0.80 mtr. 1.25 mtr. Old MR case 2. Basements N/A N/A N/A C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase to terrace 01 01 MR E. Width of corridor N/A N/A N/A F. Door size 01 mtr. 01 mtr. MR 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A 4. Smoke Management System 1) Basements 30 ACPH N/A N/A 2) Upper floors Required as Not provided Last dt. per G.N 31.03.22 of dated compliance 27.05.19 extended vide order dt. 20.12.2021

N 23

E				
5.	Fire Extinguishers	00 N-	10 Nos.	MR
	1) Total numbers	08 Nos. ABC & CO2	ABC & CO2	MR
	2) Types	Required	Provided	MR
	3) ISI marking	Required	Tiovided	
6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7	Automatic Fire Detection &		em	
7.	1) Type of detectors CO type	Required	Provided	MR
	2) Location of main panel	Gr. floor	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
		Required	Provided	MR
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Tiovided	
10.	Automatic Sprinkler System	NT/A	N/A	N/A
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	IV/A	
	ceiling			
11.	Internal Hydrants	NI/A	N/A	N/A
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	IV/A	
	floor	21/4	N/A	N/A
	3) Hose box	N/A	IN/A	1771
12.	Yard Hydrants	NT/A	N/A	N/A
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	IN/A	1771
13.	Pumping Arrangement	27/4	DI/A	N/A
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	IV/A
	pump	27/4	NT/A	NI/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
1	Captive Water Storage for Fi		1 - 1 - 1 - 1 - 1	1
4.	1) Under ground tank	N/A	N/A	N/A
	capacity	11/1	14/14	
	1	N/A	NI/A	N/A
	a) Draw-off connection	IN/A	N/A	11///

13/24

		10/00		
		1	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A 2500 ltr.	2500 ltr.	MR
	d) Over head tank	2300 iti.		
	capacity Frid Signage	Required	Provided	MR
15.	Exit Signage.	100		
16.	Provision of Lifts.	N/A	N/A	N/A
	a) Pressurization of lift	N/A		
	shaft b) Pressurization of lift	N/A	N/A	N/A
	lobby	1		N/A
	c) Communication in	N/A	N/A	N/A
	lift car		27/4	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A Provided	MR
17.	Stand by Power Supply	Required		N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	IN/A
	Total area location		27/4	N/A
19.	Fire Control Room	N/A	N/A	
17.	a) Detector system	N/A	N/A	N/A
	panel		27/4	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	14/11
		27/4	N/A	N/A
	e) Building floor plan	N/A		MR
20.	Special Fire Protection Sys	IVIK		
<b>4</b> 0.	Risk, if any: One ABC type			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. No. F6/DFS/MS/GH/2018/NDZ/1887 dated 10/08/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

Angled fragorous pri putut forcew fewerlands

Cyanture please.

Dyeroson John.