

C50

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No.F6/DFS/MS/Bnqt/2022/NDZ/04

Dated: 20/01/2022

FIRE SAFETY CERTIFICATE

Certified that M/s S.K. Mohit Party Hall located at Plot no.- B-17, Jhilmil Industrial Area, Delhi-110032 comprised of ground plus one upper floor owned/occupied by M/s S.K. Mohit Party Hall unit of SKM. Foods India was issued FSC vide letter No-F6/DFS/MS/2018/NDZ/2353 dated- 17/10/18. The premises was re-inspected by the officer concerned of this department in the presence of Mr. Mohit, and found that the Assembly building have deemed complied with the fire prevention and fire safety requirements in accordance with rules 33 of the Delhi Fire Service Rules, 2010 and observed that the banquet hall building is fit for ground plus one upper floor occupancy class "D" 'Assembly Building' with effect from 20/01/2022 for a period of **three** years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 20/01/2022 at New Delhi by


20/1/22

**(Dr. S.K Tomar)
Dy. Chief Fire Officer**



To,

1. Mr. Mohit
M/s S.K Mohit Party Hall,
Plot No. B-17 , Jhilmil Industrial Area,
Delhi-32.

Application ID No.-2021121628666

2. Deputy Health Officer,
Shahdara south zone, Karkardooma,
East Delhi Municipal Corporation Delhi-32

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building : M/s S.K. Mohit party Hall, at Plot No. B-17 Jhilmil Industrial Area, Delhi-110032 .
2. Building is comprised of : Ground plus One upper floor,
3. Type of Occupancy : Assembly
4. Type of Case : Renewal
5. Details of Previous FSC letter : F.6/DFS/MS/BNQT/2018/NDZ/2353 Dt. 17/10/1
6. Fire safety directive letter no. : F.6/DFS/MS/BP/2012/2728, Dated 26/07/12
7. Date of Inspection : 17/01/22
8. Name of the Inspecting officer : A.D.O Mehmood
9. Name and designation of Officer from the building side : Mr. Mohit,
10. Year of Construction : 2010
11. Applicant's letter No : MHA Id no. 2021121628666 dated 16/12/21

S N	Minimum Standards on fire prevention and fire safety U/R33	Circular Requirement	Provided at Site	Remark
1	Access to building			
	• Road width	12 M	18 M	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	• Upper Floor	02 nos	03 nos	MR
	• Basement	N/A	N/A	N/A
	b. Width of Staircases			
	• Upper Floor	1.5 M	1.5 M, 1.79M & 1.06M	MR
	• Basement	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	01 no.	01 no.	MR
	e. Width of Corridor	02 M	02 M	MR
	f. Door Size	02 M	(2.0 m x 2), (1.42m x 2), (1.10 m x 2) & 0.94 m	MR
3	Compartmentation.			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Sealed	MR
	• Fire rating of shaft door	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basement	N/A	N/A	N/A
	• Upper floor	N/A	Provided in kitchen	MR
5.	Fire Extinguishers			
	• Total numbers	06 Nos.	10 Nos.	MR
	• types	ABC & Co2	ABC & Co2	MR
	• IS marking	ISI marked	ISI marked	MR

6	First-aid-Hose Reels.			
	Total numbers of each floor	02 Nos	03 Nos	MR
	• Length of hose reel hose	30 M	30 M	MR
	• Nozzle diameter	05 mm	05 mm	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	N/A	N/A	N/A
	• Location of main panel	N/A	N/A	N/A
	• Location of repeater panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			
	• Basement	N/A	N/A	N/A
	• upper floor	N/A	Provided	MR
	• sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• size of riser/down-comer	100 mm	100 mm	MR
	• Number of hydrants per floor	02 Nos.	02 nos.	MR
	• Hose Box	02 Nos.	02 Nos.	MR
12	Yard Hydrants.			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.			
	• Ground Level	N/A	N/A	N/A
	• Discharge of main Pump	N/A	N/A	N/A
	• Head of Main Pump	N/A	N/A	N/A
	• Number of main pumps	N/A	N/A	N/A
	• Jockey pump out put	N/A	N/A	N/A
	• Jockey pump head	N/A	N/A	N/A
	• Standby pump out put	N/A	N/A	N/A
	• Standby pump Head	N/A	N/A	N/A
	• Auto Starting /Manual stopping	N/A	N/A	N/A
	• Pump House Access	N/A	N/A	N/A
	➤ Terrace Level			
	• Discharge of pump	900 LPM	900 LPM	MR
	• Head of the Pump	40 M	40 M	MR
	• Power supply	Required	Provided	MR
	• Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting.			
	• Underground tank capacity	N/A	N/A	N/A
	• Draw-off connection	N/A	N/A	N/A
	• Fire service inlet	Required	Provided	MR
	• Access to tank	N/A	Provided	MR
	• Overhead Tank capacity	15,000 ltrs	20,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR

16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication in lift car Firemen's grounding switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby power supply	Required	1500, Kvs	MR
18	Refuge Area.			
	<ul style="list-style-type: none"> Total area Location 	N/A	N/A	N/A
		N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> Detector system panel Flow switch panel PA system panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to renew Fire Safety Certificate under the rule 35 of Delhi Fire Service rules 2010.

Mehmood
18/11/2022

Signature of the Inspecting Officer

Name : Mehmood
Designation : A.D.O. (T.PUR)

Dy.CFO(NDZ)

A.D.O. (T.PUR)
19/11/22

ADDO(TP)
Sir, A.O.T. letter purdy for renew please

Dy CFO (NDZ)

A.D.O. (T.PUR)
20/11/22

Mehmood
20/11/2022
A.D.O. (T.PUR)

