

C/28

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No. F.6/DFS/MS/School/2022/NDZ/ 57

Dated: 21/01/2022

**FIRE SAFETY CERTIFICATE**

Certified that the Adarsh Vidya Niketan Public School at 25, Shiv Mandir Gali, Maujpur, Delhi-110053, comprised of ground plus one upper floor ( a room at second floor) owned/occupied by Adarsh Vidya Niketan Public School was issued FSC vide letter No. F.6/DFS/MS/School/2018/NDZ/2201 dated 28/09/2018. The Manager has given an undertaking dated 04/01/2022 not to use floor above first floor for any purpose. The school building have complied with the fire prevention and fire safety requirements in accordance with circular No. 262-362 dated 17/01/2005 and verified by the officer concerned of this department on 25/11/2021 in the presence of Sh. Pradeep Kumar Arora, Manager and that the building is fit for occupancy class "B" 'Educational Building' for ground plus one upper floor only with effect from 21/01/2022 for a period of **three** years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed overleaf.

Issued on..... 21/01/2022 .....at New Delhi by

**Note:- This Fire Safety Certificate does not cover second floor.**



(Dr. S. K. Tomar)  
Dy. Chief Fire Officer

O/C J.S.

To,

The Manager,  
Adarsh Vidya Niketan Public School,  
25, Shiv Mandir Gali, Maujpur,  
Delhi-110053

Copy for information and necessary action, if any:-

1. The Commissioner,  
EDMC, Headquarters,  
419, Udyog Sadan, Patparganj Industrial Area,  
New Delhi-110092
2. The Director of Education,  
EDMC, 419, Udyog Sadan,  
Patparganj Industrial Area, Delhi-110092

## CONDITIONS

10

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.
5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land or activities, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service. Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

## INSPECTION REPORT

1. Name & address of the building : Adarsh Vidya Niketan Public School, 25, Shiv Mandir Gali, Maujpur, Delhi-110053
2. Building is comprised of : Ground plus one upper floor (One room at second floor)
3. Type of Occupancy : Educational
4. Type of Case : Renewal
5. Details of Previous NOC letter : F.6/DFS/MS/School/2018/NDZ/2201 dt- 28/09/18
6. Fire Safety direction letter No : Circular No. 262-362 dated 17/01/05
7. Date of Inspection : 01/10/2021 & 25/11/2021
8. Name of the Inspecting officers : ADO Nagender Singh
9. Name and designation of Officer from the building side : Sh. Pradeep Kumar Arora, Manager
10. Year of Construction : 1991
11. Applicant's email ID : [pkarora3006@gmail.com](mailto:pkarora3006@gmail.com) dt-15/09/2021


Sr. No	Minimum Standards on fire prevention and fire safety U/R33	Old Circular Requirement	Provided at Site	Remarks MR/NMR
01	Access to building.			
	<ul style="list-style-type: none"> <li>• Road width</li> </ul>	06 m	05 m	MR(Accepted earlier)
	<ul style="list-style-type: none"> <li>• Gate width</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Width of internal road</li> </ul>	N/A	N/A	N/A
02	Number, Width, Type and Arrangement of Exits.			
	a. Number of Staircases			
	<ul style="list-style-type: none"> <li>• Upper Floor</li> </ul>	01 no.	02 nos.	MR
	<ul style="list-style-type: none"> <li>• Basement</li> </ul>	N/A	N/A.	N/A
	b. Width of Staircases			
	<ul style="list-style-type: none"> <li>• Upper Floor</li> </ul>	1.5 m	1.25 m & 0.95 m	MR(Accepted earlier)
	<ul style="list-style-type: none"> <li>• Basement</li> </ul>			
	c. Protection of exits			
	<ul style="list-style-type: none"> <li>• Fire check door</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Pressurization</li> </ul>	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	1 no.	1 no.	MR
	e. Width of Corridor			
	<ul style="list-style-type: none"> <li>• Door Size</li> </ul>	1.5 m	1.5 m	MR
		01 m	01 m	MR
03	Compartmentation.			
	<ul style="list-style-type: none"> <li>• Fire check door</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Fire rating of shaft door</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Water curtain</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Fire Dampers</li> </ul>	N/A	N/A	N/A
04	Smoke Management System.			
	<ul style="list-style-type: none"> <li>• Basement</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>• Upper floor</li> </ul>	N/A	N/A	N/A
05	Fire Extinguishers.			
	<ul style="list-style-type: none"> <li>• Total numbers</li> </ul>	04 nos.	06 nos.	MR
	<ul style="list-style-type: none"> <li>• types</li> </ul>	ABC /CO <sub>2</sub>	ABC /CO <sub>2</sub>	MR
	<ul style="list-style-type: none"> <li>• IS marking</li> </ul>	ISI marked	ISI marked	MR

06	First-aid-Hose Reels.			
	<ul style="list-style-type: none"> <li>Total numbers on each floor</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>	1 no. 30 m 05 mm	1 no. 30 m 5 mm	MR MR MR
07	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> <li>Type of detectors</li> <li>Location of main panel</li> <li>Location of repeater panel</li> <li>Alternate source of power</li> <li>Hooter's location</li> </ul>	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
08	MOEFA	N/A	N/A	N/A
09	Public address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> <li>Basement</li> <li>Upper floor</li> <li>Sprinkler above false ceiling</li> </ul>	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A
11	Internal Hydrants			
	<ul style="list-style-type: none"> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A
12	Yard Hydrants.			
	<ul style="list-style-type: none"> <li>Total number of hydrants</li> <li>Hose Box</li> </ul>	N/A N/A	N/A N/A	N/A N/A
13	Pumping Arrangements.			
	➤ Ground Level	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>Discharge of main Pump</li> <li>Head of Main Pump</li> <li>Number of main pumps</li> <li>Jockey pump out put</li> <li>Jockey pump head</li> <li>Standby pump out put</li> <li>Standby pump Head</li> <li>Auto Starting /Manual stopping</li> <li>Pump House Access</li> </ul>	N/A N/A N/A N/A N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A N/A N/A N/A
	➤ Terrace Level			
	<ul style="list-style-type: none"> <li>Discharge of pump</li> <li>Head of the Pump</li> <li>Power supply</li> <li>Auto Starting of pump</li> </ul>	220 LPM 40 m Required Required	220 LPM 40 m Provided Provided	MR MR MR MR
14	Captive Water Storage for Fire Fighting.			
	<ul style="list-style-type: none"> <li>Underground tank capacity</li> <li>Draw-off connection</li> <li>Fire service inlet</li> <li>Access to tank</li> <li>Overhead Tank capacity</li> </ul>	N/A N/A N/A N/A 2,500 Ltrs.	N/A N/A N/A N/A 2,500 Ltrs.	N/A N/A N/A N/A MR
15	Exit Signage.	N/A	N/A	N/A
16	Provision of Lifts.			
	<ul style="list-style-type: none"> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication in lift car</li> <li>Firemen's grounding switch</li> <li>Lift Signage</li> </ul>	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A

17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A


May kindly peruse affidavit received from Manager of the school regarding only ground & first floor are being used for academic purposes.

Keeping in view of the compliance of the minimum standards on fire prevention and fire safety measures required as per circular No. 262-362 dated 17/01/05 issued by Director of Education, it is recommended to renewal Fire Safety Certificate under rule 37 of Delhi Fire Service Rules, 2010.

  
(Nagender Singh)  
ADO (Shahdara)

Dy. CFO (NDZ)

Pl. speak.

  
6/12/21




ADO (Shahdara) As directed,

The said hall is sealed by school authorities ~~As directed~~ by a plywood sheet. Necessary correction has been made in DFA Also submitted please

Note: Photo enclosed.

Dy. CFO (NDZ)

  
14/11/22


  
13/1/22

ADO (Shahdara)

FT letter is resubmitted after due corrections

Dy. CFO (NDZ)

  
21/11/22

  
20/1/22

