(-43

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ

62

Dated: 24/1/22

FIRE SAFETY CERTIFICATE

Certified that the **Guru Nanak Public School**, G-8 Opp. Sports Complex, Near Swarag Ashram, Rajouri Garden, New Delhi-110064 comprised of ground plus two upper floors was issued FSC by this department vide letter no. F6/DFS/MS/School/2016/SZ/1437 dated 26.09.2016, having total 77 rooms (Including Class Rooms, Offices, Sci. Lab, Comp. Lab, Art Room, Medical Room, Judo Room, Music Room & Resource Room etc.) owned/occupied by Guru Nanak Public School was re-inspected by the officer concerned of this department on 13/01/2022 in the presence of Sh. Trilochan Singh (Chairman) and found that School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/ premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on at New Delhi.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

Copy to:-

 The Chairman, Guru Nanak Public School, G-8 Opp. Sports Complex, Near Swarg Ashram, Rajouri Garden, New Delhi-110064.

 Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	1. Name & address of the building	Ashram, 1	ak Public School, C Rajouri Garden, Ne	i-8 Opp. Sports Compl www.Delhi-110064	ex, Near Swarg			
	3. Type of Occupancy : Educational : Ground plus two upper floors 4. Type of Case : Renewal : Renewal : Ed/DES/MS/Called VON (677/1477 html) of Called : Called : Ed/DES/MS/Called VON (677/1477 html) of Called : Calle							
	6. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.201 7. Date of inspection							
	8. Name of Inspecting Officer	· ADOPL						
	9. Name and designation of officer	'S						
	from the building side		chan Singh (Chairn	nan)				
	10. Year of Construction 1998 (G+II)							
-	11. Applicant's letter No. Nil dated 12/01/2022							
S.	Standards on the prevent	ion and fire	Dir. Of Edu.	Provided at site	Remarks			
No	o. safety U/R 33		Circular dt. 01.03.2011/NBC		MR/NMR			
1.	Access to building		Requirement					
	Road width		Accessible	12 mtrs	MR			
	 Gate width 		4.5 mtrs	4.56 & 4.5 mtrs	MR			
	 Width of internal road 		N/A	N/A	N/A			
2.	Number, Width, Type & Arrangeme	nt of Exits	1	1				
	a. Number of staircases							
	 Upper Floors 		04 No's	04 No's	MR			
	 Basements 		N/A	N/A	N/A			
			1471	17/74	IV/A			
	b. Width of staircases		1.5 m &.75 m	1.35, 1.35, 1.45 & 1.45 m	MR			
	Upper Floor Parameter Para							
	Basements		N/A	N/A	N/A			
	c. Protection of exits		N/A	N/A	N/A			
	Fire check door	-						
	Pressurization		N/A	N/A	N/A			
	d. No. of continuous staircases to terrace		· · ·					
	e. Width of Corridor		Required	Two	MR			
	c. Width of Corridor		1.50 M	2.35 M	MR			
	f. Class room Door Size		1.0 M	.94 to 1.0 m	MR being old case			
	Compartmentation							
	Fire check door		N/A	N/A	N/A			
	 Sealing of electrical shafts Fire Rating of shaft door 	,	N/A	N/A	N/A			
	Water Curtain		N/A	N/A	N/A			
	Fire Dampers		N/A	N/A	N/A			
	·		N/A	N/A	N/A			
	Smoke Management System		NI/A	N1/4				
	Basements		N/A	N/A	N/A			
	Upper floors		Required	Natural ventilation provided	MR			
\Box	Fire Extinguishers							
	 Total numbers 		25 no.'s	Provided	MR			
	• Types		ABC/CO ₂ type	Provided	MR			
	IS marking		ISI marked	ISI marked	MR			

NIO

T	Sima All III D	with the party stranger and the stranger		
-	First-Aid Hose Reels	02 no.'s/floor	Provided	MR
	 Total numbers on each floor 	30 mtrs	Provided	MR
	 Length of hose reel hose 	30 11113	Provided	MR
	Nozzle diameter	5 mm	Tiovided	
	Automatic fire detection and alarming system		27/4	N1/A
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	 Hooters' Location 	N/A	N/A	N/A
	MOEFA	N/A	N/A	N/A
	Public Address System	N/A	N/A	N/A
	-			
0.	Automatic Sprinkler System	N/A	N/A	N/A
	Basement Grand Floor	N/A	N/A	N/A
	Ground Floor Social law shows falso sailing	N/A	N/A	N/A
_	Sprinkler above false ceiling	11/71	11/18	
1.	Internal Hydrants	N/A	N/A	N/A
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box			
12.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	1471		
13.	Pumping Arrangements			
	 Ground Level Discharge of main Pump 	N/A	N/A	N/A
	Discharge of main PumpHead of Main pump	N/A	N/A	N/A
	> Number of main pumps			N/A
	Jockey Pump out put	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level in OB	4501 73.5	D	7.00
	Discharge of pump	450LPM	Provided	MR
	> Head of the pump	30 mtrs	Provided	MR
	Power SupplyAuto Starting of pump	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14	. Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
		required	***************************************	

6.	Provision of Lifts.			No Lift		
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	 Pressurization of Lift lobby 	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch Lift Signage	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17.	Standby power supply	N/A	N/A	N/A		
18.	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	► Location	N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection.

In view of the compliance/deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2016/SZ/1437 dated 26.09.2016 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:- As per request submitted by chairman of the school new block (G+1 Floor) is not in use so FSC is not required for that block.

Signature of Inspecting Of

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer