

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No.F6/DFS/MS/School/2021/ 67

Dated: 24 / 1 /2021

FIRE SAFETY CERTIFICATE

Certified that the M.C Pratibha Co-ed School located at Meetha Kuan, Sabzi Mandi, Delhi-110007 comprised of Single Block, Ground and 01 upper floor only owned/occupied by M.C School was granted FSC by this department vide letter no. Pratibha Co-ed No.F6/DFS/MS/2018/SCHOOL/WZ/2356 dated 17.10.2018. The premises was re-inspected by the officer concerned of this department on 23.12.2021 in presence of Smt. Meena Kumari (Incharge) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class Group B Educational with effect from $\frac{1}{2}$ a period of three years, subject to compliance of the conditions mentioned below:

Issued on .2....... at New Delhi by

m[1] ron (Dharampal Bhardwaj) Dy. Chief Fire Officer Ph.-011-25156707 OCD

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Principal, M.C Pratibha Co-ed School located at Meetha Kuan, Sabzi Mandi, Delhi-110007.

Conditions for the validity of Fire Safety Certificate:

- All the means of escape/entry/exit shall be kept free from any obstruction. 1 2
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management. 3
- All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first Delhi Fire Service Rules 2010. The form is http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms. available on
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-5 2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

10/12

INSPECTION REPORT

		1.101.00
1.	Name & address of the building	: M.C. Pratibha (Co-ed) School, Meetha Kuan, Sabzi Mandi, Delhi-110007.
2.	Type of Occupancy	Educational
3.	Type of Case	: Renewal Single Block (G+1 upper Floors)
	Details of previous NOC	: F6/DFS/MS/2018/School/WZ/2356 dated: 17.10.2018
	Fire Safety directives letter No	: Director of Education Circular dated 01.03.2011
	Date of inspection	: 23.12.2021
7.	Name of the Inspecting Officers	: ADO (RN)
8.	Name and designation of officers	
	from the building side	: Smt. Meena Kumari (Incharge)
9. Ye	ear of Construction	: 2004
10. A	pplicant's letter No.	: Latter No. Nil Dated-06.12.2021

Plot Area-3200 sq. m2 Covered Area:1008 sq.m No. of Class Room-06

No. of Student-151

	Minimum Standards on fire prevention and fire safety U/R 33	Circular of Director of Education	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	6m	бm	MR		
	• Gate width	4.5m	4.5m	MR		
	Width of internal road	NA	NA	NA		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	02	02	MR		
	Basements					
	b. Width of staircases	1.5 m	2m & 1.5m			
	Upper Floors		2m & 1.5m	MR		
	Basements	NA	NA	NA		
	 c. Protection of exits Fire check door 	NA	NA			
	Pressurization		INA	NA		
	d. No. of continuous staircases to terrace	NA	NA	NA		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	NA	NA			
		1 m		NA		
3	Compartmentation.	1 111	lm	MR		
	Fire check door	NA	NA			
	 Sealing of electrical shafts 	NA	NA	NA		
	 Fire Rating of shaft door 	NA		NA		
	Water Curtain		NA	NA		
	Fire Dampers	NA	NA	NA		
		NA	NA	NA		
4	Smoke Management System.					
	• Basements	12 a/c per hour				
	• Upper floors		NA	NA		
	Fire Extinguishers	12 a/c per hour	Natural Ventilated	MR		
	Baronel 3					
) go				

1116

		1			
	Total numbers	05nos ABC/Co2	06nos ABC—06	MR MR	
	• Types				
	1S1 marking	ISI Marked	Yes	MR	
,	First-Aid Hose Reels.				
	Total numbers on each floor	NΛ	ΝΛ	NA	
	 Length of hose reel hose 	NΛ	NA	NA	
	Nozzle diameter	ΝΑ	ΝΛ	NA	
	Automatic fire detection and alarming system.				
	Type of detectors	NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
		NA	NA	NA	
	MOEFA			NA	
)	Public Address System.	NA	NA	INA	
10	Automatic Sprinkler System.				
		NA	NA	NA	
	• Basement	NA	NA	NA	
	Upper Floor		NA	NA	
	• Sprinkler above false ceiling	NA	1975		
1	Internal Hydrants				
	• Size of riser/down-comer	NA	NA	NA NA	
	Number of hydrants per floor	NA	NA	NA NA	
	• Hose Box	NA	NA	INA	
2	Yard Hydrants.				
	• Total number of hydrants	NA	NA	NA	
	• Hose Box	NA	NA	NA	
3	Pumping Arrangements.				
	Ground Level				
	> Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out putStandby Pump Head	N/A	N/A	N/A	
	 Standby Pump Head Auto Starting/ Manual stopping 		N/A	N/A	
	 Auto Starting/ Manual stopping Pump House Access 	N/A			
	• Terrace level	N/A	N/A	N/A	
	 Discharge of pump 				
	> Head of the pump	NA	N/A	NA	
	Power Supply	NA	N/A	NA	
	Auto Starting of pump	N/A	N/A	N/A	
		N/A	N/A ·	N/A	
	1	I State of the		1	

-1 cer ena RN

king

iirec ewa

-

N

14	Captive Water Storage for fire fighting.					
	Underground tank capacity	NΛ	ΝΛ	NA		
	> Draw-off connection	NA	NA	NA		
	 Fire service inlet 	NΛ	NA	NA		
	Access to tank	NA	NA	NA		
	Overhead Tank capacity	NA	N/A	NA		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A				
17	Standby power supply		N/A			
		N/A	N/A	N/A		
18	Refuge Area.					
	Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
9	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
0	Special Fire Protection Systems for	N/A	N/A.	N/A N/A		

M117

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular, the FSC issued vide letter of even no.2356 dated 17.10.2018 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

24/12/ 12/2021 Signature of the Inspecting Officer Name :- C.L. Meena Designation:- ADO/RN W2) 1 200 M 102 1 As approved, F.T. letter is Purup for your singnature Ple Cont ----