c-44



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2022/ 53

Dated: 25/1/22

FIRE SAFETY CERTIFICATE

Certified that M/s. Guest House T.J.S. Royale located at 16/16, WEA, Karol Bagh, New Delhi- 110005 was granted FSC for building comprised of basement, ground plus three upper floors, using basement as storage, ground floor as reception, office & pantry, first, second & third floor each having 07 guest rooms respectively (total 21 guest rooms) and a store in temporary shed on terrace, by this department vide letter No. F6/DFS/MS/GH/SZ/2018/1692 dated 19.07.2018. The premises was re-inspected by the officer concerned of this department on 05.01.2022 in presence of Mrs. Meenu, Leaser of the guest house and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class Residential (Guest House) for basement (incidental storage), first, second and third floor each having 07 guest rooms respectively (total 21 guest rooms only) with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 25/1/22 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

LA TO THE MORNING, MAIL LA ENEW GRANNERS, THE AREA ROOM, The Pengle 1986.

1 St. To The Morning, MAIL LA ENEW GRANNERS, THE AREA ROOM, The Pengle 1986.

1 St. To Mark 2. (Ch.), Mail of the 1, To have distory, In Concession, In Concession.

Following Fire Safety Directives must be adhered to: -

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/3618-37 dated 20.12.2021 in respect of existing building (copy enclosed) shall be implemented by 31.03.2022 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.

 us	tinuo	Con	
 us	tinuo	Con	

· Louging Hanes

9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.



N-22

INSPECTION REPORT

1. Name & address of the building

: M/s. Guest House T.J.S. Royale 16/16, WEA, Karol

Bagh, New Delhi- 110005.

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/GH/SZ/2018/1692 dated 19.07.2018

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 05.01.2022

7. Name of the Inspecting Officers

: P.V. Rathee, Asst. Divisional Officer (SRD)

8. Name and designation of officers

from the building side

: Mrs. Meenu, Leaser

9. Year of Construction

: Before 2007

10. Applicant's letter No.

: Online Application no. 2021122429291 dated 28.12.2021

The said guest house is comprised of basement, ground plus three upper floors.

S. No.	-	Minimum Standards on fire revention and fire safety U/R 33	Fire safety requireme as per FSC dt. 19.07.2018	Provided at site	t Remarks MR/NMR		
1	Ac	Access to building					
		Road width	06 mts	Provided	MR		
		Gate width	4.5 mts	Directly accessible	e MR being old case		
		 Width of internal road 	N/A	N/A	N/A		
2	Nu	mber, Width, Type & Arrangeme	ent of Exits				
	a. 1	lumber of staircases	-	-	-		
		Upper Floors	Old Case	01	MR being old case		
		Basements	Old Case	01	MR being old case		
	b. V	Width of staircases	-	-	-		
		Upper Floors	Old case	1.30 mts	MR being old case		
		Basements	Old case	1.20 mts to 1.30 mts			
	c. F	rotection of exits	-	-	-		
		Fire check door	Required		late of compliance has been extended up to 31.03.2022		
		 Pressurization 	N/A	N/A	N/A		
	e. N	o. of continuous staircases to terrace	01	01	MR		
	g. V	Vidth of Corridor	Old case	1.17 mts	MR		
	h. I	oor Size	Old case	0.88 mts	MR being old case		
	Coı	npartmentation.					
		Fire check door	Required		date of compliance has been extended up to 31.03.2022		
		 Sealing of electrical shafts 	N/A	Sealed			
		 Fire Rating of shaft door 	N/A	N/A	N/A		
		• Water Curtain	N/A	N/A	N/A		
		Fire Dampers	N/A	N/A	N/A		
	Sm	Smoke Management System.					
		Basements	30 a/c per hour	Exhaust fan provide			
		Upper floors	12 a/c per hour	Exhaust fan provide	ed MR		
	Fire	Extinguishers					
		Total numbers	. 15	Provided	MR		
		Types	CO ₂ , ABC, WCO ₂ ISI marked	Provided	MR		
		IS marking	131 marked	Provided	MR		

		N-2.	3		
6	First-Aid Hose Reels.				
	 Total numbers on each floor 	01	Provided	MR	
	• Length of hose reel hose	30 m	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors	Carbon Monox	ide Provided	MR	
	 Location of Main Panel 	Required	Provided near reception	on MR	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	 Alternate source of power 	Required	D.G. set 125 KVA	MR	
	Hooters' Location	N/A	N/A	N/A	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.				
	Basement University Classics	Required	Provided	MR	
	 Upper Floor Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants	N/A	N/A	N/A	
	Size of riser/down-comer	N/A	27/4	27/4	
	Number of hydrants per floor	N/A	N/A N/A	N/A N/A	
	Hose Box	N/A	N/A	N/A	
12	Yard Hydrants.	14/11	IVA	IN/A	
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	A N/A	N/A	
	Head of Main pump	N/A		N/A	
	Number of main pumps	N/A		N/A	
	Jockey Pump out put	N/A		N/A	
	Jockey pump head	N/A		N/A	
	Standby Pump out put	N/A			
	> Standby Pump Head	N/A		N/A	
	Auto Starting/ Manual stopp			N/A	
	Pump House Access			N/A	
	-	N/A	N/A	N/A	
	Terrace levelDischarge of pump	450 I	DM D :1.1		
	Head of the pump	450 L		MR	
		40 m		MR	
	- supply	Requi		MR	
	Trute Starting of pump	Requi	red Provided	MR	
14	Captive Water Storage for fire fighti	ng.			
	Underground tank capacity	N/A	N/A	N/A	
	Draw-off connection	N/A	N/A	N/A	
	Fire service inlet	N/A	Provided		
	Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	Old case	7000 lts	MR, Old case	
15	Exit Signage.	Required	Provided	MR	

A

				-21	
16	Provision of Lifts.				
	•	Pressurization of Lift Shaft	N/A	N/A	N/A
	•	Pressurization of Lift lobby	N/A	N/A	N/A
	•	Communication In lift Car	Required	Provided	MR
	•	Fireman's Grounding Switch	Required	Provided	MR
	•	Lift Signage	Required	Provided	MR
17	Sta	ndby power supply	Required	Provided	MR
18	Ref	uge Area.			
		> Total Area	N/A	N/A	N/A
		Location	N/A	N/A	N/A
19	Fire	Control Room			
		Detector System Panel	N/A	N/A	N/A
		 Flow Switch Panel 	N/A	N/A	N/A
		PA System Panel	N/A	N/A	N/A
		Battery backup	Required	Provided	MR
		Building Floor Plans	N/A	N/A	N/A
20		cial Fire Protection Systems for ection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/3618-37 dated 20.12.2021 in respect of existing building (copy enclosed) shall be implemented by 31.03.2022 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void. Undertaking given by owner/occupier placed at C-42.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2018/1692 dated 19.07.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer

P.V. Rathee Asstt. Div. Officer (SRD)