GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/Hospital/NDZ/2022/ 🔿 🔼

Dated:- 2/ /01/2022

Delhi Fire Service

FIRE SAFETY CERTIFICATE

Certified that the **College of Nursing (Florence Nightingale)** located at **GTB Hospital**, **Shahdara, Delhi** comprised of **Ground + 03 Upper floors** owned/occupied by GTB Hospital, The premises was inspected by the officers concerned of this department on 04/01/2022 in the presence of Mr. Parshant Panwar (Fire & Safety Officer) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Innstituional **Building, Gr. + 03 upper floors** with effect from $210 \circ 120 \circ 220$ for period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 21/01/2022 at New Delhi by.

Copy to:-

- 1. The Medical Superintendent, GTB Hospital, Shahdara, Delhi- 110095.
- The Executive Engineer (E), HMED (East), PWD, GTB Hospital Complex, Shahdara, Delhi – 110095.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

	Γ^{4}) inspect	CTION REPOR	т –		
1. N	Name & address of the building	College of Nu	ursing (Florence N bital, Shahdara, De		
2.0	it there is a comprised of	: Ground \pm 03		itti	
	uilding is comprised of				
	Type of occupancy	: Institutional Building : New Case			
	Type of case:-	N/Λ			
	Details of previous FSC	: N/A : N/A : 07/01/2022 : Sh. Manoj Kumar Sharma (ADO/LN) &			
	Fire safety directives No.				
/ . 0	Date of inspection:-				
8.	Name of the inspecting officer		od(ADO/TP)		
0	Name & designation of officer		(
9.	From the building side	: Sh. Parshant Panwar (Fire & Safety Officer)			
10	Year of construction	: 1998			
	Applicant's letter No	: F-8(244)/148/	PWD/GTBH/201-22/2	215-219	
11.	Applicant's letter Ho	24/12/2021			
S.No.	Minimum Standards on fire	Requirement/ BBL	Provided at site	Remarks	
2.11.101	Prevention and fire safety U/R 33			MR/NMR	
1.	Access to Building				
	1) Road width	12 mtr.	18 mtr.	MR	
	2) Gate width	4.5 mtr.	5.25 mtr.	MR	
		06 mtr.	06 mtr.	MR	
	3)Width of internal road		00 ma.		
2.	Number, Width Type & Arrang	gement of Exits			
	A. Number of staircases	02 No	02 No.	MR	
	1. Upper floor	NA	NA	NA	
	2. Basements	INA			
	B. Width of staircase	1.5 mtr.	1.5 & 1.44 mtr.	MR	
	1. Upper floors	1.5 mu.	1.5 c 1.44 ma.	(Old accepted)	
	2. Basements	NA	NA	NA	
	C. Protection of exits				
	1. Fire check door	Required	Provided	MR	
	2. Pressurization	Required	Provided	MR	
	D. No. of continuous	02 No	02 No.	MR	
	staircase to terrace				
	E. Width of corridor	1.5 mtr.	1.5 mtr.	MR	
	F. Door size	1.5 mtr.	1.5 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	Required	Provided	MR	
	2) Sealing of electrical shafts	Required	Provided	MR	
	3) Fire rating of shaft door	Required	Provided	MR	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	Required	Provided	MR	
4.	Smoke Management System				
	1) Basements	NA	NA	NA	
	2) Upper floors	Required	Natural	MR	
5.	Fire Extinguishers				
5.	1) Total numbers	25 Nos.	30 Nos.	MR	
	2) Types	CO2 & ABC	Provided	MR	
	3) ISI marking	ISI marked	Provided	MR	
6.	First-Aid Hose Reel				
	1)Total number of each floor	01 No.	01 No.	MR	
	2) Length of hose reel hose	30 m	30 m	MR	
			5 mm	MR	

Λ

	FIL				
7.	Automatic Fire Detection & Al	arming System			
	1) Type of detectors	Heat/Smoke	Provided	MR	
	2) Location of main panel	Basement	Provided	MR	
	3) Location of repeater panel	Security Room	Provided	MR	
	4) Alternate source of power	Battery & DG set	Provided	MR	
	5) Hooter's Location	Near staircase	Provided	MR	
8.	MOFFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System				
	1) Basement	NA	NA	NA	
	2) Upper floors	Required	Provided	MR	
	3) Sprinkler above false	NA	NA	NA	
	ceiling				
1.	Internal Hydrants				
	1) Size of riser/down-comer	100 MM	100 MM	MR	
		02	02	MR	
2		02	02	MR	
2.	Yard Hydrants				
	1) Total number of hydrants	02 Nos.	02 Nos.	MR	
10		02 Nos.	02 Nos.	MR	
13.	Pumping Arrangement	Common G	FB Hospital		
	1) Ground level				
	a) Discharge of main pump	2850 LPM	2850 LPM	MR	
	b) Head of main pump	70 mtr.	70 mtr.	MR	
	c) Number of main pump	01 No.	01 No.	MR	
	d) Jockey pump out put	240 LPM	240 LPM	MR	
	e) Jockey pump head	70 mtr.	70 mtr.	MR	
	f) Stand by pump output	2850 LPM	2850 LPM	MR	
	g) Stand by pump head	70 mtr.	70 mtr.	MR	
	h) Auto starting/Manual	Required	Provided	MR	
	stopping				
	2) Terrace level				
	a) Discharge of pump	450 LPM	450 LPM	MR	
	b) Head of pump	40 mtr.	40 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting Common GTB Hospital				
	 Under ground tank capacity 	N/A	1,00,000 ltr.	MR	
	a) Draw-off connection	NA	NA	NA	
	b) Fire service inlet	NA	NA	NA	
	c) Access to tank	NA	NA	NA	
	d) Over head tank capacity	ý 10,000 ltr.	10,000 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	a) Pressurization of lift	Required	Provided	MR	
	b) Pressurization of lift lobby	Required	Duquide		
	c) Communication in lift	Required	Provided	MR	
	car	Required	Provided	MR	
	d) Fireman's switch	Dequired	Duquidad) (D	
	e) Lift signage	Required	Provided	MR	

112

To Hospital. Anors

NIS

17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area			N/A
	Total area location	N/Λ	N/Λ	
19.	Fire Control Room	N/Λ	N/Λ	N/A
	a) Detector system panel	Required	Provided	MR
	b) Flow switch panel	Required	Provided	MR
		Required	Provided	MR
	c) PA system paneld) Battery backup	Required	Provided	MR
		Required	Provided	MR
	e) Building floor plan	MR		
20.	Special Fire Protection System any: Provided for HT/LT pane			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter No. F6/DFS/MS/Hospital/2012/578 dated

Keeping in view the substantial compliance of the minimum standards on fire 17/02/2012 have been rectified. prevention and fire safety required under the rules, grant of fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 / is recommended please.

Signature of the Inspecting Officer

Name :- Mehmood Designation :- ADO (1) Signature of the Inspecting Officer

Name :- M.K. Sharma Designation :- ADO (LN)

Dy. CEO/NDZ

CFO(HD) DIM Direct

F.T. Litts Di