GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 59

Dated: 2. 8./...1./2022

FIRE SAFETY CERTIFICATE

Certified that the Mother Palace Guest House located at 1454, Sangtrashan, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (01 guest room + reception + 01 store), 1st floor to 3rd floor (04 guest rooms at each floor), and 4th sealed, total 13 guest rooms owned/occupied by Mother Palace Guest House was earlier granted FSC by this department vide letter no.F6/DFS/MS/GH/NDZ/2019/65 dated 08/01/19. Now, the premises was re-inspected by the officer concerned of this department on 20/01/22 in the presence of Sh. Biru (Manager) and found that the said guest house building having given an affidavit dated 11.11.2019 regarding not to use any floor above third floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (01 guest room + reception + 01 store), 1st floor to 3rd floor (04 guest rooms at each floor), total 13 guest rooms up to third floor only, with effect from under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued?. A. New Delhi by.

(Dr.S.K.Tomar) Dy.Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2022010700418 dated 07.01.2022.
- 3. The Manager,

Mother Palace Guest House, 1454, Sangtrashan, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- This clearance/ FSC shall stand cancelled, if guest house owner/occupier fails to comply all conditions mentioned in the gazette notification dated 27.05.2019 & letter of extension of time period issued on dated 20.12.2021, latest by 31.03.2022.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

INSPECTION REPORT N 15

1. Name & address of the building:- Mother Palace Guest House at 1454,

Sangtrashan, Pahar Ganj, New Delhi

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 13 Guest rooms) Ground floor (01 guest room + reception + 01 store), 1st floor to 3rd floor (04 guest rooms at each floor), and 4th floor (an affidavit given by owner dated 11.11.2019

regarding not to use any floor above third floor)

3. Type of case:-Renewal

4. Details of previous FSC:-No.F6/DFS/MS/GH/NDZ/2019/65 dated

08/01/19.

5. Fire safety directives No.-N/A 6. Date of inspection:-20/01/22

7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer

From the building side:-Sh. Biru (Manager)

9. Year of construction:-2007

10. Applicant's letter No:-Online id no.2022010700418 dated 07.01.2022.

				Old Case		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	N/A	02 mtr.	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arra					
	A. Number of staircases					
	1. Upper floors	01 Nos.	01 Nos.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	0.80 mtr.	1.25 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits			1441		
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	N/A	N/A	N/A		
	staircase to terrace			1		
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	1 mtr.	1 mtr.	MR		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	Required as	Not provided	Last dt. 31.03.22		
		per G.N	1	of compliance		
		dated		extended vide		
		27.05.19		order dt.		
				20.12.2021		



MZL

5.	Fire Extinguishers							
	1) Total numbers							
	2) Types	08 Nos.	08 Nos.	M	R			
	3) ISI marking	ABC & CO	2 ABC & CO2	M				
6.	First Aid IX	Required	Provided	M				
	First-Aid Hose Reel			111				
	1) Total number of eachflo	oor 01	01	MI	R			
	2) Length of hose reel hose	e 30 m	30 m	MI				
7.	3) Nozzle diameter	05 mm	05					
/•	Automatic Fire Detection & Alayming System							
	1) Type of defectors (1) type Dequired D 11							
	2) Location of main panel	Gr. floor	Provided	MI				
	3) Location of repeater pan	el N/A	N/A	MI				
	4) Alternate source of now	er Required		N/A				
	5) Hooter's Location	Required	Provided	MF				
8.	MOEFA	N/A	Provided	MF				
9.	Public Address System		N/A	N/A	A			
10.	Automatic Sprinkler System	Required	Provided	MR				
	1) Basement							
	2) Upper floors	N/A	N/A	N/A				
	3) Sprinkler 1	N/A	N/A	N/A				
	3) Sprinkler above false ceiling	N/A	N/A	N/A				
11.	Cening			IVA	L			
11.	Internal Hydrants	•		+				
	1) Size of riser/down-comer	N/A	N/A	1				
	2) Number of hydrants per	N/A	N/A	N/A				
	floor	1	IVA	N/A				
•	3) Hose box	N/A	N/A					
2.	Yard Hydrants		IN/A	N/A				
	1) Total number of hydrants	N/A	27/4					
	2) Hose box	N/A	N/A	N/A				
3.	Pumping Arrangement	IVA	N/A	N/A				
	1) Ground level	27/4						
	a) Discharge of main	N/A	N/A	N/A				
	pump	N/A	N/A	N/A				
				11/7				
	und or main pullip	N/A	N/A	N/A				
	c) Number of main	N/A	N/A	N/A				
	pump		·· = =	N/A				
	d) Jockey pump out put	N/A	N/A	+				
}	e) Jockey pump head	N/A	N/A	N/A				
	f) Stand by pump	N/A		N/A				
L	output	- " - 1	N/A	N/A				
L	g) Stand by pump head	N/A						
	h) Auto	NIA	N/A	N/A				
	starting/Manual	N/A	N/A	N/A				
	stopping			11/1				
	2) Terrace level							
-				-				
\vdash	a) Discharge of pump	220 LPM	220 LPM	-				
<u> </u>	b) Head of pump	20		MR				
L	c) Power supply	D	30 mtr	MR				
	d) Auto starting of	Dog. 1	Provided	MR				
	pump	Required	Provided	MR				
- 1	гР	1		1111				
.		I		1				

411

14.	Captive Water Storage for Fire Fighting						
	Under ground tank capacity	N/A	N/A	N/A			
	a) Draw-off connection	N/A	N/A	N/A			
	b) Fire service inlet	N/A	N/A	N/A			
	c) Access to tank	N/A	N/A	N/A			
	 d) Over head tank capacity 	2500 ltr.	2500 ltr.	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.	1					
	a) Pressurization of lift shaft	N/A	N/A	N/A			
	b) Pressurization of lift lobby	N/A	N/A	N/A			
	c) Communication in lift car	N/A	N/A	N/A			
	d) Fireman's switch	N/A	N/A	N/A			
	e) Lift signage	N/A	N/A	N/A			
17.	Stand by Power Supply	Required	Provided	MR			
18.	Refuge Area	N/A	N/A	N/A			
	Total area location	N/A	N/A	N/A			
19.	Fire Control Room	N/A	N/A	N/A			
	a) Detector system panel	N/A	N/A	N/A			
	b) Flow switch panel	N/A	N/A	N/A			
	c) PA system panel	N/A	N/A	N/A			
	d) Battery backup	N/A	N/A	N/A			
	e) Building floor plan	N/A	N/A	N/A			
20.	Special Fire Protection System Risk, if any:	for Protect	ion of special	NA			

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/65 dated 08/01/19, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: 4 ADO (CC)

to porred propulate