GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001</u>

No. F6/DFS/MS/2022/ Misc/フリ

~

Dated: 24/ 0)/2022

FIRE SAFETY CERTIFICATE

Certified that the Toy Bank Cum Play Centre located at Derawal Nagar, Gujrawala Town, CHBS Limited, Delhi- 110009 comprised of basement, ground and three upper floors (Basement- Storage, School is running on G+01 upper floor, 2nd & 3rd floor residential purpose) owned/ occupied by the Toy Bank Cum Play Centre have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 18.01.2022 in the presence of Sh. Satish AE(Civil) & Sh. Sanjeev (Attendant) and that the building/premises is fit for Mixed Occupancy (Educational + Residential) with effect from ...2.1.1.2.2.2... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on . Jules 1. 2. 2. 9 at New Delhi

11/2-2

Director Ph:-011-23414000

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>http://delhi.gov.in./wps/wcm/connect/doit</u> fire/FIRE/Home/Forms.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

-			INCORE OF	WONDEBODT		
	•			<u>FION REPORT</u>		
		ne & address of the building	: Toy Ba	ank Cum Play Centr	re at Derawal Nagar, De	elhi-110009.
	2. Con	nposition of building	: B+G+	03 upper floors (Ba	asement- Store, Grou	nd & First floor-
			Educa	tional, Second & T	Third floor- Residentia	ul)
	3. Тур	e of Occupancy	: Mixed	l occupancy (Edu	cational + Residentia	1)
	4. Typ	be of Case	: Comp	letion ID No-1005	59755	
	5. Det	ails of previous NOC	: Nil			
	6. Fire	Safety directives letter No	: F6/DF	S/MS/2019/BP/64	4 Dated 15.02.2019	
		e of inspection	: 18.01.			
		ne of the Inspecting Officers				
		ne and designation of officers		w & ADO (KN)		
		m the building side			& Sh. Sanjeev (Atten	dant)
		ar of Construction	: 2017	7		
		olicant's letter No.	: Com	pletion ID No-100	59755 Dated 18.01.	.2022
		ca-487.83 m2 imum Standards on fire preventi	on and			
		fire safety U/R 33	on and	NBC Part-04 Requirement	Provided at site	Remarks MR/NMR
1		s to building				
	•	Road width		06m	18m	MR
	•	Gate width		4.5m	4.5m °	MR
	•	Width of internal road		NA	NA	NA
2	Numb	er, Width, Type & Arrangement	of Exits			
	a. Nul			02	02	MD
		Upper Floors Basements		02	02	MR
	b. Wi	th of staircases			02	WIK
		Upper Floors		1.50m	1.50m each	MR
		Basements		1.50m	1.50m each	MR
	c. Pro	tection of exits				
	•	Fire check door		Required	Provided	MR
	•	Pressurization		NA	NA	NA
	d. No	. of continuous staircases to terrace		02	02	MR
	e. Wid	lth of Corridor		NA	NA	NA
	f. Doo	r Size		1.50m & 01m	1.50m & 01m	MR
3	Comp	artmentation.		NIA		
	•	Fire check door		NA	NA	NA
	•	Sealing of electrical shafts	-		NA	NA
	•	Fire Rating of shaft door Water Curtain		NA	NA	NA
	•		r	Required	Provided	MR
4	Small	Fire Dampers e Management System.		NA	NA	NA
-+	Smoke	Basements		12 a/a par barr		
		Basements Upper floors	-	12 a/c per hour 12 a/c per hour	Provided	MR
5	Fir	e Extinguishers			Natural ventilation	MR
-		Total numbers		12nos	14nos	MR
		Types	-	ABC/Co2	ABC-10/Co2-02	MR
	1		ŀ			

) fef

Yes

Provided

MR

ISI marking

NI7

6	First-Aid Hose Reels.			
	• Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30m	Provided	MR
	Nozzle diameter	5mm	Provided	MR
	Automatic fire detection and alarming system			
	Type of detectors	NA	NA	NA
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA ·	NA
	Hooters' Location	NA	NA	NA
	MOEFA	NA	NA	NA
,	MOEFA			
)	Public Address System.	NA	NA	NA
0	Automatic Sprinkler System.	D	Provided	MR
	• Basement	Required	NA	NA
	Upper Floor	NA		
	• Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants			
	Size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	
	• Hose Box	NA	NA	NA
12				NA
	Total number of hydrants	NA	NA	
	• Hose Box	NA	NA	NA
13	Pumping Arrangements.			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A N/A	N/A	N/A
	Standby Pump out put		N/A	N/A
	 Standby Pump Head Auto Starting/ Manual stopping 	N/A N/A	N/A N/A	N/A
	 Auto Starting/ Manual stopping Pump House Access 	N/A N/A	N/A	N/A
	Terrace level			
	 Discharge of pump 	450lpm x2	Provided	MR
	 Head of the pump 	40m	40m	MR
	> Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.			
		NA	NA	NA
	 Underground tank capacity Draw-off connection 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
			15,000ltr.	MR
	Overhead Tank capacity	15,000ltrs	15,000101	

(pp

1

5

M	8
---	---

,	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.	One Car lift & Or	One Car lift & One Passenger Lift Not installed				
	Pressurization of Lift Shaft	NA	NA	NΛ			
	Pressurization of Lift lobby	NA	NA	NA			
	Communication In lift Car	Required	Provided	MR			
	• Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	 Fotal Area 	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 1440 dated 24.07.2021

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated in NBC Part 4, it is recommended to grant Fire Safety Certificate

19/01/2022

Signature of the Inspecting Officer Name :-D.B. Mukheyjee Designation:-DO/NW

52)

Signature of the Inspecting Officer Name :- C.L. Meena Designation:- ADO/RN

NW ADDEN