GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2022/ 25

Dated: 03/02/22

FIRE SAFETY CERTIFICATE

Issued - 2 / 62/12 - at New Delhi by.

(**Dr. S.K.Tomar**)

Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID NO 2021122729416 dated 30.12.21.
- 2. The Medical Officer of Health, Health Department, Palika Kendra, New Delhi.
- 3. The Manager,

M/s Bhaja Govindam Restaurant (Prop. Lakshmi Venketeshwara (P) Ltd.), ground floor Delite Theater Building, Asaf ali Road, New Delhi.

Condition for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

N/12

INSPECTION REPORT

1. Name & address of the building M/s Bhaja Govindam Restaurant (Prop.

Lakshmi Venketeshwara (P) Ltd.) at ground floor Delite Theater Building, Asaf Ali

Road, New Delhi

2. Type of occupancy:- Assembly Building Group-D

Gr. + 04 upper floors, Restaurant at ground floor only

3. Type of case:- Renewal

4. Details of previous FSC:- F6/DFS/MS/EH/2019/NDZ/950 dated

07/05/19

5. Fire safety directives No.- N/A

6. Date of inspection: 28/01/22

7. Name of the inspecting officer:- Sh. Rajinder Atwal (DO/CD) &

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer from the building side:-

Mr. R.K. Mehrotra (CEO)

9. Year of construction:-

10. Applicant's letter No:- ID No 2021122729416 dated 30.12.21

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safe arrangements	Provided at sit	e Remarks MR/NMR	
1.	Access to Building				
	1) Road width	06 mtr	18 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Ai	rrangement of E	exits		
	A. Number of staircases				
	1. Upper floors	N/A	N/A	N/A	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	N/A	N/A	N/A	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits	N/A	N/A	N/A	
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous	N/A	N/A	N/A	
	staircase to terrace				
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	02 mtr.	02 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
İ	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH		N/A	
	2) Upper floors	12 ACPH	Natural	MR	
5.	Fire Extinguishers				
	1) Total numbers	06 Nos.		MR	
	2) Types			MR	
T	3) ISI marking	Required	Provided	MR	



N/13

	'				-
6.	First-Aid Hose Reel			1.10	/
0.	1) Total number of eachfloor	01	01	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection &	Alarming Sys	stem	1.45	
/•	1) Type of detectors	N/A	Provided	MR	
	2) Location of main panel	N/A	Provided	MR	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler System				
10.	1) Basement	N/A	N/A	N/A	
	2) Ground floors	N/A	Provided at	MR	
	2) Ground freess		ground floor		
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling				
11.	Internal Hydrants				
	1) Size of riser/down-comer	100 mm	100 mm	MR	
	2) Number of hydrants per	01	01 at ground	MR	
	floor		floor	200	
	3) Hose box	01	01	MR	
12.	Yard Hydrants			1274	
	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement				
	1) Ground level			21/4	
	a) Discharge of main	N/A	N/A	N/A	
	pump	27/4	DI/A	N/A	
	b) Head of main pump	N/A	N/A N/A	N/A	
	c) Number of main	N/A	N/A	1V/A	
	pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump	IN/A	IVA	IV/A	
	g) Stand by pump head	N/A	N/A	N/A	
	g) Stand by pump head h) Auto	N/A	N/A	N/A	
	starting/Manual	14/21	1771	11"	
	stopping				
	2) Terrace level		7		
	a) Discharge of pump	450, 180 LPM	450, 180 LPM	MR	
	b) Head of pump	35 mtr.	35 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of	Required	Provided	MR	
	pump	•			
14.	Captive Water Storage for I	ire Fighting	-		
	1) Under ground tank	N/A	N/A	N/A	
	capacity				
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	



11/14

	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	10,000 ltr.	10,000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	1	TTOTAGE	IVIA
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	 c) Communication in lift car 	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System if any:	for Protection	of special Risk,	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2019/NDZ/950 dated 07/05/19 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name :- Rajinder Atwal

Designation:-DO(CD)

Signature of the Inspecting Officer

Name :- Ravinder Singh Designation :- ADO (CC)

- 1/2/22
d - Arapponin pruputup fro Kund Penus Daw
'constan Please