GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/NDZ/2022/ 7 9

Dated: 03/12/22

FIRE SAFETY CERTIFICATE

Certified that the Hotel Aster Inn located at 1078-80, Block-C, Gali No.-4, Hardhyan Singh Road, Naiwalan, Karol Bagh, New Delhi comprised of Basement + Ground + 03 Upper floors, Basement (Meeting hall + office + storage), Ground floor (reception + 04 guest rooms), 1st floor to 3rd floor (05 guest rooms + 01 store room at each floor), total 19 guest rooms owned/occupied by Hotel Aster Inn was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2019/NDZ/483 dated 08/03/19. Now, the premises was re-inspected by the officer concerned of this department on 29/01/22 in the presence of Sh. Rakesh Kumar and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (reception + 04 guest rooms), 1st floor to 3rd floor (05 guest rooms at each floor), Total - 19 guest rooms up to third floor only with effect from -4-3-4-6-2-4-2-2---- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -03/02/22 at New Delhi by.

(**Dr. S.K.Tomar**)

Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Id No. 2022012501235 dated 25.01.2022.
- 3. The Manager, Hotel Aster Inn, 1078-80, Block-C, Gali No. -4, Hardhyan singh Road, Naiwalan, Karol Bagh, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

N/16

INSPECTION REPORT

1. Name & address of the building:- Hotel Aster Inn located at 1078-80, Block-

C, Gali No. -4, Hardhyan singh Road,

Naiwalan, Karol Bagh, New Delhi

2. Type of occupancy:- Residential, Sub Division-A-1

B + Gr. + 03 Upper floors (total 19 Guest rooms) Basement (Meeting hall + office + storage), Ground floor (reception + 04 guest rooms), 1st floor to 3rd floor

(05 guest rooms + 01 store room at each floor)

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/2019/NDZ/483 dated

08/03/19.

5. Fire safety directives No.-

N/A

6. Date of inspection:-

29/01/22

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

Sh. Rajesh Kumar

9. Year of construction:-

10. Applicant's letter No:-

ld No. 2022012501235 dated 25.01.2022.

Old Case

				Old Case				
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR				
1.	Access to Building							
	1) Road width	N/A	09 mtr.	N/A				
	2) Gate width	N/A	1.96 mtr.	N/A				
	3)Width of internal road	N/A	N/A	N/A				
2.	Number, Width Type & Arr							
	A. Number of staircases							
	1. Upper floors	01 Nos.	01 Nos.	MR				
	2. Basements	01 Nos.	01 Nos.	MR				
	B. Width of staircase							
	1. Upper floors	1.25 mtr.	1.30 mtr.	MR				
	2. Basements	1.25 mtr.	1.48 mtr.	MR				
	C. Protection of exits							
	1. Fire check door	N/A	N/A	N/A				
	2. Pressurization	N/A	N/A	N/A				
	D. No. of continuous	01	01	MR				
	staircase to terrace							
	E. Width of corridor	N/A	N/A	N/A				
	F. Door size	1 mtr.	1 mtr.	MR				
3.	Compartmentation							
	1) Fire check door	N/A	N/A	N/A				
	2) Sealing of electrical shafts	N/A	N/A	N/A				
	3) Fire rating of shaft door	N/A	N/A	N/A				
	4) Water curtain	N/A N/A	N/A N/A	N/A				
	5) Fire Dampers	N/A						
4.	Smoke Management System							
	1) Basements	30 ACPH	Exhaust fan	MR				
	2) Upper floors	12 a/c per	Natural/exhaust	MR				
		hour	fan					



5.	Fire Extinguishers	T		
	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection & A			
	1) Type of detectors CO type	Required	Provided	MR
	2) Location of main panel	Gr. floor	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Each floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	Required	1 TOVIGEG	1711
10.	1) Basement	Required	Provided	MR
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	IN/A	IN/A	IN/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	1071	14/71	IVA
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		1071	IVA
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			11111
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			17/1
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping		- "	IV/A
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
			30 mtr.	MR
	b) Head of pump	30 mtr.		
	b) Head of pumpc) Power supply	30 mtr. Required		
	b) Head of pumpc) Power supplyd) Auto starting of pump	Required Required	Provided	MR
14.	b) Head of pump c) Power supply d) Auto starting of pump Captive Water Storage for F	Required Required		
14.	b) Head of pumpc) Power supply	Required Required ire Fighting	Provided Provided	MR MR
14.	b) Head of pump c) Power supply d) Auto starting of pump Captive Water Storage for F	Required Required	Provided	MR

1	(0				

	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	10000 ltr.	10000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	tion of special	NA	

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the **FSC** issued vide letter no. F6/DFS/MS/GH/2019/NDZ/483 dated 08/03/2019, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

Name: - Sh. Ravinder Singh

Designation: - ADO (CC)