1-60

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2022/ 7 8

Dated : $\frac{03}{02/2}$

FIRE SAFETY CERTIFICATE

Certified that the "Sawera International" Guest House located at 7875, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (03 guest rooms + reception + office), 1st floor to 3rd floor (06 guest rooms at each floor), total 21 guest rooms and 4th floor (05 rooms used owner's residence + kitchen) owned/occupied by Sawera International Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/EH/2018/NDZ/2594 dated 03/12/18. Now, the premises was re-inspected by the officer concerned of this department on 29/01//22 in the presence of Sh. Sukhwinder Singh and found that the said guest house building having given an affidavit dated16.12.2019 regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (03 guest rooms + reception + office), 1st floor to 3rd floor (06 guest rooms at each floor), total 21 guest rooms Total -21 guest rooms up to third floor only with effect from -03/02/2-2--- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -0-3/02/21 at New Delhi by.

(Dr. S.K.Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

2/4/22

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No 2022011700867 dated 17.01.2022.
- 3. The Manager,
 - "Sawera International" Guest House at 7875, Arakashan Road, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. This clearance/ FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 20.12.2021, latest by 31.03.2022.
- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

N/22

INSPECTION REPORT

"Sawera International" Guest House at 7875, Arakashan Road, Pahar Ganj, New Delhi 1. Name & address of the building:-

Residential, Sub Division-A-1 2. Type of occupancy:-

Gr. + 04 Upper floors Total -21 guest rooms Ground floor (03 guest rooms + reception + office),

1st floor to 3rd floor (06 guest rooms at each floor),

4th floor (05 rooms) and

not in use as per affidavit dated16.12.2019

Renewal

No. F6/DFS/MS/EH/2018/NDZ/2594 dated 3. Type of case:-4. Details of previous FSC:-

03/12/18.

N/A 5. Fire safety directives No.-29/01/22

6. Date of inspection:-Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-Sh. Rajinder Atwal DO/CD

8. Name & designation of officer Sh. Sukhwinder Singh From the building side:-

9. Year of construction:-

ID No 2022011700867 dated 17.01.2022. 10. Applicant's letter No:-

10. Applicant's letter No:-		ID No 2022011700807 dated 1770 Old Case			
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building			N/A	
	1) Road width	N/A	03 mtr.	N/A	
	2) Gate width	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr	angement of Ex	its		
۷٠	A. Number of staircases			MR	
	1. Upper floors	01 Nos.	01 Nos.	N/A	
	2. Basements	N/A	N/A	IN/A	
	B. Width of staircase 1. Upper floors	0.80 mtr.	1.25 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	01	01	MR	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1 mtr.	1 mtr.	MR	
3.	Compartmentation				
<u>. </u>	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
	Smoke Management System				
4.	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021	

2/23

	67/0					
5.	Fire Extinguishers					
	1) Total numbers	14 Nos.	14 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel	*				
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors COType	Required	Provided	MR		
	2) Location of main panel	Gr. floor	Provided	MR		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	Required	Provided	MR		
	5) Hooter's Location	Ground floor	Provided	MR		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling					
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor					
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants					
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement					
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump			1		
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main	N/A	N/A	N/A		
	pump			1 7		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping			17/1		
	2) Terrace level					
	a) Discharge of pump	450 LPM	450 LPM	MR		
	b) Head of pump	30 mtr.	30 mtr.	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided			
		1	- 10 videu	MR		
4.	Captive Water Storage for Fi	re Fighting				
	1) Under ground tank		N/A			

	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
5.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.	required	1101100	
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2018/NDZ/2594 dated 03/12/2018, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor only.

Signature of the inspecting officer

Name: - Rajinder Atwal

Designation: - DO (CD)

Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

sortone Man.