GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 67

Dated 8.4./2../2022

FIRE SAFETY CERTIFICATE

Certified that the Shanti Guest House located at 3838, Tel Mandi, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (Reception + 05 guest rooms + 02 stores), 1st floor (03 guest rooms + owner's residence), 2nd floor (05 guest rooms + 01 staff room + staff kitchen) and 3rd floor (01 staff room & 01 store room), total 13 guest rooms owned/occupied Shanti Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/2677 dated 12/12/18. Now, the premises was re-inspected by the officer concerned of this department on 21/01/22 in the presence of Sh. Gopal Krishan and found that the said guest house building having Ground floor (Reception + 03 guest rooms + 01 stores, locker room, laundry, office & manager room), 1st floor (03 guest rooms + owner's residence), 2nd floor (05 guest rooms + 02 room for personnel use) and 3rd floor (02 staff room, generator room & 01 store room), has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 03 guest rooms), 1^{st} floor (03 guest rooms), 2^{nd} floor (05 guest rooms) total -11 guest room up to second floor **only** with effect from $-\frac{0}{1/2}$ for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -01-12-12-2----at New Delhi by.

(**Dr. S.K.Tomar**)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

- The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy up to second floor as detailed above
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defense Colony New Delhi ID No 2021112627268 dated 26.11.21 & email gopalkrishan.62@gmail.com dated 12.01.2022
- 3. The Manager,

Shanti Guest House, 3838, Tel Mandi, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

N/25

INSPECTION REPORT

1. Name & address of the building

Shanti Guest House located at 3838, Tel Mandi, Pahar Ganj, New Delhi

2. Type of occupancy:-

Residential, Sub Division-A-1
Gr. + 03 Upper floors (total 11 Guest rooms)
Ground floor ((Reception + 03 guest rooms +
01 stores locker room laundry office & manager room

Ground floor ((Reception + 03 guest rooms + 01 stores, locker room, laundry, office & manager room) 1st floor (03 guest rooms + owner's residence), 2nd floor (05 guest rooms + 02 room for personnel use) and 3rd floor (02 staff room, generator room & 01 store room)

3. Type of case:-

Renewal

4. Details of previous FSC:-

No. F6/DFS/MS/GH/2018/NDZ/2677 dated

12/12/18.

5. Fire safety directives No.-

N/A

6. Date of inspection:-

21/01/22

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

Sh. Gopal Krishan (Manager) 1980

9. Year of construction:10. Applicant's letter No:-

ID No 2021112627268 dated 26.11.21 &

email gopalkrishan.62@gmail.com dated 12.01.2022

				Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	10 mtr.	MR
	2) Gate width	N/A	On road	MR
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr	angement of E	xits	
2.	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	1.06 Mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01	01	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1 mtr.	1 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
ļ.	Smoke Management System			
4.	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	12 ACPH	Natural	MR



4/26

5.	Fire Extinguishers			7
	1) Total numbers	06 Nos.	06 Nos.	100
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided Provided	MR
6.	First-Aid Hose Reel	required	Tiovided	MR
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection & A	em	IVIK	
	1) Type of detectors CO	Required	Provided	MR
	2) Location of main panel	Gr. floor	Provided	MR
	3) Location of repeater panel	Required	Provided	MR
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Gr. floor	Provided	MR
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	required	TTOVIUCU	IATIC
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	14/11	14/7	
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor		- "	
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
-	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	225 LPM	225 LPM	MR
	b) Head of pump	25 mtr.	25 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump		Provided	MR
1.4	Captive Water Storage for Fire Fighting			
14.	Under ground tank capacity	N/A	N/A	N/A

本本に	127
`. \	1

	 a) Draw-off connection 	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	 a) Pressurization of lift shaft 	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System if any:	n for Protection	on of special Risk,	NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/2677 dated 12/12/2018 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to second floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

Acapporned, per pertup for Ica felusel 1 sepostion Please