## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 8/

Dated: Q. 7.1 A. 2./2022

## FIRE SAFETY CERTIFICATE

Certified that the Station View Guest House located at 4254-55, Tel Mandi, Pahar Ganj, New Delhi comprised of stilt, Ground & three upper floors, stilt ( parking ), ground floor to 3<sup>rd</sup> floor (12 guest rooms at each floor), total 48 guest rooms owned/occupied by Station View Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2019/NDZ/225 dated 29/01/19 & F6/DFS/MS/GH/2020/NDZ/769 dated 20/04/20(corrigendum). Now, the premises was re-inspected by the officer concerned of this department on 28/01/21 in the presence of Sh. Tanmay (Manager) and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential Group Hotels A-5-1 (i), stilt ( parking ), ground floor to 3<sup>rd</sup> floor (12 guest rooms at each floor) total -**48** guest rooms up to third floor only, with effect from renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued  $\frac{03/02/22}{at}$  New Delhi by.



(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi : to ensure the occupancy as detailed above and to verify the height of building.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No 202112229089 dated 22.12.21 <u>hotelstarplalace@gmail.com</u>> dated 24.01.2021
- 3. The Manager,

Station View Guest House 4254-55, Tel Mandi, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate.

- 1. This clearance/ FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 20.12.2021, latest by 31.03.2022.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

		TION REPOR	т	
1. Nar	me & address of the building:-	Station View G	1 uest House at 440	254-55 Tel
	to address of the building."	Mandi Pahar (	Ganj, New Delhi	
2. Ty	-	,	b Division-A-1	
2. 19			Upper floors (total	18 Guast rooms)
	51 Sti	lit + Ground + 03	and floor to 3 <sup>rd</sup> floor	(12  guest room)
		each floor		(12 guest room
3. T	ype of case:-	Renewal		
	Details of previous FSC:-		1S/GH/2019/ND2	7/225 dated
2	Journa of previous 1.5C			
			b. F6/ DFS/ MS/ C	JH/ 2019/
5 1		NDZ/ 225 date	ed 29.04.2020	
	Fire safety directives No	N/A		
	Date of inspection:-	28/01/22		
7.	Name of the inspecting officer:-	Sh. Ravinder	Singh (ADO/CC)	)
		Sh. Rajinder	Atwal DO (CD)	
8.	Name & designation of officer			
]	From the building side:-	Sh. Tanmay (	Manager)	
9. `	Year of construction:-	2014		
10.	Applicant's letter No:- ID	No 20211222908	9 dated 22.12.21	
		otelstarplalace@	<u>)gmail.com</u> > date	ed 24.01.2021
			2.1.	Old Case
S.No.	Minimum Standards on fire	Requirement	Provided at site	Remarks
		Existing fire		MR/NMR
		safety		
		arrangements		
1.	Access to Building			
	1) Road width	N/A	6 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arra	angement of Exi		
	A. Number of staircases	8		
	1. Upper floors	02 Nos.	02 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	1.5 mtr. & 1	1.6 mtr. & 1 mtr.	MR
		mtr.	l intra	
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			11/1
	1. Fire check door	Required as per	Not provided	Last dt.
		G.N dated		31.03.22 of
		27.05.19		compliance
				extended vide
				order dt.
	2. Pressurization	N/A	N/A	20.12.2021 N/A
	D. No. of continuous	N/A	N/A N/A	N/A N/A
	staircase to terrace			
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1 mtr.	1 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts		N/A N/A	N/A N/A
	3) Fire rating of shaft door	N/A N/A	N/A N/A	N/A N/A
		N/A N/A	N/A N/A	N/A N/A
	4) Water curtain			IN/A
	<ul><li>4) Water curtain</li><li>5) Fire Dampers</li></ul>			
4.	4) Water curtain 5) Fire Dampers Smoke Management System	N/A	N/A N/A	N/A

C

21/18

	2) Upper floors	12 a/c per	Exhaust /Natural Ventilation	MR 🧊
<b>.</b>	Fire Extinguishers			
	1) Total numbers	12 Nos.	14 Nos.	MR
ľ	2) Types	ABC & CO2	ABC & CO2	MR
ł	3) ISI marking	Required	Provided	MR
5.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 m	30 m	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &			
	1) Type of detectors	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	-1		
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	•		
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out pu	t N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	i N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A

9	

	-				
	2) Terrace level				
	a) Discharge of pump	450 LPM 30 mtr Required		900 & 450 LPM	MR
	b) Head of pump			30 mtr	MR
	c) Power supply			Provided	MR
	d) Auto starting of pump	-	quired	Provided	MR
4.	Captive Water Storage for Fin	re Fig	hting		
	1) Under ground tank capacity		N/A	N/A	N/A
	a) Draw-off connection		N/A	N/A	N/A
	b) Fire service inlet		N/A	N/A	N/A
	c) Access to tank		N/A	N/A	N/A
	d) Over head tank capacity	у	50,000 ltr.	50, 000 ltr.	MR
5.	Exit Signage.		Required	Provided	MR
16.	Provision of Lifts.				
	a) Pressurization of lift sh	aft	N/A	N/A	N/A
	b) Pressurization of lift lobby		N/A	N/A	N/A
	c) Communication in lift	car	Required	Provided	MR
	d) Fireman's switch		Required	Provided	MR
	e) Lift signage		Required	Provided	MR
17.	Stand by Power Supply		Required	Provided	MR
18.	Refuge Area		N/A	N/A	N/A
	Total area location		N/A	N/A	N/A
19.	Fire Control Room		N/A	N/A	N/A
	a) Detector system panel		N/A	N/A	N/A
	b) Flow switch panel		N/A	N/A	N/A
	c) PA system panel		N/A	N/A	N/A
	d) Battery backup		N/A	N/A	N/A
	e) Building floor plan		N/A	N/A	N/A
20.	Special Fire Protection Syste any:	em fo	r Protection	of special Risk, if	NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2019/NDZ/225 dated 29/01/2019 & F6/DFS/MS/GH/2020/NDZ/769 dated 20/04/2020, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval.

Signature of the Inspecting Officer

Name: - Rajinder Atwal Designation :- DO/CD

(0) au

Signature of the Inspecting Officer

Name :- Ravinder Singh

Designation :- ADO (CC)

Batup for Icu penual an