C-66

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 Dated: 02./0.7./2022

No.F6/DFS/MS/GH/NDZ/2022/ 8/

FIRE SAFETY CERTIFICATE

Certified that the Hari Kiran Guest House located at 4220, Tel Mandi, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (Reception + 04 guest rooms), 1st floor (05 guest rooms), 2nd floor & 3rd floor (06 guest rooms at each floor), total 21 guest rooms owned/occupied by Hari Kiran Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2019/228 dated 29/01/19. Now, the premise was re-inspected by the officer concerned of this department on 25/01/22 in the presence of Manager and found that the said guest house building comprises of ground and four upper floor & an affidavit dated 21.10.2019 has submitted by owner regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 03 guest rooms), 1st floor (05 guest rooms), 2nd floor & 3rd floor (06 guest rooms at each floor), total 20 guest rooms up to third floor only, with effect from ... 08. 0.2. 20.22 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 08/02/2022 at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id. 2022011700851 dated 17.01.2022.

3. The Manager,

Hari Kiran Guest House, 4220, Tel Mandi, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. This clearance/ FSC shall stand cancelled, if guest house owner/occupier fails to comply all conditions mentioned in the gazette notification dated 27.05.2019 & letter of extension of time period issued on dated 20.12.2021, latest by 31.03.2022.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

INSPECTION REPORT

1. Name & address of the building Hari Kiran Guest House at 4220, Tel Mandi, Pahar Ganj, New Delhi

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 20 Guest rooms) Ground floor (Reception + 03 guest rooms+ 01 store room), 1st floor (05 guest rooms), 2nd floor & 3rd floor (06 guest rooms at each floor) 4th floor & terrace not in use as per affidavit owner

dated 21.10.2019

3. Type of case:-Renewal

4. Details of previous FSC:-No. F6/DFS/MS/GH/NDZ/2019/228 dated

29/01/19.

5. Fire safety directives No.-N/A 6. Date of inspection:-

25/01/22

7. Name of the inspecting officer:-

Sh. Rajinder Atwal (DO/CD) & Sh. Ravinder Singh (ADO/CD)

8. Name & designation of officer From the building side:-

Manager 2004

9. Year of construction:-10. Applicant's letter No:-

Online id. 2022011700851 dated 17.01.2022.

S.No.) C :			Old Case
3.110.	Minimum Standards on fire	e Requirement/	Provided at	Remarks
	Prevention and fire safety	Existing fire safet arrangements	y site	MR/NMR
1.	U/R 33	- Bernewi		
1.	Access to Building	,		
	1) Road width	N/A	4.5 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & A	14/21		
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
-	B. Width of staircase			IVA
- 1	1. Upper floors	0.80 mtr.	1.40 mtr. To	MR
-	0.7		1.50 mtr.	IVIK
	2. Basements	N/A	N/A	N/A
	C. Protection of exits		1011	IN/A
	1. Fire check door	N/A	N/A	NI/A
	2. Pressurization	N/A	N/A	N/A
1	D. No. of continuous	N/A	N/A	N/A
<u> </u>	staircase to terrace		17/2	N/A
<u> </u>	E. Width of corridor	N/A	N/A	27//
	. Door size	1.0 mtr.	1.0 mtr.	N/A
	Compartmentation		1.0 mtr.	MR
1) Fire check door	N/A	NI/A	
(2)	Sealing of electrical shafts	N/A	N/A	N/A
(3)	Fire rating of shaft door	N/A	N/A	N/A
4)	Water curtain	NI/A	N/A	N/A
5)	Fire Dampers	27/4	N/A	N/A
Sn	noke Management System	IVA	N/A	N/A
1)	Basements	20 A CDIT		
		30 ACPH	J/A	N/A



	2) Upper floors	Required as	Not provided	Last dt. 31-3.22		
		per G.N		of compliance		
		dated		extended vide		
		27.05.19		order dt.		
				20.12.2021		
5.	Fire Extinguishers					
	1) Total numbers	08 Nos.	08 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel					
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection &					
·	1) Type of detectors CO	Required	Provided	MR		
	Type	Required	1101100			
	2) Location of main panel	Gr. floor	Provided	MR		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	Required	Provided	MR		
	5) Hooter's Location	Required	Provided	MR		
0	<u>'</u>			MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System/	Required	Provided	IVIK		
10	Intercom					
10.	Automatic Sprinkler System	27/4	27/4	DT/A		
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling					
11.	Internal Hydrants	27/4	27/1			
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor	27/1				
10	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants					
	1) Total number of hydrants	N/A	N/A	N/A		
12	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement					
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump					
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A		N/A		
	stopping	IN/A	N/A	N/A		
	2) Terrace level					
	a) Discharge of pump	450 7 75 5				
	b) Head of pump	450 LPM	450 LPM	MR		
	7	30 mtr.	30 mtr.	MR		
	c) Power supply	Required	Provided	MR		

	NM					
	d) Auto starting of pump	Required	Provided	MR		
14.	Captive Water Storage for Fire Fighting					
	capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.	1				
	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection Syst Risk, if any:	N/A				

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2019/228 dated 29/01/19, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name:- Rajinder Atwal

Name: - Ravinder Singh Designation: - ADO (CC)

Designation:-DO (CD)

Servi

pporon por putub for Kus penuso