

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No.F.6/DFS/MS/Mercantile/2022/SZ/ 53 <u>FIRE SAFETY CERTIFICATE</u>

Dated: 07/02/2022

Certified that the Mercantile Building located at A-2/41, Najafgarh Road, Rajouri Garden, New Delhi-110027, comprised of basement, stilt, ground plus three upper floors, owned/occupied by Rakesh Suri have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of this department on 31/01/2022 in the presence of Sh. Rakesh Suri and found that the building is fit for occupancy Group "Mercantile Building" with effect from c_{10}/c_{10

Issued on 0.7.62/2022 at New Delhi by

Delhi Fire Service

OLC

To,

The Manager, A-2/41, Najafgarh Road, Rajouri Garden, New Delhi-110027.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <u>www.dfs.delhigovt.nic.in</u>.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry

N/6

		A-2/41, Najafgarh Road	i, Rajouri			
G	arden, New Delhi-11	0027.				
Building is comprised of Basement, stilt, ground plus three upper floors						
. Type of Occupancy : M	Aercantile building					
. Type of Case : N	New					
. Details of Previous FSC : N						
			-			
. Fire Safety directives letter no. : F	6/DFS/MS/BP/2020/	56 dated 10/02/2020				
. Date of Inspection : 31	/01/2022					
. Name of the Inspecting officers : A	DO R.K.Yadav & D	CFO Sunil Chawdhary				
. Name and designation of						
Officer from the building side : S	Sh. Rakesh Suri					
	2020 Dutdoor diary no. 593	4 dated 24/01/2022				
	-		Domostro			
N Minimum Standards on fire O prevention and fire safety U/R33	Requirement	Provided at Site	Remarks			
Access to building						
Road width	09 m	61 m	MR			
Gate width	5.0 m	5.0 m	MR			
• Width of internal road	N/A	N/A	N/A			
2 Number, Width, Type and Arrange	ment of Exits					
a. Number of Staircases	2 Nos.	2 Nos.	MR			
Upper Floor	2 Nos. 2 Nos.	2 Nos.	MR			
Basement B. Width of Staircases	2 1103.	21(03.				
Upper Floor	1.5 m each	1.5 m each	MR			
• Basement	1.5 m each	1.5 m each	MR			
c. Protection of exits						
Fire check door	Required	Provided	MR			
 Pressurization d. No. of continuous staircases to 	N/A	N/A	N/A			
d. No. of continuous staticases to terrace	2 Nos.	2 Nos.	MR			
e. Width of Corridor	N/A	N/A	N/A			
f. Door Size	N/A	N/A	N/A			
Compartmentation.						
Fire check door	Required	Provided	MR			
 Sealing of electrical shafts 	Required	Sealed N/A	MR N/A			
 Fire rating of shaft door 	<u>N/A</u> N/A	N/A N/A	N/A N/A			
• Water curtain	N/A N/A	N/A N/A	N/A			
Fire Dampers						
Smoke Management System.	Required	Provided	MR			
- Decement	Required	Natural	MR			
 Basement Upper floor 	1					
Upper floor	1					
		20 11	MD			
Upper floor	20 Nos. ABC & Co2	20 Nos. ABC & Co2	MR MR			

6	First-aid-Hose Reels.					
1(Total numbers of each floor	1 Nos.	Provided	MD		
	 Length of hose reel hose 	30 M		MR		
	Nozzle diameter		Provided	MR		
7		5 MM	Provided	MR		
/	Automatic fire detection and alarming system.					
	• Type of detectors	N/A	N/A	N/A		
17	 Location of main panel 	N/A	N/A	N/A		
18	 Location of repeater panel 	N/A	N/A	N/A		
	• Alternate source of power	Required	Provided	MR		
19	Hooter's location	N/A	N/A	N/A		
-8	MOEFA	Required	Provided	MR		
<u> </u>	Public address System.	N/A	N/A	N/A		
—10	Automatic Sprinkler System.					
	Basement/Stilt	Required	Provided	MR		
	• upper floor	N/A	N/A	N/A		
	sprinkler above false ceiling	N/A	N/A	N/A N/A		
20 11	Internal Hydrants	11/2 X	11/21	11/11		
The	• size of riser/down-comer	150 mm	Provided	MR		
ime	• Number of hydrants per floor	1 Nos.	Provided	MR		
ate	Hose Box	01 No	Provided	MR		
12	Yard Hydrants.					
Keef	Total number of hydrants	N/A	N/A	N/A		
nde	Hose Box	N/A N/A	N/A	N/A		
Serv 13	Pumping Arrangements.		1071			
	Ground Level					
	Discharge of main Pump	2280 LPM	Provided	MR		
	> Head of Main Pump	60 M	Provided	MR		
	Number of main pumps	1 no.	Provided	MR		
	Jockey pump out put	180 LPM	Provided	MR		
	Jockey pump head	60 M	Provided	MR		
۰ ۲	Standby pump out put	2280 LPM	Provided	MR		
I]	Standby pump Head	60 M	Provided	MR		
1	Auto Starting /Manual stopping	Required	Provided	MR		
	 Pump House Access 	Required	Provided	MR		
	Terrace Level each block					
	 Discharge of pump 	900 & 450 LPM	Provided	MR		
	> Head of the Pump	40 M	Provided	MR		
	> Power supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	2,00,000 ltrs	Provided	MR		
	Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	Required	Provided	MR		
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	10,000 Ltrs	10,000 Ltrs	MR		
15	Exit Signage.	Required	Provided	MR		

-1

N	1	8
	·	-

16	Provision of Lifts. Not Installed			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication in lift car	Required	Provided	MR
	• Firemen's grounding switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	Detector system panel	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	Required	LT & HT panel provided	MR

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings was issued vide letter no.F.6/DFS/MS/Mercantile/2022/SZ/167 dated 18/01/2022 has been complied.

Keeping in view of the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name : R.K.Yadav Designation:- ADO (JKP)

5

Signature of the Inspecting Office Name : Sunil Chawdhary Designation:- DCFO (SZ)

F.J. C.

þ

И

C.F.O. €.

Di