6-49

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

## No.F6/DFS/MS/GH/2022/ ND2- 98 FIRE SAFETY CERTIFICATE

Dated :- 09/02/2022

Certified that the Mahajan Palace located at 10830, Jhandewalan Road, Chowk Motia Khan, Karol Bagh, New Delhi comprised of Ground + Mezzanine + 03 Upper floors, Ground floor (03 guest rooms + Reception), Mezzanine floor (03 guest rooms),  $1^{st}$  floor to  $2^{nd}$  floor (11 guest rooms at each floor), and  $3^{rd}$  floor (02 guest rooms + Staff kitchen + 01 store room) total 30 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2020/NDZ/25 dated 17/01/20. Now, the premises was re-inspected by the officer concerned of this department on 03/02/2022 in the presence of Mr. Pawan Kumar Mahajan (Owner) and found that the said guest house building comprising of Ground floor (03 guest rooms + Reception), Mezzanine floor (03 guest rooms), 1<sup>st</sup> floor to 2<sup>nd</sup> floor (10 guest rooms & 01 store room at each floor), and having given an undertaking dated 03.02.2022 regarding not use any floor above second floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (03 guest rooms + Reception), Mezzanine floor (03 guest rooms),  $1^{st}$  floor to  $2^{nd}$  floor (10 guest rooms at each floor), total 26 guest rooms with effect from  $\frac{27}{02}/2021$  for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -----at New Delhi by.

(F) 912122

(**Dr. S.K. Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1

- 1. The Commissioner, North MCD, Civic Centre, New Delhi : to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID no. 2022011100630 dated 21.01.2022.
- The Manager, Mahajan Palace at 10830, Jhandewalan Road, Chowk Motia Khan, Karol Bagh, New Delhi.

## Condition for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

		NII	r				
1.	Name & address of the buil		an Palace located	at 10830			
		Jhande	ewalan Road, Cho	wk Motio Khan			
		r ai oi	Bagh New Dolh;				
		Gr. + Mezzan	ine + 02 Upper floors	s (total 26 Guest m			
		- · · · · · · · ·	noor top guest rooms	+ Recention)			
		Mezzan	ine floor (03 guest roo	oms), 1st floor to 2nd			
	Mezzanine floor (03 guest rooms), 1 <sup>st</sup> floor to 2 <sup>nd</sup> (10 guest rooms at each floor) & 3 <sup>rd floor</sup> /terrace fl						
3.	Type of case:- not in use as per affidavit dated 03.02.2022 Renewal						
4.	Acone way						
	No. F6/DFS/MS/GH/2020/NDZ/25dated 17/01/20.						
5.	Fire safety directives No	N/A	20.				
6.	Date of inspection:-	03/02/2	2022				
7.	Name of the inspecting office		ajinder Atwal (DO				
	1		winder Singh (AD	$(CD) \alpha$			
8.	Name & designation of office	cer	winder Singh (AD	0/00)			
	From the building side:-		awan kumar Maha	ion (Ourmon)			
9.	Year of construction:-	1011.16	wall Kulliar Walla	jan (Owner)			
10.	Applicant's letter No:-	ID no. 20	22011100630 dated 2	01 01 2022			
			22011100050 ualeu 2	Old Case			
S.No.	Minimum Standards on fire	Requireme	nt/ Provided at a				
	Prevention and fire safety	Existing fir		MR/NMF			
	U/R 33	safety					
		arrangemen	nts				
1.	Access to Building						
	1) Road width	N/A	10 mtr.	N/A			
	2) Gate width	N/A	N/A	N/A N/A			
	3)Width of internal road	N/A	N/A N/A				
2.	Number, Width Type & An	rangement of	IN/A Evita	N/A			
	A. Number of staircases						
	1. Upper floors	01 Nos.	01 Nos.				
	2. Basements	N/A	N/A	MR			
	B. Width of staircase			N/A			
	1. Upper floors	0.80 mtr.	1.23 Mtr.	MR			
	2. Basements	N/A	N/A				
	C. Protection of exits			N/A			
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A N/A			
	D. No. of continuous	01	01	MR			
	staircase to terrace			TATIC			
	E. Width of corridor	1.25	1.25 mtr.	MR			
	F. Door size	01 mtr.	01 mtr.	MR			
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A N/A			
	4) Water curtain	N/A	N/A	N/A N/A			
	5) Fire Dampers	N/A	N/A	N/A N/A			
4.	Smoke Management System			11/11			
	1) Basements	30 ACPH	N/A	N/A			
	2) Upper floors	12 a/c per	Natural/exhaust	MR			
	I	hour					
	Eine E die in	noui					
5.	Fire Extinguishers						
5.	1) Total numbers	12 ABC & CO2	12	MR			

,

## N116

	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel					
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors CO	Required	Provided	MR		
	2) Location of main panel	Gr. Floor	Provided	MR		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	Required	Provided	MR		
	5) Hooter's Location	Ground floor	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System			IN/A		
	1) Basement	N/A	N/A			
	2) Upper floors	N/A	N/A N/A	N/A		
	3) Sprinkler above false	N/A	N/A N/A	N/A		
	ceiling	IN/A	IN/A	N/A		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A			
	2) Number of hydrants per	N/A	N/A N/A	N/A		
	floor	IN/A	IN/A	N/A		
	3) Hose box	N/A	N/A			
12.	Yard Hydrants	IN/A	IN/A	N/A		
	1) Total number of hydrants	N/A	NI/A			
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement		N/A	N/A		
	1) Ground level					
	a) Discharge of main	N/A N/A	N/A	N/A		
	pump	IN/A	N/A	N/A		
	b) Head of main pump	N/A				
	c) Number of main pump	N/A N/A	N/A	N/A		
	d) Jockey pump out put	N/A N/A	N/A	N/A		
	e) Jockey pump bead		N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
		N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping					
	2) Terrace level					
	a) Discharge of pump	450 LPM	450 LPM	MR		
	b) Head of pump	30 mtr.	30 mtr.	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
4.	Captive Water Storage for Fi	re Fighting		1711		
	1) Under ground tank	N/A	N/A	N/A		
	capacity			IN/A		
	a) Draw-off connection	N/A	N/A			
	b) Fire service inlet	N/A		N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank		N/A	N/A		
	capacity	5,000 ltr.	5,000 ltr.	MR		
5.	Exit Signage.	Required				
	NICHARD.	Kennired	Provided	MR		

11

16.	Provision of Lifts.				
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System for Protection of special Risk, if any:				

NIIZ

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2020/NDZ/25 dated 17/01/20, renewal under Rule 35 of the Delhi Fire Service Rules 2010, is recommended up to second floor only .

Signature of the Inspecting Officer

1222

Name :- Rajinder Atwal Designation :- DO (CD)

Name :- Ravinder Singh

Designation :- ADO (CC)

Signature of the Inspecting Officer

sommed pri pertup for Kas per

62 Choz

12020 Com

I flease

MS

ADOR