GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 95

Dated: 05/02/22

FIRE SAFETY CERTIFICATE

Certified that the Noble Inn Guest House located at 90, Krishna Gali, Pahar Gani, New Delhi comprised of Ground + 04 Upper floors, Ground floor (04 guest rooms + Reception), 1st floor to 4th floor (06 guest rooms at each floor), total 28 guest rooms owned/occupied by Noble Inn Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/2080 dated 12/09/18. Now, the premise was re-inspected by the officer concerned of this department on 04/02/22 in the presence of Mr. Puneet (Manager) and found that the said guest house building having given an undertaking dated 04.02.2022 regarding not to use fourth floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (04 guest rooms + Reception), 1st floor to 3rd floor (06 guest rooms at each floor) total -22 guest rooms up to third floor only with effect from - 49-1-02-1-2--- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below. Issued -09/02/92-at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above and deviation in building if any.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. 2022012801302 dated 28.01.22.
- 3. The Manager,

Noble Inn Guest House at 88-91, Krishna Gali, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 20.12.2021, latest by 31.03.2022
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. Further, earlier FSC was issued at the address 89-91 Krishana Gali Pahargani, New Delhi
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

21

INSPECTION REPORT

Noble Inn Guest House at 90, Krishna 1. Name & address of the building

Gali, Pahar Ganj, New Delhi Residential, Sub Division-A-1

Gr. + 04 Upper floors (total **13** Guest rooms) Ground floor (04 guest rooms + Reception), 1st floor to 3rd floor (06 guest rooms at each floor) and fourth floor not in use as per undertaking dated

04.02.22 Renewal

3. Type of case:-4. Details of previous FSC:-

No. F6/DFS/MS/GH/2018/NDZ/2080 dated

12/09/18.

5. Fire safety directives No.-

N/A

6. Date of inspection:-

2. Type of occupancy:-

04/02/22

7. Name of the inspecting officer:-

8. Name & designation of officer

Sh. Ravinder Singh (ADO/CC)

From the building side:-9. Year of construction:-

Sh. Puneet (Manager)

10. Applicant's letter No:-

ID no. 2022012801302 dated 28.01.22.

10.	Applicant's letter 140	15 1101 2022		Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	03 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr			
2.	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	1.50 mtr. except of 1 step of 1.25 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1.0 mtr.	1.0 mtr.	MR
3.	Compartmentation			
_	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	Required as	Not provided	Last dt. 31.03.22 of

5.	Fine Factor and A	per G.N dated 27.05.19		complian extended vide order dt. 20.12.2021
	Fire Extinguishers			
	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &		em	
	1) Type of detectors Co type	Required	Provided	MR
	2) Location of main panel	Gr. floor	Provided	MR
	3) Location of repeater panel	Required	Provided	MR
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	At each floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	•		
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling		1,111	
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		•	
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			-
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR

4.	Captive Water Storage for F	ire Fighting	NI/A	N/A
	Under ground tank capacity	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	5000 ltr.	5000 ltr.	MR
	capacity	Required	Provided	MR
15.	Exit Signage.	Required		
16.	Provision of Lifts. a) Pressurization of lift	N/A	N/A	N/A
	b) Pressurization of lift	N/A	N/A	N/A
	c) Communication in	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
10.	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Further, earlier FSC was issued at the address 89-91 Krishana Gali Paharganj , New Delhi, now the address is 90 Krishana Gali Paharganj, New Delhi as per online application form.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/2080 dated 12/09/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

Leposture Please.

Leposture Please.

Leposture Please.

Liptor Control Properties of the Porter Period Properties of the Properties of th