

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/School/2022/ \\

Dated: 03 /03 /2022

FIRE SAFETY CERTIFICATE

Certified that the O.P Suri Memorial Education Society (The Srijan School) located at Plot No. 4B, North Model Town, Delhi-110009 comprised of Ground and 04 upper floors only owned/occupied by O.P Suri Memorial Education Society was issued Fire Safety Certificated vide this office letter no. F-6/DFS/MS/2017/1696 dated 23.11.2017. The premise was re-inspected by the officer concerned of this department on 24.01.2022 in the presence of Sh. Devashish Tiwari (Admin. Officer) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition there is premise additional alteration running of offices & library at fourth floor. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from O. 2. 1021 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on .03 02 2022 at New Delhi

Director

Ph:-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Principal, O.P Suri Memorial Education Society (The Srijan School) located at Plot No. 4B, North Model Town, Delhi-110009.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available or http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

: O.P Suri Memorial Education Society (The Srijan School) at

Plot no. 4B, North Model Town, Delhi-110009.

2. Composition of building

: Ground and 04 upper floors

3. Type of Occupancy

: Educational

4. Type of Case

: Add/Alt

5. Details of previous NOC

: F6/DFS/MS/2017/1696 Dated 23.11.2017

6. Fire Safety directives letter No

: F6/DFS/MS/BP/2014/337 Dated 18/12/2014

7. Date of inspection

: 24.01.2022

8. Name of the Inspecting Officers : ADO (RN) 9. Name and designation of officers

From the building side

: Sh. Devashish Tiwari/ Admin. Officer

10. Year of Construction

: 2015-16

11. Applicant's letter No.

: Online E-mail I.D Dated 24.12.2021

1	Minimum Standards on fire prevention fire safety U/R 33 Access to building	on and NBC Requirement	Provided at site	Remarks MR/NMR			
	Road width						
	• Gate width	12m	24m	MR			
	Width of internal road	4.5m	5m	MR			
2	Number, Width Type 8 A	6m	6m	MR			
	Number, Width, Type & Arrangement of a. Number of staircases	of Exits					
	Upper Floors	03	03	MR			
	Basements	NA	NA				
	b. Width of staircases		IIA	NA			
	 Upper Floors 	1.50m	1.50				
			1.50m	MR			
	Basements	NA	NA	NA			
	c. Protection of exits						
	 Fire check door 	Required	Provided				
	 Pressurization 		riovided	MR			
		NA	NA	NA			
	d. No. of continuous staircases to terrace	01	01				
e. Wi <mark>d</mark> th of Corridor		NA		MR			
1	f. Door Size		NA	NA			
(Compartmentation.	1.0m & 1.5m for offices	Provided	MR			
-	• Fire check door						
	Sealing of electrical shafts	Required	Provided	MR			
	• Fire Rating of shaft door	Required	Provided	MR			
	• Water Curtain	01 hrs	Provided	MR			
	• Fire Dampers	NA	NA	NA			
		NA ·	NA	NA			
Sn	noke Management System.						
	Basements						
	 Upper floors 	30 a/c per hour	No basement	NA			
	Fire Extinguishers	12 a/c per hour	Open window	MR			



	Total numbers	30no	30nos	MR		
	• Types	ABC/Co2	ABC-30	MR		
	ISI marking	Yes	Yes	MR		
	First-Aid Hose Reels.					
	Total numbers on each floor	03	03 Provided	MR		
	Length of hose reel hose	30m	30m Provided	MR		
	Nozzle diameter	5mm	5mm Provided	MR		
	Automatic fire detection and alarming system					
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA NA	NA		
		NA	NA	NA		
	Location of Repeater Panel	INA				
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
	MOEFA	Required	Provided	MR		
	Public Address System.	NA .	Provided	NA		
0	Automatic Sprinkler System.			NT 4		
	Basement	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
1	Internal Hydrants					
	• Size of riser/down-comer	100mm	Provided	MR		
	Number of hydrants per floor	03	03	MR		
	Hose Box	Required	Provided	MR		
2	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
3	Pumping Arrangements.					
	Ground Level					
	> Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A			
	> Jockey pump head	N/A N/A	N/A N/A	N/A		
	Standby Pump out put		IN/A	N/A		
	> Standby Pump Head	· N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	• Terrace level 900 lpm 900 lpm					
	> Discharge of pump	40m	40m	MR		
	➤ Head of the pump	Required	Provided	MR		
	> Power Supply	Required	Provided	MR		
	 Auto Starting of pump 	Required	riovided	MR		
4	Captive Water Storage for fire fighting.					
	Underground tank capacity	NA .	NA	NA		
	> Draw-off connection	NA	NA	NA		
	> Fire service inlet	NA	NA			
	Access to tank	NA	NA	NA NA		
		Jøp		NA		
		T		4		

	Overhead Tank capacity	25,000ltrs	Provided	MR			
15	Exit Signage.	Required	Provided	MR			
10	Provision of Lifts.						
	Pressurization of Lift Shaft Pressurization of Lift Shaft	Required	Provided	MR			
	ressarization of Lift lobby	Required	Provided	MR			
	 Communication In lift Car Fireman's Grounding Switch 	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17		Required	Provided	MR			
18	Standby power supply	Required	Provided	MR			
	Refuge Area.						
	Total AreaLocation	N/A	N/A	N/A			
19	Fire Control Room	N/A	N/A	N/A			
	Detector System Panel	Required	Ground floor	MR			
	• Flow Switch Panel	Required	Ground floor	MR			
	PA System Panel Batter backup	Required	Ground floor	MR			
20	Dance backup	Required	Ground floor	MR			
	Danding Floor Plans	Required	Ground floor	MR			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 70 dated 17.02.2021

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated in NBC Part 4, it is recommended to grant Fire Safety Certificate Signature

Der

Mark un wegelth

The state of the service of the s

Signature of the Inspecting Officer

Name :-C.L. Meena Designation:- ADO/RN

Spoken

three stain case having wielth 1:5mtr. eater

approved by this outhant wild letter NO. 199

detail 11/06/2020 at C-88

resubmitted P1.

Test/01/2022