GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2022/SZ / 192

Dated: 18/02/22

FIRE SAFETY CERTIFICATE

Certified that the D.D. Gyan Jyoti Public School running at ground floor only in a building comprised of ground plus two upper floors located at RZ-R-51-52, Chanakya Place Part-II, New Delhi-110059, owned/occupied by D.D. Gyan Jyoti Public School was issued FSC by this department vide letter No F.6/DFS/MS/School/2016/SZ/1841 dated 26.12.2016. The premises was re- inspected by the officer concerned of this department on 07/02/2022 in the presence of Sh. Rajinder Gambhir and found that School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (ground floor only) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

Ton s

Copy to:-

- The Principal,
 D.D. Gyan Jyoti Public School, RZ-R-51-52,
 Chanakya Place Part-II, New Delhi-110059.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: D.D. Gyan Jyoti Public School, RZ-R-51-52, Chanakya Place Part-II,

New Delhi-110059

2. Building comprised of : G+2 But school running at ground floor only

3. Type of Occupancy : Educational
4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2016/SZ/1841 dated 26.12.2016 (For GF Only)
6. Fire Safety directives letter No : F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection : 07/02/2022

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Rajinder Gambhir (Manager)

10. Year of Construction : 2006 to 2008 (GF, FF) & 2019 (SF 2 rooms)

11. Applicant's letter No. : Nil dated 24/01/2022

S. No.		m Standards on fire prevention and ety U/R 33	Requirements	Provided at site	Remarks MR/NMR			
	Access to building							
	•	Road width	Accessible 06 mtrs	Provided	M/R			
	•	Gate width	4.5 mtrs N/A	2.4 mtrs. N/A	M/R, being old case N/A			
2.	Numbe	Width of internal road r, Width, Type & Arrangement of Exits						
	a. Nun	iber of staircases						
	•	Upper Floors	01 No.'s	02 No.'s	M/R			
	•	Basements	N/A	N/A	N/A			
	b. Wid	th of staircases	1.50 &.75m	1.13 m & 1.14m	M/R			
	•	Upper Floor	N/A	N/A	N/A			
	•	Basements	N/A	IN/A	IN/A			
	c. Pro	tection of exits	N/A	N/A	N/A			
	•	Fire check door	N/A	N/A	N/A			
	•	Pressurization						
	1 31	-f time and ataimagasa to	Required	Provided	M/R			
		o. of continuous staircases to	N/A	N/A	N/A .			
	e. W	idth of Corridor ass room Door Size	Old case	.85 to 1.02 cms	MR being old case			
3.	Comp	partmentation						
	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A			
		Fire Rating of shaft door Water Curtain	N/A	N/A	N/A			
		Fire Dampers	N/A	N/A	N/A			
4	C	•	N/A	N/A	N/A			
4.	Smok	Re Management System Basements	N/A	N/A	N/A			
		Upper floors	N/A	N/A	N/A			
_	7.							
5.	Fire	Extinguishers	04 no's	D i I I				
		Total numbers Types	04 no's ABC/CO ₂ type	Provided Provided	M/R M/R			
		IS marking						
			ISI marked	Provided	M/R			

6.	First-Aid Hose Reels					
-	Total numbers on each floor	N/A	N/A	N/A		
	 Length of hose reel hose 	N/A	N/A	N/A		
	Nozzle diameter	N/A	N/A	N/A		
7.	Automatic fire detection and alarming system					
/•	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A				
	Alternate source of power	N/A	N/A N/A	N/A		
	Hooters' Location	N/A	N/A N/A	N/A		
8.	MOEFA	N/A	N/A N/A	N/A N/A		
9,	Public Address System	N/A N/A	N/A	N/A		
10.	Automatic Sprinkler System	14/74	IVA	IV/A		
	Basement	N/A	N/A	N/A		
	Ground Floor	N/A	· N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants	14/11	11/7	111/73		
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A				
	Jockey Pump out putJockey pump head		N/A	N/A		
	Jockey pump headStandby Pump out put	N/A	. N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A		
	· · · · · · · · · · · · · · · · · · ·	N/A	N/A	N/A		
		N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A N/A		
	Terrace level			IV/A		
	Discharge of pump	N/A	NT/A			
	➤ Head of the pump	N/A	N/A	N/A		
	➤ Power Supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
		IN/A	N/A	N/A		
	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A				
	> Access to tank	N/A	N/A	N/A		
		I IN/A	N/A	N/A		
	 Overhead Tank capacity 			IN/A		
	Overhead Tank capacity Exit Signage.	N/A N/A	N/A	N/A		

			No Lift					
16.	Provisio	on of Lifts.	N/A	N/A	N/A			
10.	•	Pressurization of Lift Shaft	N/A	N/Λ	N/A			
	•	Pressurization of Lift lobby	N/A N/A	N/A	N/A			
	•	Communication In lift Car		N/Λ	N/A			
	•	Fireman's Grounding Switch	N/A					
	•	Lift Signage	N/A	N/A	N/A			
			N/A	N/A	N/A			
17.	Standb	power supply	,					
18.	Refuge	Total Area	N/A	N/A	N/A			
	A A	Location	27/4	N/A	N/A			
		Cocation	N/A	14/74				
19.	Fire Co	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A			
	•	Flow Switch Panel	N/A	N/A	N/A			
		PA System Panel	N/A	N/A	N/A			
		Battery backup	•	N/A	N/A			
		Building Floor Plans	N/A					
		2	N/A	N/A	N/A			
	Special	Fire Protection System for Protection of	N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection.

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC was issued vide letter no. F.6/DFS/MS/School/2016/SZ/1841 dated 26.12.2016 renewal in accordance with the circular no. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- Earlier FSC was issued vide letter no. F.6/DFS/MS/School/2016/SZ/1841 dated 26.12.2016 for ground floor only in a building comprised of ground plus two upper floor but the school running at ground floor only first floor for official purpose and two rooms at second floor used as storage purpose and there are less than 45 students in each class room as per undertaking submitted by the manager (placed C-13).

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

)

w alabora

900 (SKP)