C-87



# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/\\3

## FIRE SAFETY CERTIFICATE

Dated: 21 | 02 | 2022

Certified that the Jyoti Mahal Guest House located at 2488-90 & 1507, Nalwa Gali and Ranjit Gali, Pahar Ganj, New Delhi comprised of Basement + Ground + 03 Upper floors, Basement (storage), Ground floor (reception + lobby + office + 01 hall + 04 guest rooms), 1st floor (11 guest rooms + 01 store), 2nd & 3rd floor (12 guest rooms + 01 store at each floor), total 39 guest rooms owned/occupied by Jyoti Mahal Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/2575 dated 12/12/18. Now, the premises was re-inspected by the officer concerned of this department on 17/02/22 in the presence of Sh. Jasbir Singh and found that the said guest house building having given an affidavit dated 27.11.2019 regarding not to use kitchen for staff (sealed) at terrace floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (reception + office + 04 guest rooms), 1st floor (11 guest rooms), 2nd & 3rd floor (12 guest rooms) Total-39 guest rooms upto third floor only with effect from 21 2022 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued  $\frac{9102}{2000}$   $\frac{22}{200}$  at New Delhi by.

(**Dr. S.K.Tomar**) Dy. Chief Fire Officer Delhi Fire Service

### Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi ID no. 20220118000941 dated 18.01.22 email gurjeet1818@gamil.com dated 14.02.2022.
- 3. The Manger, Jyoti Mahal Guest House at 2488-90 & 1507, Nalwa Gali and Ranjit Gali, Pahar Ganj, New Delhi.

#### Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 20.12.2021, latest by 31.03.2022
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

1/20

## **INSPECTION REPORT**

1. Name & address of the building:-Jyoti Mahal Guest House at 2488-90 & 1507,

Nalwa Gali and Ranjit Gali, Pahar Ganj, New Delhi

2. Type of occupancy:-Residential, Sub Division-A-1

B + Gr. + 03 Upper floors (total 39 Guest rooms).

basement (storage)

Ground floor (reception + 04 guest rooms), 1st floor(11 Room+01 store), 2<sup>nd</sup> to 3<sup>rd</sup> (12 guest rooms & 01 store at each floor), terrace floor- staff kitchen sealed

and not in use as per affidavit dated 27.11.2019

3. Type of case:-Renewal

No. F6/DFS/MS/GH/2018/NDZ/2675 dated 4. Details of previous FSC:-

N/A

12/12/18.

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

17/02/22 Sh. Ravinder Singh (ADO/CC)

Sh. Jasbir Singh

2007

ID no. 20220118000941 dated 18.01.22 email gurjeet1818@gamil.com dated 14.02.2022

				Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	06 mtr	06 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr			
	A. Number of staircases			
	1. Upper floors	02 Nos.	02 Nos.	MR
	2. Basements	01 Nos.	02 Nos.	MR
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	1.25 & 1.28 mtr.	MR
	2. Basements	0.80 mtr.	1.48 & 0.78 mtr.	MR
	C. Protection of exits			
	1. Fire check door	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	0.90 mtr.	0.90 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			



	1) Basements		30 ACPH		Exhaust		N	IR
	2) Upper floors		12 a/c per	•	Natural Ventilation	on	N	1R
			hour					
5.	Fire Extinguishers							
	1) Total numbers		18 Nos.		18 Nos.			IR
	2) Types		ABC & C	O2	ABC & CO2			R
	3) ISI marking		Required		Provided		M	R
6.	First-Aid Hose Reel							
	1) Total number of eachflo		02		02		M	
	2) Length of hose reel hos	e	30 m		30 m		M	
	3) Nozzle diameter		05 mm		05 mm		M	R
7.	<b>Automatic Fire Detection</b>	1 &	Alarming S	yste				
	1) Type of detectors CO		Required as per G.N date 27.05.19		Not provided		31. cor ext ord	st dt. .03.22 of npliance ended vide ler dt. 12.2021
	2) Location of main panel		N/A		N/A		V.	
	3) Location of repeater pan	el	N/A		N/A	_	V/	
	4) Alternate source of power	er	N/A		N/A		V/	
	5) Hooter's Location		N/A	_	N/A	$\rightarrow$	V/A	
8.	MOEFA		Required	_	Provided	_	/F	
9	Public Address System		Required	$\overline{}$	Provided		/R	
10.	Automatic Sprinkler Syste	em				1	T	
	1) Basement		Required	]	Provided	N	1R	
	2) Upper floors		N/A	1	V/A	_	I/A	
	3) Sprinkler above false	]	N/A	1	N/A		VA	
	ceiling							•
1.	Internal Hydrants					$\top$	t	
	1) Size of riser/down-comer	1	N/A	N	J/A	N	ľΑ	
	2) Number of hydrants per	1	V/A	_	J/A		/A	
	floor					^ `	1.	
	3) Hose box	N	V/A	N	I/A	N	/A	
	Yard Hydrants				··	14	Ω	
	1) Total number of hydrants	N	J/A	N	I/A	N	A	
	2) Hose box	N	J/A	_	//A	N		
	Pumping Arrangement	Ť		+-		14	A	
	<ol> <li>Ground level</li> </ol>	N	/A	N	/A	) I	/ 4	
	a) Discharge of main	_	/A	_	/A		/A	
	pump			1	A	IN	/A	
	b) Head of main pump	N/	'A	N	/A	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	/ 4	
	c) Number of main	N/		_	A A		/Α	
	pump	^ "	**	111/	A	N	/A	
	d) Jockey pump out put	N/	Δ	N/	/ A			
	e) Jockey pump head	N/		_		N		
	f) Stand by pump	N/A		N/		N		
	output	11/1	A	N/	A	N	Ά	
	g) Stand by pump head	) T/						
-	h) Auto	N/A		N/		N	Ά	
	,	N/A	A	N/	Α	N		
	starting/Manual					- 1	- 1	
_	stopping 2) Terrace level							
				1		- 1		

20.	Special Fire Protection Syste Risk, if any:	m for Protect	ion of special	extinguisher from provided near
	e) Building floor plan	N/A	N/A	N/A One Co <sub>2</sub> type fire
	d) Battery backup	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
	e) Lift signage	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	c) Communication in lift	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	<ul> <li>a) Pressurization of lift shaft</li> </ul>	N/A	N/A	N/A
16.	Provision of Lifts.			
15.	Exit Signage.	Required	Provided	MR
	capacity			
	c) Access to tank d) Over head tank	5,000 ltr.	5,000 ltr.	MR
	b) Fire service inlet	N/A N/A	N/A N/A	N/A N/A
	a) Draw-off connection	N/A	N/A	N/A
	Under ground tank capacity	N/A	N/A	N/A
14.	Captive Water Storage for F			
	d) Auto starting of pump	Required	Provided	MR
	c) Power supply	Required	Provided	MR
	b) Head of pump	30 mtr	30 mtr	MR
	a) Discharge of pump	450 LPM	450 LPM	MR

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/2675 dated 12/12/2018 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only .

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

MR

MRMRMR

MRMR

Ventilation

Acomposition Please . A.

MS