

FORM 'H'
FORM FOR ISSUING FIRE SAFETY CERTIFICATE
[Refer sub - rule (1) of rule 35]
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F-6/DFS/MS/SZ/2022/73

Dated: 17/02/2022

FIRE SAFETY CERTIFICATE

Certified that the "School for Physically Challenged " Located at Sector-13,(Near Iskon Temple) Dwarka, New Delhi comprised of Basement + Stilt + 03 Upper Floors Owen and occupied by **Chandra Bhushan Singh Memorial Mahila Bal Evam Shravan Viklang Siksha Evam Punarvas Sansthan** have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officer concerned of this department on 01/02/2022 in the presence of Sh. GB Singh (President) and found that the said building is fit for occupancy class B "Educational building" with effect from 17/02/2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 17/02/2022 at New Delhi by.


(Atul Garg)
Director
Delhi Fire Service

Copy to:

1. Directorate of Education Old Secretariat Delhi – 110054.
2. The Principal "School of Physically Challenged and blind Institute" belonging to Chandra Bhushan Singh Memorial Mahila Bal Evam Shravan Viklang Siksha Evam Punarvas Sansthan, Sector-13,(Near Iskon Temple) Dwarka, New Delhi

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. Basement shall be used as per building bye-laws.
7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: "School of Physically Challenged and blind Institute" belonging to Chandra Bhushan Singh Memorial Mahila Bal Evam Shraavan Viklang Siksha Evam Punarvas Sansthan, Located at Sector-13,(Near Iskon Temple) Dwarka, New Delhi
2. Type of Occupancy : Educational (B +Stilt + 03 Upper Floors)
3. Type of Case : New
4. Details of previous NOC : Nil
5. Fire Safety directives L. No. : F6/DFS/MS/BP/2015/241 Dated 26/08/2015
6. Date of inspection : 01/02/2022
7. Name of the Inspecting Officer :Udai vir Singh, ADO (DWK)
8. Name and designation of Officer

from the building side :Sh. GB Singh (President)

9. Year of Construction : 2015

10. Applicant's letter No. : Email Dated-20/01/2022

Basement & GF = Parking
1st & 2nd Floor= Class room
3rd floor= Vaccant

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	30 mtrs	12 mtr	MR
	• Gate width	4.5mtrs	Provided	MR
	• Width of internal road	NA	NA	NA
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	02 Nos.	Provided	MR
	• Basements	1No & 2 Ramp	Provided	MR
	b. Width of staircases			
	• Upper floors	1.5m,	154cm & 167cm	MR
	• Basements	1.5m & 2 Ramp	169cm & Ramp 2x340cm	MR
	c. Protection of exits			
	• Fire check door	Required	Provided in basement	MR
	• Pressurization	NA	NA	NA
	d. No of continuous staircase to terrace	01 Nos.	Provided	MR
	e. Width Of Corridor	1.5 mtr	Provided	MR
	f. Door Size	1 mtr	1.2m (including door frame)	MR
3.	Compartmentation			
	• Fire check door	Required	Provided in basement	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA

14.	Captive water Storage for fire fighting:			
	• Underground tank capacity	100000ltrs	Provided	MR
	➤ Draw off connection	NA	NA	NA
	➤ Fire service inlet	NA	Provided	NA
	➤ Access to tank	NA	NA	NA
	• Overhead Tank capacity	15,000Ltr	Provided	MR
15.	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	NA	NA	NA
	➤ Pressurization of lift lobby	NA	NA	NA
	➤ Communication in lift Car	Required	Provided	MR
	➤ Fireman's Grounding Switch	Required	Provided	MR
	➤ Lift Signage	Required	Provided	MR
17.	Standby power supply	Required	D.G Set	MR
18.	Refuge Area			
	➤ Total area	NA	NA	NA
	➤ Location	NA	NA	NA
19.	Fire control room			
	➤ Detector system panel	NA	NA	NA
	➤ Flow Switch Panel	NA	NA	NA
	➤ PA System Panel	NA	NA	NA
	➤ Battery backup	NA	NA	NA
	➤ Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	CO2 fire extinguisher provided near electric panel	MR

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers

NIL.....

Signature of the Inspecting Officer
 Name *Vijay V. Singh*
 Designation *ADCP/12014*

ADCP/12014

ADCP/12014
 02/02/2022



ADCP/12014
ADCP/12014
ADCP/12014
 02/02/22

ADCP/12014