GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/EH/SZ/2022/46 Dated 2/.../02/2022

FIRE SAFETY CERTIFICATE

Certified that Ms Aravali Villa located at FH-1, Bandh Road, Khasra No 37/5/1/1, NH-8, Rajokri Samalkha New Delhi -110038 comprised of Ground floor only owned/occupied by Ms Aravali Villa was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2013/SZ/585 dated 19/09/2013. The restaurant premise was re-inspected by the officer concerned of this department on 05/02/2022 in the presence of Sh. Randhir Yadav of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant as above with effect from .21./.0.2/2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 21/02/2022 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

-

- 8M/ 1. The Dy. Health Officer, Najafgarh Zone, Public Health Department, South MCD, Najafgarh Delhi (Ref. MHA Portal ID 2021121928903 dated 20-12-2021)
- 2. Ms Aravali Villa located at FH-1, Bandh Road, Khasra No 37/5/1/1, NH-8, Rajokri Samalkha New Delhi -110038

Conditions for the validity of Fire Safety Certificate: -

- All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire fighting system.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of 5. UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



	INSPECTIO	ON REPORT			
1	Name & Address of the Building	Ms Aravali Villa located at FH-1, Bandh Road,			
		Kh. No 37/5/1/1, NH-8, Rajokri Samalkha Nev			
		Delhi -110038			
2	Type of Occupancy	Assembly 'Group-D'			
3	Building comprised of	Ground Floor Only			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/DFS/MS/EH/	2013/SZ/585 dated 19	/09/2013	
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	05.02.2022			
8	Name of the Inspecting Officers	Rajesh Kumar/ ADO (BCP)			
9	Name & Designation of Officers	Sh. Randhir Yaday			
7	from the building side	On Automit 1995			
10	Year of construction/ date of conversion	2000			
11	Applicant letter No.	MHA Portal ID 2021121928903 dated 20-12-2021			
S. No.	Minimum standards on Fire Prevention	As per old	Provided at Site	Remarks	
	and Fire Safety U/R 33	NOC	Provided at Site	Kemark	
1	Access to Building.				
	Road width	Required 4.5 m	Provided	MR	
	Gate width	NA	NA	-NA-	
	Width of internal road	NA	NA	-NA-	
2	Number, width, type & arrangement of e	xits			
	a. Number of Staircase			NIA	
	 Upper floors 	NA	NA NA	-NA-	
	Basement floor	NA	NA	-NA-	
	b. Width of Staircase	NA	NA	-NA-	
	Upper floors	NA NA	NA NA	-NA-	
	Basement floor Protection of exits	IVA	1174		
	Fire check door	-NA-	NA	-NA-	
	Pressurization	-NA-	NA	-NA-	
	d. No. of continuous staircase to terrace	-NA-	NA	-NA-	
	e. Width of corridor	N/A	N/A	N/A	
	f. Door size	02 exits	Provided	MR	
				(old case	
3	Compartmentation.	27/4	N/A	N/A	
	Fire check door.	N/A N/A	N/A	N/A	
	 Sealing of electrical shafts. 	N/A	N/A	N/A	
	 Fire rating of shaft door. 	N/A	N/A	N/A	
	Water curtain Fire demonstrate	N/A	N/A	N/A	
4	• Fire dampers. Smoke Management system.				
•	Smore Management of the			77/4	
	Basement	N/A	N/A	N/A	
	 Upper floors 	N/A	N/A	N/A	
5	Fire Extinguishers.	08 Nos	08 Provided	MR	
	 Total numbers 	ABC / CO2	ABC & Co2	MR	
	• Types	ISI marked	Provided	MR	
	ISI Marking Park Park	101 marked	. 10 11000	1 2.22	
6	First Aid Hose Reels.	Two	Provided	MR	
	Total numbers on each floor. I would ask age real hose.	30m	Provided	MR	
	Length of hose-reel hose.Nozzle Diameter	5mm	Provided	MR	
7	Automatic fire detection & alarming system.				
'			N1/A	N/A	
	Type of detectors	N/A	N/A	14/73	

	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A		
	Alternate source of power	N/A N/A	N/A	N/A
	 Hoofer's location 	N/A	N/A N/A	N/A N/A
8	MOEFA	Danimi		
9	Public Address System	Required	Provided	MR
	Automatic Sprinkler System	Required	Provided	MR
	Basement	-NA-	NA	-NA-
	• Upper floors	-NA-	NA	-NA-
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	Size of Riser/Down-comer	100mm	100mm	MR
	Number of Hydrant per floor	02	03	MR
	 Hose box. 	02	03	MR
12	Yard Hydrants.			
	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.			
	Ground Level			
-		-NA-	-NA-	-NA-
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.Jockey Pump output.	-NA-	-NA-	-NA-
	> Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	N/A	-NA-	-NA-
	> Standby Pump head.	N/A	-NA-	-NA-
	Auto Starting / Manual Stopping.Pump House Access	-NA-	-NA-	-NA-
	- Tunip House House	-NA-	-NA-	-NA-
-	Terrace Level	450 1 774	D :111	1.00
	Discharge of pump.	450 LPM 35 m	Provided Provided	MR MR
	Head of pump.Power supply.	Required	Provided	M/R
	> Auto starting of pump.	Required	Provided	M/R
14	Captive water storage for Fire Fighting.	•		
	Underground tank capacity.	-NA-	-NA-	-NA-
	> Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	Required	Provided	M/R
	Access to tank.Overhead tank capacity.	-NA-	-NA-	-NA-
15	Exit Signage.	10,00 ltrs	10,000 ltrs	MR MR
		Required	Provided	MK
16	Provision of Lifts.			274
	Pressurization of lift shaft.	-NA-	-NA- -NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage. Standby Power Supply			_
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
-+	Total area	-NA-	-NA-	-NA-

	• Location	-NA-	-NA-	-NA-
19	Fire Control Room.			
	Detector System Panel.	-NA-	-NA-	-NA-
	Flow Switch Panel.	-NA-	-NA-	-NA-
	PA system Panel.	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA-
	Building floor plan	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any:	-NA-	-NA-	-NA-

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

It is submitted that during the course of visit it is observed that an overhead high voltage electric service line is passing just above the existing Restaurant which have already been issued with Fire Safety Certificate, having a vertical distance of 18 appx (Distance certificate is endorsed at opposite of file). The minimum vertical distance permitted in NBC Part III is 3.7m vertical.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2013/SZ/585 dated 19/09/2013, renewal under rule 35(6) of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Rajesh Kumar Designation: ADO / BCP

DO (SD)

B(P)
As approved, F.T. lettre et fort up for
me sagnature PI
11.