



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ 130

Dated: 02/03/2022

## **FIRE SAFETY CERTIFICATE**

Certified that the Basant Guest House located at 5611, Basant Road, Pahar Ganj, New Delhi comprised of Ground + 03 upper floor, Ground floor (Reception + 05 guest rooms), 1st floor (05 guest rooms + 01 office), 2nd floor (04 guest rooms + 01 store rooms + 01 manager room), 3rd floor (05 guest rooms + 01 store room + 01 servant room), total 19 guest rooms owned/occupied by Basant Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2019/NDZ/390 dated 13/02/2019. Now, the premises was re-inspected by the officer concerned of this department on 24/02/22 in the presence of Sh. Jagjeet Singh and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 05 guest rooms), 1st floor (06 guest rooms), 2nd floor (04 guest rooms), 3rd floor (04 guest rooms) Total- 19 guest rooms only with effect from -02-102-1022-for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 02/03/2022 at New Delhi by.

(Dr. S.K.Tomar)
Dy. Chief Fire Officer
Pelhi Fire Service

## Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. 2022020901921 dated 10/02/2022.
- 3. The Manager,

Basant Guest House at 5611, Basant Road, Pahar Ganj, New Delhi.

## Condition for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

	H 114					
	INSP	ECTION REPO	RT			
1. 1	Name & address of the building	Basant Gue	st House at 5611 I	200001		
	1. Name & address of the building  Basant Guest House at 5611, Ba Pahar Ganj, New Delhi					
2.	Гуре of occupancy:-	Residential, Sub Division-A-1				
		apper floor, total 19 guest rooms				
		Ground floor	(Reception + 05 guest	rooms) 1 <sup>st</sup> floor		
		Ground floor (Reception + 05 guest rooms), 1 <sup>st</sup> floor (06 guest rooms), 2 <sup>nd</sup> floor (04 guest				
	rooms + 01 store rooms + 01 manager room), 3 <sup>rd</sup> floor (4 guest rooms + 01 store room + 01 servant room)					
3	Type of case:-	Renewal	ooms + 01 store room + (	1 servant room)		
	Details of previous NOC:-		ACCITION ON	7/200		
т.	betails of previous NOC	13/02/2019	S/MS/GH/2019/ND	0Z/390 dated		
5.	Fire safety directives No	N/A				
	Date of inspection:-	24/2/22				
	Name of the inspecting officer:		er Singh (ADO/CC	,		
	Name & designation of officer	- Sii. Kaviiluk	a singii (ADO/CC	) .		
	From the building side:-	Sh. Jagjeet S	Singh			
	Year of construction:-	2002	onign			
	Applicant's letter No:-		20901921 dated 10/02	/2022		
S.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks		
5.110.	Prevention and fire safety	Existing fire	Flovided at site	MR/NMR		
	U/R 33	safety		MINIMIN		
		arrangements				
1.	Access to Building					
	1) Road width	N/A	10 feet (Approx.)	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arra	angement of Ex	its			
	A. Number of staircases					
	1. Upper floors	01 Nos.	01 Nos.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	0.80 mtr.	1.05 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits					
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	N/A	N/A	N/A		
	staircase to terrace					
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	1.0 mtr.	1.0 mtr.	MR		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Natural/exhaust	MR		
			fan			
5.	Fire Extinguishers	1001	00.11	MO		
	1) Total numbers	08 Nos.	08 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		



M]15

		, 1 113		
6.	First-Aid Hose Reel			4
	1) Total number of eachfloor	01	01	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syst	em	MR
	1) Type of detectors CO	Required	Provided	MR
	2) Location of main panel	Ground floor	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Ground floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	required	Tiovided	IVIK
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	. 1/1 k	""	1771
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	225 LPM	225 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
	u) Auto starting or pump			
4	Captive Water Storage for Fi	ire Fighting		
4.	1) Under ground tank	N/A	N/A	N/A
		1 1/ / 1		
	capacity	N/A	N/A	N/A
	a) Draw-off connection		N/A	N/A
	b) Fire service inlet	N/A		N/A
	c) Access to tank	N/A	N/A	MR
	d) Over head tank	2500 ltr.	2500 ltr.	IVIIC
	d) Over near min		1	1



15.	Exit Signage.	Required	Provided	100
16.	Provision of Lifts.		- To Vided	MR
	<ul> <li>a) Pressurization of lift shaft</li> </ul>	N/A	N/A	N/A
	<ul> <li>b) Pressurization of lift lobby</li> </ul>	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	<ul> <li>a) Detector system panel</li> </ul>	N/A	N/A	N/A
	<ul><li>b) Flow switch panel</li></ul>	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2019/NDZ/390 dated 13/02/2019 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

and Reporting Green.

Ms uploaded shout