(-51

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2022/ / 27

Dated: 02/03/2022

FIRE SAFETY CERTIFICATE

Certified that the Northern Palace Guest House located at 4425, Katra Rai Ji, Basant Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 09 guest rooms + Shops), 1st floor to 3rd floor (06 guest rooms at each floor) and 4th floor (Rooms sealed by MCD), total 27 guest rooms owned/occupied by Northern Palace Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2015/NDZ/2572 dated 28/11/18. Now, the premises was re-inspected by the officer concerned of this department on 24/02/22 in the presence of Sh. Ranjeet and found that the said guest house building having given an affidavit dated13.11.2019 regarding not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 09 guest rooms), 1st floor to 3rd floor (06 guest rooms at each floor) total -27 guest rooms up to third floor only with effect from floor (06 guest rooms at each floor) total -27 guest rooms up to third floor only with effect from floor (10 guest rooms at each floor) total -27 guest rooms up to third floor only with effect from floor (20 guest rooms at each floor) total -27 guest rooms up to third floor only with effect from floor (20 guest rooms at each floor) total -27 guest rooms up to third floor only with effect from floor (20 guest rooms at each floor) total -27 guest rooms up to third floor only with effect from floor (20 guest rooms at each floor) total -27 guest rooms up to third floor only with effect from floor cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 02/03/2022 at New Delhi by.

(Dr.S.K.Tomar)

Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. 2021120928190 dated 11.12.21& northernhotel234@gmail.com dated 22.02.2022.
- 3. The Manager,

Northern Palace Guest House, 4425, Katra Rai Ji, Basant Road, Pahar Ganj, New Delhi Condition for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 8. 4th floor was for sealed by MCD.

ial,

as

er e

est

G.

11119

INSPECTION REPORT

1. Name & address of the building:- Northern Palace Guest House located at 4425 Katra Rai Ji, Basant Road, Pahar Ganj, New

Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 27 Guest rooms) Ground floor & lower ground (Reception & 5+4 09 guest room) 1st floor to 3rd floor (06 guest rooms at each floor) and 4th floor (Rooms sealed by

MCD), an affidavit given by owner dated 13.11.2019 regarding not to use any floor above third floor.

3. Type of case:-Renewal

No. F6/DFS/MS/GH/NDZ/2018/2572 dated 4. Details of previous FSC:-

28/11/18.

5. Fire safety directives No.-N/A

24/02/22 6. Date of inspection:-

Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

Sh. Ranjeet

9. Year of construction:-

2006

on line ID No. 2021120928190 dated 11.12.21& 10. Applicant's letter No:northenrhotel234@gmail.com dated 22.02.2022.

10. Applicant's letter 140.		northenrhotel234@gmail.com dated 22.02.2022. Old Case		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building		03 Mtr.	NA
	1) Road width	N/A	N/A	N/A
	2) Gate width	N/A	N/A	N/A
	C: 4 mond	N/A		
2.	Number, Width Type & Arra	angement of E	Alts	
۷٠	A. Number of staircases	01 Nos.	01 Nos.	MR
	1. Upper floors	N/A	N/A	N/A
	2 Basements	IN/A		
	B. Width of staircase	0.80 mtr.	1.25 mtr.	MR
	1. Upper floors	0.80 mm		N/A
		N/A	N/A	IN/A
	2. Basements			N/A
	C. Protection of exits	N/A	N/A	N/A
	1. Fire check door	N/A	N/A	MR
	2. Pressurization	01	01	
	D. No. of continuous		NI/A	N/A
	staircase to terrace	N/A	N/A	MR
	E. Width of corridor	1 mtr.	1 mtr.	
	F. Door size		27/4	N/A
3.	Compartmentation	N/A	N/A	N/A
		N/A	N/A	N/A
	1) Fire check door 2) Sealing of electrical shafts	N/A	N/A N/A	N/A
	2) Fire rating of share de-	N/A	N/A N/A	N/A
	1) Water curtain	N/A	N/A	
		1		
4.	5) Fire Dampers Smoke Management System			NI/A
		30 ACPH	N/A	N/A
	D-coments	30 ACFII		
	1) Basements			



	2) Upper floors	Required	exhaust fan	MR
5.	Fire Extinguishers		January Iun	
	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	Required	Trovided	
O.	1) Total number of each floor	01	Provided	MR
	2) Length of hose reel hose	30 m	30 m	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.				1711
/•	Automatic Fire Detection & A		provided	MR
	1) Type of detectors CO Type	Required Gr. floor	provided	MR
	2) Location of main panel		N/A	N/A
	3) Location of repeater panel	N/A		MR
	4) Alternate source of power	Required	provided	MR
•	5) Hooter's Location	Gr. floor	provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	IVI
10.	Automatic Sprinkler System	21/4	NI/A	N/A
	1) Basement	N/A	N/A	N/A N/A
	2) Upper floors	N/A	N/A	N/A N/A
	3) Sprinkler above false	N/A	N/A	IN/A
	ceiling		-	
11.	Internal Hydrants	Laria	27/4	NIA
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	NA
	floor		27/	27/4
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	1514	77/4	NIA
	1) Total number of hydrants	N/A	N/A	NA
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main	N/A	N/A	N/A
	,		1	
	d) Jockey pump out put	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	,	13/74	1771	1
	stopping 2) Terrace level			
		225 LPM	225 LPM	MR
	a) Discharge of pump	30 mtr	30 mtr	MR
	b) Head of pump		Provided	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	IVIK
14.	Captive Water Storage for Fi	re Fighting	DI/A	N/A
	Under ground tank	N/A	N/A	IN/A
	capacity			21/4
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A

	 d) Over head tank capacity 	2500 ltr.	3000 ltr.	MR
5.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	 c) Communication in lift car 	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	20. Special Fire Protection System for Protection of special Risk, if any:			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/2572 dated 28/11/2018, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

Wheeled + 1HA ordere Portal