

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001 Dated: 07 03 2022

No. F6/DFS/MS/2022/School/WZ/238

FIRE SAFETY CERTIFICATE

Certified that the G.D. Goenka Public School, Pkt-04, Sector-9, Rohini, Delhi-110085, comprised of Ground + 03 upper floors has already been issued FSC by this department vide letter No. F.6/DFS/MS/2018/WZ/2144 dated 19.09.2018. The premises was re-inspected by the officer concerned of this department on 19.02.2022 in the presence of Mr. Mukesh and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Educational "Group B" with effect from 07/03/2021 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 0.3/03 2022 at New Delhi by

(Dhrampal Bhardwaj) **Dy.Chief Fire Officer** Tel;-01123414250

Copy to :-

- 1. The Principal, G.D. Goenka Public School, Pkt-04, Sector-9, Rohini, Delhi-110085.
- 2. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner/ occupier shall submit a declaration every year in Form 'K'[sub rule (2) of Rule 38] provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of Rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

: G. D. Goenka Public School, Pkt-04, Sector-9, Rohini, 1. Name & address of the building

Delhi-110085.

2. Type of Occupancy

: Educational : Renewal (Ground+03Upper Floors) 3. Type of Case

: F.6/DFS/MS/2018/WZ/2144 dated 19.09.2018 4. Details of previous NOC

5. Fire Safety directives letter No : NBC Part-4 : 19.02.2022 6. Date of inspection

: A.K.Sharma ADO (Rohini) 7. Name of the Inspecting Officers

8. Name and designation of officers

: Mr. Mukesh from the building side : 2005-2009 9. Year of Construction

10.		e-mail dated 16.	Provided at site	Remarks				
	Minimum Standards on fire	Director of	Provided at site	MR/NMR				
	prevention and fire safety U/R 33	Education		MICHAIN				
		letter dated						
		17.01.2005						
	Access to building Pood width Accessible Accessible MR							
	Road width	Accessible		MR				
	• Gate width	Accessible	5m					
	Width of internal road	NA	NA	NA				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases		1 00	MD				
	Upper Floors	02	02	MR				
	Basements	NA	NA	NA				
	b. Width of staircases		1) (D(-14)				
	Upper Floors	1.50m	1.42m &1.43m	MR(old case)				
	Basements	NA	NA	NA				
	c. Protection of exits		· · · · · · · · · · · · · · · · · · ·	NT A				
	• Fire check door	NA	NA	NA				
	Pressurization	NA	NA	NA				
	d. No. of continuous staircases to terrace	NA	NA	NA				
	e. Width of Corridor	NA	NA	NA				
	f. Door Size	1 m	1.0m with door	MR(old case)				
			frame					
3	Compartmentation.							
J	Fire check door	NA	NA	NA				
	Sealing of electrical shafts	NA	NA	NA				
	• Fire Rating of shaft door	NA	NA	NA				
	Water Curtain	NA	NA	NA				
	Fire Dampers	NA	NA	NA				
1	• Fire Dampers Smoke Management System.							
4		30 a/c per hour	NA	NA				
	Basements	12 a/c per hour	Natural Ventilated	MR				
	Upper floors	12 de per neur	Exhaust James	-				
5	Fire Extinguishers) (D				
	Total numbers	16 nos	20nos	MR				
	• Types	ABC/Co2	ABC-20	MR				
	ISI marking	ISI Marked	Yes	MR				
	First-Aid Hose Reels.							
6		02	02	MR				
	Total numbers on each floor		30m	MR				
	• Length of hose reel hose	30m	5mm	MR				
	Nozzle diameter	5mm	JIIIII	IVIIC				
7	Automatic fire detection and alarming system.							
	Type of detectors	NA	NA NA	NA NA				
	Location of Main Panel	NA	NA					
	 Location of Repeater Panel 	NA	NA	NA				

	Alternate source of power	NA	NA	NA			
	Hooters' Location	NA	NA	NA			
3	MOEFA	NA	NA	NA			
9	Public Address System.	Required	Provided	MR			
0	Automatic Sprinkler System.						
	Basement	NA	NA	NA			
	Upper Floor	NA	NA	NA			
	 Sprinkler above false ceiling 	NA	NA	NA			
1	Internal Hydrants						
	Size of riser/down-comer	100mm	Provided	MR			
	 Number of hydrants per floor 	Required	Provided	MR			
	Hose Box	Required	Provided	MR			
2	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A .	N/A			
	> Jockey Pump out put	225lpm	225lpm	MR			
	> Jockey pump head	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A	N/A			
		N/A	N/A	N/A			
	_	N/A	N/A	N/A			
	> Auto Starting/ Manual stopping	N/A	N/A	N/A			
	> Pump House Access	11/12					
	Terrace level						
	Discharge of pump	450lpm& 220 lpm	450lpm& 220 lpm	MR			
	➤ Head of the pump	40m	40m	MR			
	> Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting						
	Underground tank capacity	NA	Provided	NA			
	> Draw-off connection	NA	NA	NA			
	Fire service inlet	NA	NA	NA			
	> Access to tank	NA	NA	NA			
	Overhead Tank capacity	10,000 ltrs	10,000ltrs	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
- 0	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17	Standby power supply	N/A	N/A	N/A			
		IVA	17/12	1,111			
8	Refuge Area. > Total Area	N/A	N/A	N/A			
	> Location	N/A N/A	N/A	N/A			
		IN/A	14/12	1 1/2 1			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A N/A			
	Flow Switch Panel	N/A	N/A	N/A N/A			
		N/A	N/A	11/14			

1'

	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
20	Building Floor Plans Special Fire Protection Systems for	N/A	N/A	N/A
20	Protection of special Risks, if any:		1 '11'	1/ -111

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education, and removal of shortcomings issued vide letter no. 602 dated 08.11.2021, the FSC issued vide letter no. F.6/DFS/MS/2018/WZ/2144 dated 19.09.2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Signature of the Inspecting Officer

Name

Ajay Kumar Sharma

Designation ADO(Rohini)

DO (NW) - on leave

FT letter's purt up for think poursal and signature pears.