GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F 6/DFS/MS /2022/ WZ /BNOT. /13

Dated: 67 / 03/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Azizaa Banquet (A Unit of Roshni Hotels Pvt. Ltd) located at B-07, G.T. Karnal Road Industrial Area, Delhi-110033 comprised of Ground, First & Second floors Only owned/occupied by M/s Azizaa Banquet (A Unit of Roshni Hotel Pvt. Ltd) was issued fire safety certificate vide letter no. F6/DFS/MS/2018/WZ/2411 dated 26.10.2018. The premises was re-inspected by the officer concerned of Fire Service on 24.02.2022 in the presence of Sh. Rachit Yadav (Manager) and observed that all the fire prevention and fire safety arrangements as provided in the premise found good working condition. The premise have therefore deemed complied with the fire prevention and fire safety measures in accordance with the rule 33 of Delhi Fire Service Rules, 2010 and that the building / premise is fit for occupancy class "Assembly Group D-3 (Banquet Hall)" with effect from D-3 (2022) for a period of three years in accordance with rules 36 unless renewed under rule. 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 07/03/2022 at New Delhi by

(Dharampal Blardwaj)
Dy. Chief Fire Officer
Ph: 01125156707

Copy to:-

- 1. The Dy. Commissioner, (Civil Line Zone) North Delhi Municipal Corporation, 16, Rajpura Road, New Delhi-110054.
- 2. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049.
- 3. The Manager, M/s Azizaa Banquet (A Unit of Roshni Hotels Pvt. Ltd) located at B-07, G. T. K. Road Industrial Area, Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

1. Name & address of the building

: M/s Azizaa Banquets (A Unit Of Roshni Hotels Pvt. Ltd.), B-07, G T K Road

Indl. Area, Delhi-110033.

2. Composition of building

: Ground + 02 upper floors only

3. Type of Occupancy

: Assembly (Banquet Hall)

4. Type of Case

: Renewal

5. Details of previous NOC

: F-6/DFS/MS/2018/WZ/2411 Dated: 26.10.2018

6. Fire Safety directives letter No

: F.6/DFS/MS/2018/2018/3980 Dated : 24.09.2018

7. Date of inspection

: 24.02.2022 : ADO (RN)

8. Name of the Inspecting Officers9. Name and designation of officers

from the building side

: Mr. Rachit Yadav (Manager)

10. Year of Construction

: 2017

11. Applicant's letter No.

: Online Portal ID. No-2022020701748 dated:08.02.2022

		a—1167.195m2 num Standards on fire prevention and	NBC/ BBL	Provided at site	Remarks		
		fire safety U/R 33	Requirement		MR/NMR		
	Access	ss to building					
	•	Road width	06m	6m	MR		
	•	Gate width	NA	NA	NA		
	•	Width of internal road	NA	NA	NA		
	Number, Width, Type & Arrangement of Exits						
	a. Num	ber of staircases					
		Upper Floors	02	02	MR		
		Basements	NA	NA	NA		
	b. Widt	of staircases					
		Upper Floors	02m	02m	MR		
	•	Basements	NA	NA	NA		
	c. Prote	ction of exits					
		Fire check door	Required	Provided	MR		
		Pressurization	NA	NA	NA		
	d. No.	of continuous staircases to terrace	01	01	MR		
	e. Widt	n of Corridor	NA	NA	NA		
	f. Door	Size	2.0m	2.0m	MR		
_	Compartmentation.						
		Fire check door	Required	Provided	MR		
		Sealing of electrical shafts	Required	Provided	MR		
		Fire Rating of shaft door	Required	Provided	MR		
	•	Water Curtain	NA	NA	NA		
	•	Fire Dampers	NΛ	NA	NA		
4	Smoke	ke Management System.					
	•	Basements	NA	NA	NA		
		Upper floors	12 a/c per hour	Natural Ventilated	MR		



_			4			
5	Fire Extinguishers					
	Total numbers	15nos	16nos	MR		
	• Types	ABC & Co2	ABC-10, Co2-04 &	MR		
	 ISI marking 	Yes	Co2 trolly-02 Yes	MR		
5	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	 Length of hose reel hose 	30m	Provided	MR		
	Nozzle diameter	5mm	Provided			
7	Automatic fire detection and alarming system. 5mm Provided MR					
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA NA	NA		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location					
		NA	NA	NA		
})	MOEFA Public Address System.	Required	Provided Provided	MR MR		
0	Automatic Sprinkler System.	Required	Provided	IVIK		
	Basement	NA	NA	NA		
	Upper Floor	NA NA	NA NA	NA NA		
	Sprinkler above false ceiling					
	Internal Hydrants	NA	NA	NA		
	Size of riser/down-comer	100mm 01	Provided	MR		
	Number of hydrants per floor	01	Provided Provided	MR		
	Hose Box Yard Hydrants.	01	Provided	MR		
	raru riyuranis.					
	• Total number of hydrants	Required	Provided	MR		
	Hose Box	Required	Provided	MR		
	Pumping Arrangements.		· · · · · · · · · · · · · · · · · · ·			
	Ground Level					
	Discharge of main Pump	2280lpm	2280lpm	MR		
	Head of Main pump	40m	40m	MR		
	Number of main pumps	NA	NA	NA		
	> Jockey Pump out put	180lpm	180lpm	MR		
	> Jockey pump head	NA	NA	NA		
	Standby Pump out put	2280 lpm	2280lpm	MR		
	 Standby Pump Head Auto Starting/ Manual stopping 		·			
	Auto Starting/ Manual stoppingPump House Access	40m	40m	MR		
		Required	Provided	MR		
	Terrace level					
	Discharge of pump	450 lpm	450 lpm	MR		
	Head of the pump	40m	40m	MR		
	➤ Power Supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		



	•	Jnderground tank capacity	1,00000 ltr	1,00,000 ltr	MR	
	>	Draw-off connection	NA	. NA	NA	
	>	Fire service inlet	NA	NA	NA	
	۶	Access to tank	NA	NA	NA	
	•	Overhead Tank capacity	10,000 ltr	10,000 ltr	MR	
5	Exit Sig	nage.	Required	Provided	MR	
6	Provision of Lifts.		Two Passenger Lift & One Open Good lift			
	•	Pressurization of Lift Shaft	Required	Provided	MR	
	•	Pressurization of Lift lobby	Required	Provided	MR	
	•	Communication In lift Car	NA	NA	NA	
	•	Fireman's Grounding Switch	NA	NA	NA	
	•	Lift Signage	Required	Provided	MR	
17	Standb	y power supply	Required	Provided	MR	
18	Refuge	Area.			,	
	>	Total Area	N/A	N/A	N/A	
	>	Location	N/A	N/A	N/A	
19	Fire Control Room					
		Detector System Panel	N/A	N/A	N/A	
		Flow Switch Panel	N/A	N/A	N/A	
		PA System Panel	N/A	N/A	N/A	
		Batter backup	N/A	N/A	N/A	
		Building Floor Plans	N/A	N/A	N/A	
20	Specia	l Fire Protection Systems for tipn of special Risks, if any:	NA	NA	NA	

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. 2701 dated 21.12.2021have been compiled by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. 2411 dated 26.10.2018 under rule 37 of the Delhi Fire Service Rules 2010.

Dycro (WZ)

Signature of the Inspecting Officer
Name: - C.L. Meena

Nanhe: - C.L. Meena Designation:- ADO/RN

ABJR-N

As approved, F.T. letter is Putup for your singuature le

28 02 2022

Cont . - -