GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/Motel/2022//00

(

Dated 09 /03 /2022

FIRE SAFETY CERTIFICATE

Certified that the Best Hotels And Resorts India Pvt. Ltd (Mikado) located at Village Nangli Poona, G.T.K Road, Delhi-110036 comprised of basement, ground and one upper floor with 10 Guest Rooms and One Hall owned/occupied by Best Hotels And Resorts India Pvt. Ltd (Mikado) was issued fire safety certificate vide letter no. F6./DFS/MS/Motel/2017/WZ/1841 dated 20.12.2017 have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 26.02.2022 in the presence of Mr. Manas Arora and that the building/ premises is fit for occupancy Class Sub Div. D-5 Assembly Buildings with effect from 10 / 103 / 2029 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 09/03/2022..... at New Delhi by

(Dharampal Bhardwaj)
Dy. Chief Fire Officer
Ph: 01125156707

olc b

Copy to: -

- 1. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049.
- 2. The Manager, Best Hotels And Resorts India Pvt. Ltd (Mikado) located at Village Nangli Poona, G.T.K Road, Delhi-110036

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.Delhigovt.nic.in
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

1. Name & address of the building: Mikado (Best Hotels And Resorts India Pvt. Ltd). located at

Kh. No. 40/3, 40/4, Village Nangli Poona, GTK Road. Delhi

2. Composition of building : Basement + Ground+ One upper floor only

3. Type of Occupancy : Assembly

4. Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/Motel/2017/WZ/1841 Dated: 20.12.2017

6. Fire Safety directives letter No : F6/DFS/MS/BP/2013/2038 dated 19.08.2013.

7. Date of inspection : 26.02.2022

8. Name of the Inspecting Officers :ADO (RN)

9. Name and designation of officers

from the building side : Mr. Manas Arora

10. Year of Construction : 2014

11. Applicant's letter No. : Online Portal No.2022020501667 Dated 07.02.2022

S. No		nimum Standards on fire evention and fire safety U/R 33	e NBC Requirement	Provided at site	Remarks MR/NMI
1	Ac	cess to building	,		
		Road width	09m	09m	MR
		Gate width	06m	06m	MR
		Width of internal road	06m	06m	MR
2	Nu	mber, Width, Type & Arrangen	nent of Exits		
		a. Number of staircases			
		Upper Floors	03	03	MR
		Basements	04	04	MR
		b. Width of staircases			
		Upper Floors	1.50m each	1.50m x3	MR
		Basements	1.50m each	1.5m X 4	MR
	c. Pr	otection of exits			
	•	Fire check door	Required	Provided	MR
	•	Pressurization	N/A	N/A	N/A
		o. of continuous staircases to	Basement to terrace 03	Provided	MR
	e. W	idth of Corridor	N/A	N/A	N/A
		or Size	Hall 02m & Rooms 01m	Provided	MR
	Com	partmentation.			
	•	Fire check door	Required	Provided	MR
	•	Sealing of electrical shafts	Required	Provided	MR
	•	Fire Rating of shaft door	NA	NA	NA
	•	Water Curtain	NA	NA	NA
	•	Fire Dampers	N/A	N/A	NA

4	Smoke Management System.						
	Basements	30 a/c per hour	Exhaust fan	M			
		12 a/c per hour	Natural Ventilation	M			
5	• Upper floors Fire Extinguishers	,					
	Total numbers	17nos	17nos	Ml			
	• Types	ABC/Co2	Co2-10 & ABC-07	MI			
	• IS marking	Required	Provided	MI			
5	First-Aid Hose Reels.	770-7					
	Total numbers on each	02nos	Provided	M.			
	floor		Provided	M			
	 Length of hose reel hose 	30m		M			
	Nozzle diameter	5mm	Provided	IVI			
,	Automatic fire detection and alar	ming system.					
	Type of detectors	NA	NA	N.A			
	Location of Main Panel	NA	NA	N.A			
	• Location of Repeater Panel	NA	NA	NA.			
	Alternate source of power	NA	NA	N.A			
	Hooters' Location	NA	NA	N/			
	MOEFA	Required	Provided	MI			
	Public Address System.	Required	Provided	MI			
0	Automatic Sprinkler System.						
	Basement	Required	Provided	MR			
	Upper Floor	NA	NA .	NA			
	Sprinkler above false ceiling	NA	NA	NA			
l	Internal Hydrants						
	Size of riser/down-comer	150mm	150mm	MR			
	Number of hydrants per floor	r 02nos each	02nos not functional	MR			
	Hose Box	02nos each	Provided	MR			
2	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
3	Pumping Arrangements.						
	> Ground Level						
	Discharge of main Pump	2850 Lpm	2850LPM	MR			
	Head of Main pump	40mtr	40m	MR			
	Number of main pumps	NA	NA	NA			
	Jockey Pump out put	180 LPM	180 LPM	MR			
	Jockey pump head	40m	40m	M/R			
	Standby Pump out put	2880LPM	2880lpm	MR			
	Standby Pump HeadAuto Starting/ Manual	40mtr	40m	MR			
- 1							

1/ 1/-0/00

Service L

	→ Pump House Access	Required	Provided	MR				
,	Terrace level							
	Discharge of pump	900lpm	900plm	MR				
	Head of the pump	40m	40m	MR				
	> Power Supply	Required	Provided	MR				
	➤ Auto Starting of pump	Required	Provided	MR				
14	Captive Water Storage for fire fighting.							
	Underground tank capacity	50,000ltrs	50,000ltrs	MR				
	Draw-off connection	Required	Provided	MR				
	Fire service inlet	Required	Provided	MR				
	Access to tank	Required	Provided	MR				
	Overhead Tank capacity	20,000ltrs	20,000ltr	MR				
15	Exit Signage.	Required	Provided	MR				
16	Provision of Lifts.							
	Pressurization of Lift Shaft	ΝΛ	NA	NA				
	Pressurization of Lift lobby	NA	NA	NA				
	Communication In lift Car	Required	Provided	MR				
	Fireman's Grounding	Required	Provided	MR				
	Switch	D	Provided	MR				
	Lift Signage	Required	Tiovided	IVIIC				
17	Standby power supply	Required	Provided	MR				
18	Refuge Area.							
	> Total Area	NA	NA	NA				
	Location	NA	NA	NA				
19	Fire Control Room							
	Detector System Panel	NA	NA	NA				
	 Flow Switch Panel 	NA	NA	NA				
	PA System Panel	NA	NA	NA				
	Batter backup	NA	NA	NA				
	Building Floor Plans	NA	NA	NA				
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA				

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. It is recommended to renew Fire Safety vide this department letter of even no.344 dated 28.02.2018 Certificate under rule 37(3) of Delhi Fire Service Rules 2010.

DY 280(WZ)

2/8/200

Signature of the Inspecting Officer
Name: - C.L. Meena

Designation:- ADO/RN

ALLOTAN