GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/Mercantile/2022/SZ/) o 5

Dated: 101.03/2022

FIRE SAFETY CERTIFICATE

Certified that M/s Big Bazar (A Unit Black Clothing Pvt. Ltd) located at P.D Area of Kalkaji Mandir Metro Station, Kalkaji, New Delhi 110019 comprised of ground plus One upper floor owned/occupied by (A Unit Black Clothing Pvt. Ltd) was issued Fire Safety Certificate by this department vide letter No F6.DFS/MS/2019/SZ/693 dated 02/04/2019. The premise was reinspected by the officer concerned of this department on 22/02/2022 in the presence of Mr. Amar Nath Kumar and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group-F "Mercantile Building" with effect from the date of issue 10/03/2022 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10/03/2022 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

au

Copy to: -

6

1. M/s Big Bazar (A Unit Black Clothing Pvt. Ltd) located at P.D Area of Kalkaji Mandir Metro Station, Kalkaji New Delhi 110019.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



		ON REPORT		1	
1	Name & Address of the Building	M/s Big Bazar (A Unit Black Clothing Pvt. Ltd) located at P.D Area of Kalkaji Mandir Metro Station, New Delhi 110019			
2	Type of Occupancy	Mercantile Occupancy Building Group-F			
3	Building Comprised of	Ground + 01 upper floors. (Big Bazar)			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6.DFS/MS/2019/SZ/693 dated 02/04/2019			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	22/02/2022			
8	Name of the Inspecting Officers	Sh. Rajesh Kumar, ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Amar Nath Kumar			
10	Year of construction	2009			
11	Applicant letter No.	Nil dated 14/02/2022			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Provided at Site Remarks Requirements MR/NMR			
1		Requirements			
1	Access to Building.	12 m	Provided	MR	
	Road width	06 m	Provided	MR	
	Gate width	06 m	Provided	MR	
	Width of internal road	00 111	Tiovided	1.24	
2	Number, width, type & arrangement of exits.				
	a) Number of Staircase	02 nos	02 Nos	MR	
	Upper floors.		NA NA	NA	
	Basement floor.	NA	INA	INA	
	b) Width of Staircase			MR	
	Upper floors	1.5 mtr	1.50 m & 1.80 m		
	Basement floor	NA	NA	NA	
	c) Protection of exits				
	Fire check door	-NA-	-NA-	-NA-	
	Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	-NA-	-NA-	-NA-	
	e) Width of corridor	-NA-	-NA-	-NA-	
	f) Door size	2 m	Provided	MR	
3	Compartmentation.	1			
-	Fire check door.	-NA-	-NA-	-NA-	
	Sealing of electrical shafts.	-NA-	-NA-	-NA-	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4	Smoke Management system.				
	Basement	-NA-	-NA-	-NA-	
	Upper floors	12 ACPH	Exhaust fan	MR	
5	Fire Extinguishers. • Total numbers	25 Nos	Provided	MR	
		ABC / CO2	ABC & CO2	MR	
	Types ISI Morking	ISI marked	Provided	MR	
	ISI Marking Si A	101 marked	2.01.000		
6	First Aid Hose Reels.	0	Provided	MR	
	Total numbers on each floor.	One			
	 Length of hose-reel hose. 	30 mtr	Provided	MR	
	Nozzle Diameter	5 mm	Provided	MR	
	Automatic fire detection & alarming system.				



4/14

	Type of detectors	Danis		
	Location of Main Panel	Required Required	Smoke type	MR
8	Location of Repeater Panel	-NA-	Ground floor	MR
	Alternate source of power	Required	-NA-	-NA-
	Hooter's location	Control of the Contro	Provided	MR
	MOEFA Public Address System	All area Required	Provided Provided	MR MR
	Basement	-NA-	NA	
	Upper floors.	The second secon	-NA-	-NA-
	Sprinkler above false ceiling	Required -NA-	Provided	MR
11	Internal Hydrants.	-11/4-	-NA-	-NA-
	Size of Riser/Down-comer	100		
	Number of Hydrant per floor	100 mm	Provided	MR
	Hose box.	GF-04, FF-01	Provided	MR
12	Yard Hydrants.	GF-04, FF-01	Provided	MR
				,
	Total number of flydrants.	02	Provided	MR
13	TIOSE OOK.	02	Provided	MR
13	Pumping arrangements.			
	Ground Level		,	
	Discharge of main pump.	900 LPM	1680 LPM	MR
	Head of main pump	40m	50m	MR
	Number of main pumps. Jockey Pump output	01 No	02 Nos	MR
	Tamp output.	180 LPM	Provided	MR
	a solidy a unip field.	40m	Provided	MR
	Standby Pump output.Standby Pump head.	Required	1680 LPM	MR
	Auto Starting/Manual Stopping.	Required	50m	MR
	> Pump house access.	Required	Provided	MR
		Required	Provided	MR
	Terrace Level			
	Discharge of pump.	-NA-	-NA-	-NA-
	Head of pump.	-NA-	-NA-	-NA-
	Power supply	-NA-	-NA-	-NA-
	Auto starting of pump.	-NA-	-NA-	-NA-
14	Captive water storage for fire fighting.			
	 Underground tank capacity. 	25,000 ltrs	1,00,000 ltrs	MR
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	Overhead tank capacity.	-NA-	-NA-	-NA-
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			IVII
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage.	-NA-	-NA-	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area	Required	riovided	IVIK
10		NIA T	NT A	NT A
	Total area	-NA-	-NA-	-NA-
	• Location	-NA-	-NA-	-NA-
19	Fire Control Room.			
	Detector system panel.	Required	Provided	MR



	Flow switch panel.	-NA-	-NA-	•NA-
	 PA system panel. 	-NA-	-NA-	-NA-
	Battery backup.	Required	Provided	MR
	Building floor plan.	-NA-	~NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

Accordingly, the fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules, the fire safety certificate issued vide letter F6.DFS/MS/2019/SZ/693 dated 02/04/2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: - Rajesh Kumar

Designation: - ADO/BCP

DO/S/D

As approved, F.T. letter ei putrop for om signature Pl. My 05/2022