

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/2022/WZ/Hospital/ 109

Dated: 14/03/22

FIRE SAFETY CERTIFICATE

Certified that the **Dr. B.R Ambedkar Hospital, Sec-06, Rohini, Delhi-110085**, comprised of **02 Blocks, intereconnected at Ground level (B+G+2 & B+G+5 upper floors)** has already been issued FSC by this department vide letter No. **F.6/DFS/MS/2017/Hospital/1585 dated 07.11.2017** for **02 blocks- B+Gr+01 & B+G+ 02 floors**. The premises was re-inspected by the officer concerned of this department on **22.02.2022** in the presence of **Mr. Sanjeev Yadav, J.E.(Elec.)** and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class **Institutional 'Group C'** with effect from 14/03/22 for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 14/03/2022 at New Delhi by


(Atul Garg)
DIRECTOR
Ph; 011-23414000

o/c
Garg

Copy to :-

1. Executive Engineer (E), PWD, HMED (North), Dr. B.R Ambedkar Hospital, Sec-06, Rohini, Delhi-110085.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of firefighting system.
5. The owner/ occupier shall submit a declaration **every year** in **Form 'K'**[sub rule (2) of Rule 38] provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doiit_fire/FIRE/Home/Forms
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of Rule 37] along with a copy of this Certificate, **six months** prior to its expiry."
8. Smoke management system of entire building shall be reviewed with certified consultant for entire building within year, failure to which FSC shall stand null & void.

INSPECTION REPORT

- 1 Name & address of the building : Dr. B.R Ambedkar Hospital, Sec-06, Rohini, Delhi.110085.
- 2 Type of Occupancy : Institutional
- 3 Type of Case : Earlier (02 blocks- B+Gr+01 & B+G+ 02 floors)
Now (B+Gr+5 upper floors).
- 4 Details of previous NOC : F.6/DFS/MS/2017/Hospital/1585 dated 07.11.2017
- 5 Fire Safety directives letter No : F.6/DFS/MS/94/BP/77 dated 18.01.1994
- 6 Date of inspection : 22.02.2022
- 7 Name of the Inspecting Officers : A.K.Sharma ADO (Rohini)
- 8 Name and designation of officers from the building side : Sh. Sanjeev Yadav, J.E.(Elec.)
9. Year of Construction :
10. Applicant's letter No. :23(Gen)/EE(E)/PWD/HMED(North)/2021-22/233 dated 08.02.22

S. No	Minimum Standards on fire prevention and fire safety U/R 33	Rule-36(5) of DFS Rule 2010 (Fire prevention & Fire Safety Rules, 1987)	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	9m	18m	MR
	• Gate width	5m	5m	MR
	• Width of internal road	06m	06m provided as per C-82/C-83	MR
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	NA	18	MR
	• Basements	NA	14	MR
	b. Width of staircases			
	• Upper Floors	NA	190m x 03, 1.45 x 02, 1.17 x 02 & 87 cm	MR (old case)
	• Basements	NA	190m x 03, 1.45 x 02, 1.17 x 02 & 87 cm & 1.35m x 02	MR (old case)
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	NA	NA	NA
	e. Width of Corridor	NA	NA	NA
	f. Door Size	NA	NA	NA
3	Compartmentation.			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	NA	NA	NA
	• Upper floors	NA	NA	NA
5	Fire Extinguishers			
	• Total numbers	Required	Provided	MR
	• Types	Required	Provided	MR
	• IS marking	Required	Provided	MR
6	First-Aid Hose Reels.			
	• Total numbers on each floor	09 nos	09	MR
	• Length of hose reel hose	30m	30mm	MR
	• Nozzle diameter	5mm	5mm	MR

	<ul style="list-style-type: none"> Length of hose reel hose Nozzle diameter 	30m 5mm	30mm 5mm	MR MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Required G.F NA NA NA	Provided Provided NA NA NA	MR MR NA NA NA
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	Required Required NA	Provided Provided (high rise block only) NA	MR MR NA
11	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	Required Required Required	Provided Provided Provided	MR MR MR
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	Required Required	Provided Provided	MR MR
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	Required NA Required Required NA Required NA NA Required NA NA NA NA	2850 lpm NA Provided 180 lpm NA 2850 lpm NA NA Provided NA NA NA NA	MR NA MR MR NA MR NA NA MR NA NA NA NA
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	Required Required Required Required Required	3,00,000ltrs Provided Provided Provided 50000ltrs	MR MR MR MR MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	NA NA NA Required NA	NA NA NA Provided NA	NA NA NA MR NA
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	<ul style="list-style-type: none"> Total Area Location 	NA NA	NA NA	NA NA

MR
MR

19	Fire Control Room			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Rule 35(6), and removal of shortcomings issued vide letter no. 2795 dated 30.12.2021, the FSC issued vide letter no. F.6/DFS/MS/2017/Hospital/1585 dated 07.11.2017 this is recommended for entire building under rule 35 of the Delhi Fire Service Rules, 2010.

Ajay
25/12/22

Signature of the Inspecting Officer
Name : Ajay Kumar Sharma
Designation : ADO (Rohini)

DO (NW)

Ajay
04/03/2022

Ajay
04/03/2022

Ajay
7/12/2022

Ajay
04/03/2022

Ajay
04/03/2022

Ajay
04/03/2022
FI PS

Ajay
04/03/2022

FI letter is put up for kind
perusal and signature please.

Ajay
11/03/2022
Director
Ruseer

Ajay
19/3/22

