

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 Dated: 15../.0.3./2022

No.F6/DFS/MS/GH/NDZ/2022/ \40

FIRE SAFETY CERTIFICATE

Certified that the Vivek Guest House located at 1534-50, Main Bazar, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (04 guest rooms + Reception + 01 Office + lobby + internet cafe), 1st floor (11 guest rooms), 2nd floor (22 guest rooms), 3rd floor (13 guest rooms) and 4th floor sealed by MCD, total 50 guest rooms owned/occupied by Vivek Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2018/2082 dated 12/09/18. Now, the premise was re-inspected by the officer concerned of this department on 09/03/22 in the presence of Manager and found that the said guest house building comprised of ground, mezzanine (not a part of guest house) and four upper floor, having given an undertaking dated 09.03.2022 regarding not to use any floor above second floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (04 guest rooms), 1st floor (11 guest rooms), 2nd floor (22 guest rooms), total 37 guest rooms up to second floor only, with effect from [5...03...2022 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ... 15/03/2027 at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Commissioner, North Delhi Municipal Corporation, Civic Centre, New Delhi: to ensure the occupancy as detailed above.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2022020701744 dated 21.02.2022.&e- mail<reservation@vivekhotel.com 08.03.2022

3. The Manager,

Vivek Guest House 1534-50, Main Bazar, Pahar Gani, New Delhi.

Condition for the validity of Fire Safety Certificate

1. This clearance/ FSC shall stand cancelled, if guest house owner/occupier fails to comply all conditions mentioned in the gazette notification dated 27.05.2019 & letter of extension of time period issued on dated 20.12.2021, latest by 31.03.2022.

2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid only for guest house part.

3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

4135

INSPECTION REPORT

1. Name & address of the building Vivek Guest House at 1534-50, Main

Bazar, Pahar Ganj, New Delhi.

2. Type of occupancy:- Residential, Sub Division-A-1

Gr. +Mez. + 04 Upper floors (total 37 Guest rooms)
Ground floor (04 guest rooms + Reception + 01
office + lobby + internet cafe), Mez. (other portion in other
use) 1st floor (11 guest rooms), 2nd floor (22 guest rooms),
3nd floor (13 guest rooms) and 4th floor not in use as per
undertaking dated 09.03.2022 regarding not to use any

floor above second

3. Type of case:-

Renewal

4. Details of previous FSC:-

No.F6/DFS/MS/GH/NDZ/2018/2082 dated

12/09/18.

5. Fire safety directives No.-

N/A

6. Date of inspection:-

09/03/22

7. Name of the inspecting officer:-

Sh. Ravinder Singh(ADO/CC)

8. Name & designation of officer From the building side:-

(Manager)

9. Year of construction:-

10. Applicant's letter No:

Online id no.2022020701744 dated 21.02.2022.& e-mail<reservation@vivekhotel.com 08.03.2022

Old Case

		· ·		Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	06 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr			
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	1.05 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021
-	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
-			1	1
	E. Width of corridor	N/A	N/A	N/A
	E. Width of corridor F. Door size	N/A 1.0 mtr.	N/A 1.0 mtr.	N/A MR
3.	E. Width of corridor F. Door size Compartmentation			N/A MR
3.	E. Width of corridor F. Door size Compartmentation 1) Fire check door	1.0 mtr.	1.0 mtr.	MR
	E. Width of corridor F. Door size Compartmentation 1) Fire check door 2) Sealing of electrical shafts	1.0 mtr.	1.0 mtr.	MR N/A
	E. Width of corridor F. Door size Compartmentation 1) Fire check door 2) Sealing of electrical shafts 3) Fire rating of shaft door	1.0 mtr.	1.0 mtr. N/A N/A	MR N/A N/A
3.	E. Width of corridor F. Door size Compartmentation 1) Fire check door 2) Sealing of electrical shafts	N/A N/A	1.0 mtr.	MR N/A

4.	Smoke Management System				
	Smoke Management System			M	
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021	
5.	Fire Extinguishers				
	1) Total numbers	10 Nos.	16 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel				
	1) Total number of eachfloor	01	01	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection & Alar				
	1) Type of detectors	Required as per G.N dated 27.05.19	Not provided	Last dt. 31.03.22 of compliance extended vide order dt. 20.12.2021	
	2) Location of main panel	N/A	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System				
	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false ceiling	N/A	N/A	N/A	
12.	Internal Hydrants				
	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per floor	N/A	N/A	N/A	
	3) Hose box	N/A	N/A	N/A	
	Yard Hydrants				
	1) Total number of hydrants	N/A	N/A	N/A	
12	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement				
,	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main pump	N/A	N/A	N/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual stopping	N/A	N/A	N/A N/A	

		•			
	2) Terrace level				
	 a) Discharge of pump 	450 LPM	450 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting				
	Under ground tank capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System fo any:	r Protection	of special Risk, if	N/A	

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Further, the building is comprised of ground, mezzanine and four upper floor from the beginning and mezzanine floor having separate entry/exit & not a part of guest house. Accordingly we may renew the FSC up to second floor as mezzanine floor is counted as a floor.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/2082 dated 12/09/18, renewal under rule 35 of the Delhi Fire Service rules 2010, up to second floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

1722 11-03-22 15-03-22

11/2/22

Dycho (MD2)

Bonn 11/3/22

A DO(CC)