GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/2022/159

Dated: 31/03/2022

FIRE SAFETY CERTIFICATE

Certified that the Guest House in the Name & Style of AMBIENCE located at 10, 11, 12, 13, 13/1, Krishna Market, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 02 guest rooms + store), 1st floor (03 guest rooms), 2nd floor & to 4th floor (05 guest rooms at each floor), total 20 guest rooms owned/occupied by AMBIENCE Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2019/NDZ/212 dated 28/01/19. Now, the premise was re-inspected by the officer concerned of this department on 16/03/22 in the presence of Manager and found that the said guest house building having ground floor (Reception + 01 guest rooms + 02 store room), 1st floor (03 guest rooms), 2nd floor & to 3rd floor (05 guest rooms at each floor) & 4th floor not in use as per undertaking dated 16.03.2022 submitted by owner, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1, Ground floor (Reception + 01 guest rooms), 1st floor (03 guest rooms), 2nd floor & to 3rd floor (05 guest rooms at each floor)as above 14 guest rooms only up to third floor with effect from ...21./.03./.20.22... for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 21/03/2022 at New Delhi by.

(**Dr. S.K.Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID no. 2022021202065 dated 12.02.2022
- 3. The Manager,
 AMBIENCE Guest House, 10, 11, 12, 13, 13/1, Krishna Market, Pahar Ganj, New Delhi.
 Conditions for the validity of Fire Safety Certificate
 - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
 - 3. The trained fire fighting staff should be available round the clock.
 - 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
 - 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
 - 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
 - 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

INSPECTION REPORT 1. Name & address of the building 4HAMBIENCE at 10, 11, 12, 13, Krishna

Market, Pahar Ganj, New Delhi 2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 4 Upper floors (total 14 Guest rooms) Ground floor (Reception + 01 guest rooms +02 store room 1st floor (03 guest rooms), 2nd floor & to 3rd floor (05 guest rooms at each floor), 4th floor not in use as per

under taking dated 16.03.2022

3. Type of case:-Renewal

4. Details of previous FSC:-No. F6/DFS/MS/GH/NDZ/2019/NDZ/212

N/A

dated 28.01.19

5. Fire safety directives No.-

6. Date of inspection:-16/03/22

7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer

From the building side:-

Manager 9. Year of construction:-2010

10. Applicant's letter No:-ID no. 2022021202065 dated 12.02.2022

		10 110. 2022021	202003 dated 22.02.	Old Case		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	N/A	6 mtr.	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arrangement of Exits					
	A. Number of staircases					
	1. Upper floors	01 Nos.	01 Nos.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	1.5 mtr.	1.50 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits					
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	01	01	MR		
	staircase to terrace					
	E. Width of corridor	1.5 mtr.	1.5 mtr.	MR		
	F. Door size	1.0 mtr.	1.0 mtr.	MR		
3.	Compartmentation	,				
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Natural/exhaust	MR		
5.	Fire Extinguishers					
	1) Total numbers	10 Nos.	12 Nos.	MR		
				1		



11/14

	2) Types	ABC & CO2	ABC & CO2	MR N	
	3) ISI marking	Required	Provided	MR	
6	First-Aid Hose Reel				
6.	Total number of eachfloor	01	01	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection & A	larming Syst	em		
/•	1) Type of detectors CO type	Required	Provided	MR	
	2) Location of main panel	Gr. floor	Provided	MR	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	Gr. floor	Provided	MR	
8.	MOEFA	N/A	Provided	N/A	
9.	Public Address System/	N/A	Provided	N/A	
7.	Intercom				
10.	Automatic Sprinkler System				
10.	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling				
11.	Internal Hydrants				
	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor				
	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants				
	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement				
	Ground level	N/A	N/A	N/A	
	 a) Discharge of main 	N/A	N/A	N/A	
	p um p				
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump		N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output		N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual	N/A	N/A	N/A	
	stopping				
	2) Terrace level				
	a) Discharge of pump	450 LPM	450 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting				
	1) Under ground tank	N/A	N/A	NI/A	
	capacity		17/74	N/A	
	a) Draw-off connection	N/A	N/A	NI/A	
	b) Fire service inlet	N/A	N/A	N/A	
		1 11/11	IN/A	N/A	

20.	Special Fire Protection System for Protection of special Risk, if any: ABC & Co2			MR
	e) Building floor plan	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	
	c) PA system panel	N/A	and the same of th	N/A
	b) Flow switch panel	N/A	N/A	N/A
	panel		N/A	N/A
19.	Fire Control Room a) Detector system	N/A	N/A	N/A
	Ti Control Poom	N/A	N/A	N/A
	Total area location	N/A	N/A	19//3
8.	Refuge Area	N/A	N/A	N/A
7.	Stand by Power Supply	N/A	The state of the s	N/A
	e) Lift signage	N/A	Provided	N/A
	d) Fireman's switch	N/A	N/A	N/A
	lift car		N/A	N/A
	lobby c) Communication in	N/A	N/A	N/A
	b) Pressurization of lift	N/A	,,,,,	
	shaft	NI/A	N/A	N/A
6.	Provision of Lifts. a) Pressurization of lift	N/A	N/A	N/A
5.	Exit Signage.	and the second second second		
	capacity	Required	Provided	MR
	 d) Over head tank 	5000 ltr.	5000 Jtr.	MR
	c) Access to tank	Required	Provided	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2019/NDZ/212 dated 28/01/19 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

da.

Name: - Ravinder Singh Designation: - ADO (CC)

17/2/22

Dyces (NO2)

X Demy

Asoface). Asooponed, on putup for Kan Perusal

Deco (nos

DEN 5/12

uploaded

Mozhon

TAS