



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

F6/DFS/MS/GH/NDZ/2022/157

Dated: 2// 03/2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Amrit Guest House located at 855, S.P.M. Marg, Delhi, comprised of Ground floor (Commercial use), Mezzanine floor (03 staff rooms), 1st floor (14 guest rooms + Reception + office), 2nd floor (12 Guest rooms + 1 staff room + staff kitchen) and third floor (18 guest rooms), total 44 guest rooms owned/ occupied by M/s Amrit Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/2599 dated 03/12/2018. The premises was re- inspected by Assistant Divisional Officer (SPM) from this department on 07/03/2022 in presence of Mr. Manish, Owner Nephew and found that the building is comprised of Ground floor + 03 upper floor and now the floor wise occupancy is Ground + 03 upper floors: Ground floor (Commercial use) - Shop with Parchatti, 1st floor - 14 guest rooms + reception + office, 2nd floor - 12 guest rooms + 02 staff room, 3rd floor - 18 guest rooms, total 44 guest rooms. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of "Residential Sub Division-A-1 for 44 guest rooms at 1st floor to 3rd floor only with effect from 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 21 03 2022 at New Delhi by

(Dr. S.K. Tomar) Dy. Chief Fire Officer

Tel: 011-23412025

Copy to:-

- 1. The Commissioner, North Delhi Municipal Corporation, S.P.M, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi: Ref. MHA Portal ID. No. 2021120227697 dated 02.12.2021.
- 3. The Licensee, M/s Amrit Guest House located at 855, S.P.M., Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

R

P. m

D.
'N
th

for re-

1	N	lam	e & address of the building	NSPECTION RE				
				Delhi.	Guest House located at	855, S.P.M. Marg		
2	В	uile	ding is comprised of					
				Ground floo	Ground + 03 upper floors Ground floor – Shop with Parchatti			
				1 st floor = 14	r – Snop with Parchatti			
				2 nd floor - 12	guest rooms + reception	1 + office		
				3 rd floor – 18	guest rooms + 01 staff r	oom		
3	T	ype	of occupancy	Residential C	guest rooms			
4	T	ype	of case	Residential G Renewal	roup A-1			
5			ls of previous FSC					
6	Fi	re s	afety direction letter no.	FO/DFS/MS/(GH/NDZ/2018/2599 date	ed 03.12.2018		
7	D	ate	of inspection	Nil				
8	N	ame	of the inspecting officers	07.03.2022				
9	N	ame	of the dispecting officers	Sumit Kumar	ADO (SPM)			
	Name of the designation of officer from the building side			cer Mr.Manish ((Owner Nephew)			
10	V	201	of construction					
11				1920				
S.No	A	ppii	cant's letter no.	Online applica	tion no. 2021120227697	dated 02 12 2021		
9.140	IM D	ıniı	num Standards on fire	Requirement	Requirement/ Provided at Site Remarks MR			
	ro	eve	ention and fire safety	Existing fire		NMR		
	16	qui	rements U/R 33	safety				
1	A	Ces	s To Building:	arrangements				
	Road width		width	120				
		_		NA	06 mtrs	MR		
	Gate width Width of internal road			NA	NA	NA		
2	Number, Width, Type and Arrangem			NA	NA	NA		
	A	\ \	lumber of staircases	angement of Exits:				
	-	a						
		b		01 nos.	02 nos.	MR		
	В	_	/idth of staircases	NA	NA	NA		
		-	Upper floor		_			
		l a	Opper fioor	80 cms	Gr. to terrace - 82 to 110 cms	MR		
					1 st to 3 rd floor- 94 cms			
		b	Basement	NA	NA	NA		
	C	Pı	otection of exits		107	IVA		
		а	Fire check door	(Required as	provided	MR		
				per GN dated				
				27.05.2019)				
			Pressurization	NA	NA	NA		
	D		o. of continuous staircases	01 nos.	01 nos.	MR		
			terrace					
	E		idth of corridor	NA	NA	NA		
	F		oor size	0.91 mtrs.	0.91 mtrs.	MR		
	Cor	_	rtmentation:					
	A		re check door	NA	NA	NA		
	В		ealing of electrical shafts	NA	NA	NA		
	C	Fi	re rating of shaft door	NA	NA	NA		
- 1	D		ater curtain	NA	NA	NA		
-	_	Fi	re dampers	NA	NA	NA		
	\mathbf{E}		•					
			Management System:					
	Smo	ke	Management System:	NA	NA	NA		
		ke Ba	Management System: sement oper floor	NA Natural	NA Natural (Open	NA MR		

5.	Fire	Extinguisher:			
	A	Total numbers	10 nos.	10 nos.	MR
	В	Types	CO ₂ & ABC	CO ₂ & ABC	MR
	C	ISI marking	ISI marked	ISI marked	MR
6	First	-Aid-Hose Reels:			
	A	Total numbers of each floor	01 nos.	01 nos.	MR
	В	Length of hose reel hose	30 mtrs.	30 mtrs.	MR
	C	Nozzle diameter	5 mm	5 mm	MR
7	Auto	matic Fire Detection And A	larming System:		
	A	Type of detectors	CO detectors (required as per point no. viii of GN dated 27.05.2019)	Provided	MR
	В	Location of main panel	Required	Provided	MR
	C	Location of repeater panel	NA	NA	NA
	D E	Alternate source of power	Required	Provided	MR
8	MOI	Hooters	Required	Provided	MR
9			NA	NA	NA
		ic Address System:	Required	Provided	MR
10		matic Sprinkler System:		'	
	A	Basement	NA	NA	NA
	В	Upper floor	NA	NA	NA
	C	Sprinkler above false	NA	NA	
11	Τ.,	ceiling			NA
11		rnal Hydrants:			
	A	size of riser/down-comer	NA	NA	NA
	В	Number of hydrants per floor	NA	NA	NA
10	C	Hose box	NA	NA	NA
12		d Hydrants:			140
	A	Total number of hydrants	NA	NA	NIA
	В	Hose box	NA	NA	NA
13	Pum	ping Arrangements:		IVA	NA
	A	Ground level			
	a)	Discharge of main pump	NA	NA	
	b)	Head of main pump	NA		NA
	c)	Number of main pumps	NA	NA	NA
	d)	Jockey pump out put	NA	NA	NA
	e)	Jockey pump head	NA	NA	NA
	f)	Standby pump out put	NA	NA	NA
	g)	Standby pump head	NA	NA	NA
	h)	Auto starting /manual	NA	NA	NA
	-,-	stopping	,	NA	NA
	i) B	Pump house access	NA	NA	• • • •
		Terrace level		143	NA
	a)	Discharge of pump	225 LPM	225 LPM	
	b)	Head of the pump	30 mtrs.	30 mtrs.	MR
	c)	Power supply	Required	Provided	MR
	d)	Auto starting of pump	Required	Provided	MR
				riovided	MR

- N/44_

14	Captive Water Storage For Fire Fighting: A Underground tank capacity.					
	A	Underground tank capacity	Fighting:			
	В	Draw-off connection	NA			
	C	Fire service inlet	NA	NA	NA	
	D	Access to tank	NA	NA	NA	
	E	Overhead tank capacity	NA	NA	NA	
15	Exit Signage:		2,500 ltrs	NA	NA	
16	Provision of Lifts:		Required	2,500	MR	
	A	Pressurization of life 1		Provided	MR	
	В	Pressurization of lift lobby	NA			
	C	Communication in lift car	NA	NA	NA	
	D	Firemen's grounding switch	NA	NA	NA	
	E	Lift signage	NA	NA	NA	
17	Sta	ndby Power Supply:	NA	NA	NA	
18	Ref	fuge Area:	Required	NA	NA	
-	A		required	Provided	MR	
H	B	Total area	NA			
_		Location	NA	NA	NA	
		e Control Room:	NA	NA	NA NA	
-	A	Detector system panel			IVA	
-	В	Flow switch panel	NA	NA	110	
	C	Pa system panel	NA	NA	NA	
	D	Battery backup	NA	NA	NA	
	E	Building floor plans	NA	NA	NA	
20	Special Fire Protection Survey		NA	NA	NA	
	Spe	cial Risks, If Any:	NA	NA		
		,,			NA	

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/2599 dated 03.12.2018 is recommended to be renewed "Residential Sub Division-A-1 for 44 guest rooms at 1st floor to 3rd floor only under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name: - Sh. Sumit Kumar
Designation ADO (SPM)

DO (CD)

0.000

07 0 mm

ADOCSPM) C.T. letter is Port up for your Signature, Please.

12

upualed W

by. Cho (NOZ

MS